

MEMORANDUM

TO: Planholders for
SIA Project #15-42-1849
Spokane International Airport, Spokane, Washington
Airport Buildings Demolition

FROM: Alton W. Dail III, P.E.
T-O Engineers
W 280 Prairie Avenue
Coeur d'Alene, Idaho 83815

DATE: August 18, 2015

SUBJECT: Addendum #1 - Transmittal of Documents

Transmitted herewith is the following:

1. Addendum Number One, dated August 18, 2015.
2. Mandatory Pre-Bid Conference – Meeting Minutes.
3. Mandatory Pre-Bid Conference – Attendance Sheet.
4. Table of Contents – Revised August 18, 2015.
5. REMTECH Water Well Log
6. Airport Buildings Demolition Asbestos Survey.

Please note that the Bid Opening will be held at 11:00 a.m., Wednesday August 26, 2015 at the Spokane International Airport, W. 9000 Airport Drive, Suite 204, Spokane, Washington 99224.

Questions will be accepted until 5:00 p.m. Friday, August 21, 2015.

Signed,



Alton W. Dail III, PE
T-O Engineers, Inc.

ADDENDUM NUMBER ONE

Date: August 18, 2015

PROJECT TITLE: SIA Project #15-42-1849
Spokane International Airport, Spokane, Washington
Airport Buildings Demolition

OWNER: Spokane Airport Board

ENGINEER: T-O Engineers
W. 280 Prairie Avenue
Coeur d'Alene, Idaho 83815
(208) 762-3644

The Contract Documents for the project identified above, dated August 2015, are amended as follows and additional information is provided to clarify the Contract Documents.

CONSTRUCTION DOCUMENTS AND SPECIFICATIONS:

TABLE OF CONTENTS

REPLACE the TABLE OF CONTENTS issued with the Contract Documents and Specifications with the attached TABLE OF CONTENTS dated August 7, 2015.

SECTION 02 41 00 DEMOLITION OF EXISTING STRUCTURES

ADD the following to the end of Section 3.2.E:

“Existing domestic well log is attached as an appendix to these specifications.”

ADD the following to the end of Section 4.2.C:

“Existing USTs are anticipated to be 1,000 gallon tanks containing 200 gallons of Kerosene heating oil. Contractor shall excavate and dispose of contaminated soil to a depth of 2-foot below bottom of tank.”

SECTION 02 82 33 REMOVAL AND DISPOSAL OF ASBESTOS-CONTAINING MATERIALS

CLARIFICATION: Bidders should expect the asbestos-containing flooring scheduled for abatement in Buildings 360, 1378, and 2501 to be present under the interior walls of the building.

APPENDICES

ADD the attached REMTECH water well tog to the appendices of the Contract Documents and Specifications.

ADD the attached Airport Buildings Demolition Asbestos Survey report to the appendices of the Contract Documents and Specifications.

END OF ADDENDUM

**SPOKANE INTERNATIONAL AIRPORT
SPOKANE, WASHINGTON
SIA Project #15-42-1849
AIRPORT BUILDINGS DEMOLITION**

PRE- BID CONFERENCE
August 13, 2015 1:00 pm

MEETING MINUTES

I. INTRODUCTIONS

(Please sign attendance roster. This is a mandatory meeting for all prime and asbestos contractors)

Spokane International Airport - Owner

Lisa Corcoran – Project Manager

Matt Breen – Acting Director, Planning and Engineering

Environmental Risk Management

Kevin McCrink – Asbestos Consultant

T-O Engineers

Trey Dail – Project Engineer

II. PROJECT DESCRIPTION

A. Overview –Site clearing and demolition of 8 buildings at SIA.

B. Project Schedule

- Mid October start.
- 148 calendar days for completion of project.
- All phase calendar days overlap with preceding and following phases due to separate asbestos abatement crew and demo crew.

C. Project Phasing

- Preconstruction Meeting - Submittals
- Phase 1 Building 2501 – 8600 W. Electric Avenue
- Phase 2 Building 85 – 8924 W. Electric Avenue
- Phase 3 Building 365 - 8120 W. Luke Avenue
- Phase 4 Building 360 – 7810 W. Luke Avenue
- Phase 5 Building 7 – 2945 S. Flint Road
- Phase 6 Building 1378 – 3707 Godfrey Boulevard
- Phase 7 Building 1424 – 7306 W. Pilot Drive
- Phase 8 Building 1425 - 7210 W. Pilot Drive

**SPOKANE INTERNATIONAL AIRPORT
SPOKANE, WASHINGTON
SIA Project #15-42-1849
AIRPORT BUILDINGS DEMOLITION**

PRE- BID CONFERENCE
August 13, 2015 1:00 pm

MEETING MINUTES

- Phasing has been established based on vacancy of buildings and proximity to other buildings. Phasing may be revised based on need for paved trench repair for specific buildings as asphalt plants will be shut down during winter months.

D. Construction Issues

- Demolition – Contractor to remove all buildings, fencing, and surface features to 3' below existing ground elevations unless otherwise noted on plans. If features are deeper than 3' below grade then portions below 3' may be abandoned in place. Remove landscaping, retain and protect large trees. Remove and dispose of all materials legally and properly offsite. Building 7 includes depressed ramps and foundation, these are being removed to 3' below existing elevations and will require additional backfill to make the site level and smooth with adjacent ground. Contractor required to backfill and grade site smooth. Backfill consists of 2" minus gravel fill material with 10% max on #200 sieve. All disturbed areas shall be capped with 4-inches of WSDOT crushed surfacing base course.
- Asbestos Abatement –Asbestos materials have been identified in all but one building (1425) for the project. Materials include but are not limited to insulation, roofing, sealant, piping. A complete list of materials is included in specifications. Pre abatement submittals are required for the project. Contractor must comply with all regulatory agencies.
- Asphalt Removal – All asphalt and concrete from site is being removed from the site as defined by the project limits noted on the plans. Cap all areas with 4" of WSDOT crushed surface base course following removal of asphalt and concrete. Existing base course found beneath existing asphalt does not constituted a capped site.

**SPOKANE INTERNATIONAL AIRPORT
SPOKANE, WASHINGTON
SIA Project #15-42-1849
AIRPORT BUILDINGS DEMOLITION**

PRE- BID CONFERENCE
August 13, 2015 1:00 pm

MEETING MINUTES

- Utilities – Contractor to coordinate locates with One Call, Spokane International Airport and Federal Aviation Administration (FAA) prior to beginning construction. FAA locates does not participate with local utility locates and must be contacted individually. FAA contact number is included in plans. Contractor to coordinate with Avista gas and electric for transformer and service removal. City of Spokane Water Department will be removing the meter and mainline tap. Contractor required to provide trenching, backfill out to mainline for removal of tap, City to complete actual removal and capping, Contractor to conduct paved trench repair, as necessary. Avista and City of Spokane Water Department requested 2 week lead time for scheduling removal for services and taps. City of Spokane Wasterwater Department is purveyor for sewer. Sewer services to be capped a minimum of 3' below grade. No coordination with waste water department is required. Contractor to mark all utilities found and removed on as built drawing set. All infrastructure below 3' shall be abandoned in place
- Underground Storage Tanks – Two tank vents have been identified, one at Bldg 2501 and on at Bldg 365. Removal and disposal of tank, it's contents, excavation and backfill are considered incidental to Building demolition. Tank sizes are unknown, contents unknown. Addenda will be issued to establish baseline parameters for bidding purposes to include an assumed amount of additional excavations required below the tank for removal of contaminated soils. Tank size, contents or excavation outside of or in excess of these parameters will be considered additional work. Contractor to maintain site open for 5 days to complete soil testing by Owner's representative. Owner's rep. must be on site during excavation and removal. Contractor to coordinate schedule with Owner.

**SPOKANE INTERNATIONAL AIRPORT
SPOKANE, WASHINGTON
SIA Project #15-42-1849
AIRPORT BUILDINGS DEMOLITION**

PRE- BID CONFERENCE
August 13, 2015 1:00 pm

MEETING MINUTES

- Domestic Well – Building 85 domestic well decommissioning must be completed by current license well driller. Size and depth of well is unknown at this time. Addenda will be issued to establish baseline parameters for bidding purposes to include an assumed size and depth of well. Work outside of or in excess of these parameters will be considered additional work.
 - Fencing – Buildings 2501 and 7 include temporary fencing. Building 7 includes permanent fencing. All fence consists of 7' tall chain link, 3 strand barb. Fence inspections are required as noted.
 - Security – Buildings 2501 and 7 are located in secure areas of airport. Temporary security fence will isolate project limits on unsecure side of airport perimeter fence. Installers and removers of temporary fence must be badge or escorted by badge personnel, airport will not provide escorts. Temporary fence inspection required after installation by airport police or engineer before demolition may begin. No gaps greater than 4" (2" on bottom), ecology blocks located on secure side, fitting bolts facing secure side. Inspection of installed permanent fencing required by airport police or engineer before removal of temporary fencing on building 7.
 - Dust Control and FOD control -Will be monitored by airport and corrected as necessary due to vicinity of work and impacts on airport operations.
 - Project Testing – Compaction tests required by certified testing consultant on all backfill and crushed surfacing. 90% Compaction on maximum 8" lifts and 2 tests per lift.
- E. Bidding – Sign Bid, 5% Bid Bond, Acknowledge Addenda, Fill in forms completely.
- Recent bids for projects have been thrown out and required rebidding due to careless, inattentive bidding practices by contractor. Contractor's must

**SPOKANE INTERNATIONAL AIRPORT
SPOKANE, WASHINGTON
SIA Project #15-42-1849
AIRPORT BUILDINGS DEMOLITION**

PRE- BID CONFERENCE
August 13, 2015 1:00 pm

MEETING MINUTES

be complete and comply with requirements of the bid documents and specifications.

- Three separate Bid Items for project – Demolition, Asbestos Abatement, Trenching Safety Systems. All work not included under asbestos abatement or trenching safety systems is considered incidental to demolition.

F. Administrative

- Washington State Prevailing Wages do Apply – Public Works Project.
- Liquidated damages - \$1,000 per day per phase
- Retainage 5% until all claims are resolved. (L&I, DOR, ESD)
- Performance and Payment Bonds – 100%
- Insurance – Raised to \$5,000,000 due to work on secure side of airport

III. QUESTIONS

All questions following meeting shall be forwarded in writing to Lisa Corcoran, Project Manager. Lisa's contact information can be found on the Call for Bids. Addenda will be issued addressing all contractor's questions. Questions will be taken until end of day, August .

Plans are available at <http://siaplanroom.com/public.php>.

IV. SITE TOUR

BID OPENING
11:00 AM WEDNESDAY, AUGUST 26, 2015
9000 West Airport Drive, Suite 204
Spokane, Washington 99224

**SPOKANE INTERNATIONAL AIRPORT
SPOKANE, WASHINGTON**

**SIA PROJECT #15-42-1849
AIRPORT BUILDINGS DEMOLITION**

Revised: August 18, 2015

TABLE OF CONTENTS

DIVISION 00 - PROCUREMENT AND CONTRACTING REQUIREMENTS

I. BIDDING INFORMATION

Call for Bids
Instructions to Bidders

II. BID PROPOSAL

Bidder's Checklist
Bid Proposal Form
Bid Schedule
Subcontractor List

III. GENERAL CONDITIONS

General Conditions for Spokane Airports Public Works Construction
Supplementary Conditions
Airport Construction Work Rules and Job Conditions
Contract Prevailing Wage Rates

DIVISION 01 - GENERAL REQUIREMENTS

01 10 00 Summary of Work
01 20 00 Construction Safety and Phasing Plan
01 30 00 Administrative Requirements
01 45 00 Quality Control
01 55 26 Traffic Control and Regulation
01 57 26 Dust Control
01 71 13 Mobilization
01 77 00 Closeout Procedures

TECHNICAL SPECIFICATIONS

02 41 00 Demolition of Existing Structures
02 41 13 Pavement Removal
02 82 33 Removal and Disposal of Asbestos-Containing Material
31 23 23 Compaction Watering
31 41 00 Trench Excavation Safety Systems
32 31 13 Chain Link Fences

APPENDICES

Inland Northwest Regional Pavement Cut Policy
Building 85 – Domestic Well Log
Airport Buildings Demolition Asbestos Survey

The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

File Original and First Copy with Department of Ecology
Second Copy—Owner's Copy
Third Copy—Driller's Copy

286611

WATER WELL REPORT

STATE OF WASHINGTON

Start Card No. W 21151

UNIQUE WELL I.D. # _____

Water Right Permit No. _____

(1) OWNER: Name Remtech Address 9109 W. Electric Ave., Spokane, WA 99204

(2) LOCATION OF WELL: County Spokane NW 1/4 NW 1/4 Sec 5 T. 24 N., R. 42E W.M.

(2a) STREET ADDRESS OF WELL (or nearest address) Parcel #24052.9013

(3) PROPOSED USE: Domestic Industrial Municipal
 Irrigation Test Well Other
 DeWater

(4) TYPE OF WORK: Owner's number of well (if more than one) _____
Abandoned New well Deepened Reconditioned
Method: Dug Cable Rotary
Bored Driven Jetted

(5) DIMENSIONS: Diameter of well 6 inches.
Drilled 100 feet. Depth of completed well 100 ft.

(6) CONSTRUCTION DETAILS:
Casing installed: 6 " Diam. from +2 ft. to 41 ft.
Welded PVC 4 " Diam. from 5 ft. to 100 ft.
Liner installed Threaded
Percorations: Yes No PVC Liner
Type of perforator used Skill Saw
SIZE of perforations 1/4 in. by 5 in.
80 perforations from 80 ft. to 100 ft.

Screens: Yes No
Manufacturer's Name _____
Type _____ Model No. _____
Diam. _____ Slot size _____ from _____ ft. to _____ ft.
Diam. _____ Slot size _____ from _____ ft. to _____ ft.

Gravel packed: Yes No Size of gravel _____
Gravel placed from _____ ft. to _____ ft.

Surface seal: Yes No To what depth? 18 ft.
Material used in seal Bentonite Slurry
Did any strata contain unusable water? Yes No
Type of water? _____ Depth of strata _____
Method of sealing strata off _____

(7) PUMP: Manufacturer's Name _____
Type: _____ H.P. _____


(8) WATER LEVELS: Land-surface elevation above mean sea level _____ ft.
Static level 30 ft. below top of well Date _____
Artesian pressure _____ lbs. per square inch Date _____
Artesian water is controlled by _____ (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? Yes No If yes, by whom? _____
Yield: 15 gal./min. with _____ ft. drawdown after _____ hrs.
" ESTIMATED AIRLIFT "
" " "

(10) WELL LOG or ABANDONMENT PROCEDURE DESCRIPTION

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of information.

MATERIAL	FROM	TO
Large Cobbles & Boulders	0	13
Clay, Brown W/Gravels	13	30
Clay, Tan	30	40
Broken Basalt, Gray	40	43
Broken Basalt W/Clay, Brown	43	62
Basalt, Gray, Hard	62	63
Basalt, Rusty Red	63	65
Basalt, Gray, Hard	65	90
Broken Basalt, Gray & Red W/Water	90	100



6" Drive Shoe Utilized
4" to 6" Formation Packer Utilized

Work started 9-4-93, 19. Completed 9-5-93, 19.

WELL CONSTRUCTOR CERTIFICATION:
I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to my best knowledge and belief.

NAME Ponderosa Drilling & Development, Inc.
(PERSON, FIRM, OR CORPORATION) (TYPE OR PRINT)

Address E. 6010 Broadway, Spokane, WA 99212

(Signed) Roger Kelly License No. 2004
(WELL DRILLER)

Contractor's Registration (Roger Kelly)
No. PO-ND-EI*248JE Date September 13, 19 93

(USE ADDITIONAL SHEETS IF NECESSARY)



Asbestos Survey

**AIRPORT BUILDINGS DEMOLITION, SPOKANE
INTERNATIONAL AIRPORT, SIA PROJECT 15-42-1849**

**Building 7, 2945 South Flint Road
Building 85, 8924 West Electric Avenue
Building 360, 7810 West Luke Avenue
Building 365, 8120 West Luke Avenue
Building 1378, 3707 Godfrey Boulevard
Building 1424, 7306 West Pilot Drive
Building 1425, 7210 West Pilot Drive
Building 2501, 8600 West Electric Avenue**

Spokane, Washington

Project No.: ERM-15-130

**By
Environmental Risk Management
1324 Liberty Lake Road #231
Liberty Lake, Washington 99019
Phone: (509) 991-7357**

August 14, 2015

Prepared for:

**Spokane International Airport
9000 West Airport Drive #204
Spokane, Washington 99224**

TABLE OF CONTENTS	Page
1.0 EXECUTIVE SUMMARY	1
2.0 INTRODUCTION	11
2.1 Purpose	
2.2 Scope of Services	
2.3 Authorization	
2.4 Warranty	
3.0 METHODOLOGY	12
3.1 Inspection Procedure	
3.2 Sampling Procedure	
4.0 LABORATORY METHODOLOGY	13
4.1 Method of Analysis-Asbestos	
4.2 Laboratory Quality Assurance	
5.0 ASBESTOS FINDINGS	13
5.1 Asbestos Containing Materials	
5.2 Non-Asbestos Materials	
APPENDIX	
Appendix A: Inspector Certification	
Appendix B: Bulk Asbestos Analytical Results	
Appendix C: Laboratory Certification	

1.0 Executive Summary

Environmental Risk Management was retained by the Spokane Airports to conduct an asbestos survey for the Multiple Building Demolition Project, located at the Spokane International Airport, in Spokane, Washington. The survey was conducted from July 1st through July 24th, 2015.

General Building Observations

The survey included SIA Buildings 7, 85, 360, 365, 1378, 1424, 1425, and 2501

Building 7 is a one-story commercial high bay building approximately 7,800 square feet in size. The original construction date was in the 1960's. The building was constructed as a flight kitchen food preparation facility and is currently vacant. The exterior wall system is a combination of structural framing, concrete and CMU block finished with fiberglass decorative panels. The roof structure is corrugated metal panel. The north area of the building is finished as an office with sheetrock walls and the ceiling system is drop-in 2x4 ceiling tiles in a suspended metal frame. The remaining areas of the building interior are unfinished and have concrete floors with epoxy flooring in the food prep areas. The exterior door jambs are steel with steel doors. The exterior windows are steel frame. The heating system for the building is roof-mounted gas and electric forced air furnaces. Roll-up overhead doors are present on the north and south sides of the building in the loading dock areas.

Building 85 is a two-story commercial building approximately 2,300 square feet in size. The original construction date was in the 1900's. The building was constructed as an electrical service station for a rail line and is currently vacant office space. The exterior wall system is brick and mortar. The roof structure is wood. The interior walls and ceilings are textured sheetrock. The floors are a combination of carpeting, laminate wood flooring and sheet vinyl in the restrooms.

Building 360 is a one-story commercial building approximately 4,300 square feet in size. The original construction date was in the 1940's. The building was constructed for military personnel use. The exterior wall system is a combination of structural framing and CMU block. The roof structures are wood truss with wood decks. Transite panel siding is present on the upper areas of the building exterior. The southeast area of the building is finished as an office with sheetrock walls and ceilings, floor tile and carpeting floor coverings in the main office areas and sheet vinyl in the restroom. The remaining areas of the building interior are unfinished warehouse space with bare concrete floors. The exterior door jambs are steel with steel doors. The exterior windows are steel frame. The heating systems for the building are roof-mounted gas and electric forced air furnaces. Roll-up overhead doors are present on the north and west sides of the building.

Building 365 is a one-story commercial building approximately 4,500 square feet in size. The original construction date was in the 1940's. The building was constructed as for military parachute maintenance. The building has been redesigned as light manufacturing. The exterior wall system is structural framing with a transite shingle exterior. The roof structure is flat. The southeast area of the building is finished as an office with sheetrock walls and the ceiling system is drop-in 2x4 ceiling tiles in a

suspended metal frame. The remaining areas of the building interior have concrete floors, sheetrock walls and ceilings. The exterior door jambs are steel with steel doors. The exterior windows are steel frame. The heating systems for the building are roof-mounted gas and electric forced air furnaces and radiant heat from a boiler room located in the southeast corner of the building. A roll-up overhead door is present on the east side of the building. Two CMU block outbuildings are present. Both buildings have flat roofs and unfinished interiors.

Building 1378 is a one-story commercial building approximately 10,500 square feet in size. The original construction date was in the 1940's. The building was originally constructed as a military mess hall. The building was renovated for office use with sheetrock walls and ceilings with a suspended ceiling system. The building floors have 9x9 floor tile covered with carpeting in the office areas and hallways. Sheet vinyl covers the floor tile in the restrooms and kitchen area. The exterior is wood siding with asphalt composite roofing in the office section. The kitchen section has a rubber membrane roof over built-up roofing. The heating systems for the building are roof-mounted gas and electric forced air furnaces.

Building 1424 is a one-story commercial building approximately 9,100 square feet in size. The original construction date was in the 1940's. The building is wood framed with wood siding and an asphalt composite shingle roof. The interior is predominantly unfinished with particle paper ceiling panels, unfinished wood floors, and sheetrock walls. Insulated radiant steam piping is present on the building interior. Loading docks with overhead roll-up doors are present on the south side of the building.

Building 1425 is a one-story commercial building approximately 9,100 square feet in size. The original construction date was in the 1940's. The building is wood framed with wood siding and an asphalt composite shingle roof. The interior is predominantly unfinished with unfinished wood floors, and walls. The building was renovated for office use in the west area with sheetrock walls and a suspended ceiling system. The ceiling system is drop-in 2x4 ceiling tiles in a suspended metal frame. The building floors are carpeting in the office areas and sheet vinyl covers the floors in the restrooms and hallway area. The exterior is wood siding with asphalt composite roofing shingles. Loading docks with overhead roll-up doors are present on the south side of the building.

Building 2501 is a one-story commercial building approximately 9,200 square feet in size. The original construction date was in the 1940's. The building was constructed for military personnel. The wall system is structural framing with a transite shingle exterior. The roof structure is flat. The building interior is finished as an office with sheetrock walls and the ceiling system is drop-in 2x4 ceiling tiles in a suspended metal frame. The remaining service areas of the building interior have concrete floors, sheetrock walls and ceiling tile ceilings. The exterior door jambs are steel with steel doors. The exterior windows are steel frame. The heating systems for the building are gas and electric forced air furnaces located in the mechanical room.

Asbestos Containing Materials

The materials that were sampled and analyzed from the **SIA Multiple Building Demolition Project** and found to contain asbestos consist of the following.

Building 7, Class I Materials: Interior Vermiculite

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
CMU walls block cavities	Vermiculite insulation in CMU block chamber cavity Estimated quantity: 1,060 square feet of CMU wall	Assumed asbestos	Yes	Yes Assumed asbestos	Miscellaneous	Good

Building 7, Class II Materials: Exterior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Exterior metal roof exposed surface, roof panel undersides and roof panel seams	All roof sealers Estimated quantity: 9,000 s.f. of roof	7-58, 7-59, 7-60, 7-61, 7-62, 7-63, 7-64, 7-65, 7-66, 7-67, 7-68, 7-69, 7-70, 7-71, 7-72	No	Yes Roof sealer: 0%-10% Chrysotile	Miscellaneous	Good

Building 85, Class II Materials: Exterior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Main building roofs, roof mastics	All roofs, roof mastics, and sealers Estimated quantity: 1,370 s.f. of roof	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good

Building 360, Class II Materials: Exterior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Main building roofs	All roofs, roof mastics, and sealers Estimated quantity: 5,180 s.f. of roof	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good
Building soffits, fascia, and siding	Transite panels and shingles Estimated quantity: 1,700 s.f.	360-1	No	Yes Transite: 15% Chrysotile	Miscellaneous	Good
All window frames, door frames, and building seams	All caulking and sealers Estimated quantity: 100 s.f.	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good
Three dock bollards on west side of building	Gray cloth/black tar Estimated quantity: 24 s.f.	360-65, 360-66	No	Yes Gray cloth: 70% Chrysotile Black sealer: 2%-4% Chrysotile	Miscellaneous	Fair

Building 360, Class II Materials: Interior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Main building east warehouse floor	Black residual floor mastic Estimated quantity: 50	360-11, 360-12	No	Yes Black mastic: 5%-8% Chrysotile		

	s.f.					
Main building ceiling south and east walls of office area	Transite panels and joint compound on edges and corners. (office area will need to be demoed to access transite walls) Estimated quantity: 3,100 s.f.	360-15. 360-16, 360-26, 360-27	No	Yes Joint compound: 3% Chrysotile Transite: 15% Chrysotile	Miscellaneous	Good
Main building east office area warehouse office, north entrance floor	Green 9x9 floor tile Estimated quantity: 25 s.f.	360-35. 360-36	No	Yes Floor tile: 3% Chrysotile Mastic: Assumed asbestos	Miscellaneous	Good
Main building east office area warehouse office walls	Green wall paneling mastic Estimated quantity: 300 s.f.	360-39. 360-40	No	Yes Wall paneling mastic: 15% Chrysotile	Miscellaneous	Good
Main building east office area warehouse office, southwest entrance floor and potentially under partition walls	White 12x12 floor tile Estimated quantity: 30 s.f.	360-35. 360-36	No	Yes Floor tile: 3% Chrysotile Mastic: N.D.	Miscellaneous	Good
Main building	Gray 12x12 floor tile/	360-43. 360-44	No	Yes Floor tile:	Miscellaneous	Good

center office area break room and restroom floors and potentially under partition walls	black mastic Estimated quantity: 200 s.f.			N.D. Mastic: 5% Chrysotile		
Main building center office area restroom floor and potentially under partition walls	Black mastic under sheet vinyl flooring Estimated quantity: 200 s.f.	360-48. 360-49	No	Yes Sheet vinyl: N.D. Mastic: N.D. Sheet vinyl: N.D. Black mastic: 3% Chrysotile	Miscellaneous	Good
Main building west office area floor and potentially under partition walls	Black carpet mastic Estimated quantity: 205 s.f.	360-56. 360-57	No	Yes Carpet: N.D. Black mastic: 5% Chrysotile	Miscellaneous	Good

Building 365, Class II Materials: Main Building Exterior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Main building roofs and HVAC units	All roofs, roof mastics, and sealers Estimated quantity: 5,495 s.f. of roof	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good
Building exterior siding	Transite shingles Estimated quantity:	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good

	5,684 s.f.					
Exterior windows	Window glazing Estimated quantity: 70 s.f.	365-1, 365-2, 365-3, 365-4, 365-5, 365-6, 365-7, 365-8, 365-9, 365-10	No	Yes Window glazing: 0%-3% Chrysotile	Miscellaneous	Fair
All window frames, door frames, and building seams	All caulking and sealers Estimated quantity: 210 s.f.	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good

Building 365, Class II Materials: North Outbuilding Exterior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Building roof	All roofs, roof mastics, and sealers Estimated quantity: 595 s.f. of roof	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good
Building soffit and interior ceiling	Transite panels Estimated quantity: 590 s.f.	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good
Exterior windows	Window glazing Estimated quantity: 8 s.f.	365-1-1, 365-1-2, 365-1-3, 365-1-4	No	Yes Window glazing 0%-3% Chrysotile	Miscellaneous	Fair
All window frames, door	All caulking and sealers Estimated	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good

frames, and building seams	quantity: 30 s.f.					
----------------------------	-------------------	--	--	--	--	--

Building 365, Class II Materials: West Outbuilding Exterior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Main building roofs	All roofs, roof mastics, and sealers Estimated quantity: 310 s.f. of roof	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good
Exterior windows	Window glazing Estimated quantity: 2 s.f.	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Fair
All window frames, door frames, and building seams	All caulking and sealers Estimated quantity: 10 s.f.	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Fair
Building Interior floor	Brown sheet vinyl/ black mastic Estimated quantity: 134 s.f.	365-2-1, 365-2-1	No	Yes Sheet vinyl: N.D. Mastic: 4%-5% Chrysotile	Miscellaneous	Good

Building 1378, Class II Materials: Exterior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
East roof under rubber membrane roof with roof top	All roofs, roof mastics, and sealers Estimated	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good

HVAC units	quantity: 4,278 s.f. of roof					
East cooler, east fascia	Transite panel Estimated quantity: 6 s.f.	1378-87	No	Yes 15% Chrysotile	Miscellaneous	Good

Building 1378, Class II Materials: Interior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Main building floors throughout and potentially under partition walls	All floor coverings and mastics. Bottom layer is 9x9 asbestos floor tile and asbestos black mastic on wood. Estimated quantity: 9,800 s.f.	1378-14, 1378-15, 1378-20, 1378-21, 1378-24, 1378-30, 1378-34, 1378-42, 1378-52, 1378-53, 1378-54, 1378-58, 1378-59	No	Yes Floor tile: 15%-8% Chrysotile Black mastic: 3%-4% Chrysotile		

Building 1424, Class I Materials: Interior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Building interior	Pipe insulation and mudded fittings Estimated quantity: 720 l.f.	Assumed asbestos	Yes	Yes Assumed asbestos	Thermal System Insulation	Good

Building 1425

No asbestos materials were identified.

Building 2501, Class II Materials: Exterior

Material	Material	Sample	Friable	Asbestos	Type	Condition
----------	----------	--------	---------	----------	------	-----------

Location	Description	Number	Yes/No			
Building roofs	All roofs, roof mastics, and sealers Estimated quantity: 9,316 s.f.	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good
Building siding.	Transite shingles Estimated quantity: 6,970 s.f.	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Fair
Exterior windows	Window glazing Estimated quantity: 50 s.f.	2501-58, 2501-59	No	Yes Window glazing: 5% Chrysotile	Miscellaneous	Fair
All window frames, door frames, and building seams	All caulking and sealers Estimated quantity: 100 s.f.	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good

Building 2501, Class II Materials: Interior


Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Main building floors and potentially under partition walls	All floor coverings and mastics. Bottom layer is 9x9 asbestos floor tile and asbestos black mastic on concrete. Estimated quantity:	2501-1, 2501-2	No	Yes Floor tile:10% Chrysotile Black mastic: 5% Chrysotile	Miscellaneous	Good

	8,510 s.f.					
Office area ceilings	White 2x4 floral pattern, pin hole ceiling tile. Estimated quantity: 4,800 s.f.	2501-1, 2501-2	Yes	Yes Ceiling tile:4%-5% Amosite 1% Chrysotile	Miscellaneous	Good
Vault area ceiling	White 2x4 worm hole pattern ceiling tile. Estimated quantity:48 s.f.	2501-1, 2501-2	Yes	Yes Ceiling tile:4%-5% Amosite 1% Chrysotile	Miscellaneous	Good

ACM quantities are estimates only. It is the Abatement Contractor's responsibility to verify ACM quantities and field conditions for bidding purposes.

Reference the Asbestos Findings section and the analytical appendix of this report for specific sample information.

Signed,



Kevin McCrink,
 AHERA/EPA Accredited Inspector #151416. Expires April 30, 2016
 AHERA/EPA Accredited Project Designer #151424. Expires April 29, 2016

2.0 Introduction

2.1 Purpose

The purpose of the asbestos survey was to provide information identifying the presence of exposed and/or accessible suspect building materials that commonly contain asbestos.

2.2 Scope of Work

The scope of work consisted of conducting a visual inspection and sampling survey in accordance with OSHA 29 CFR 1926.1101 and NESHAPS 40 CFR part 61 guidelines to determine the presence of suspected asbestos containing building materials (ACBM) which were exposed and/or accessible.

The bulk samples collected from the project area were analyzed at an accredited laboratory to determine the presence and concentrations of asbestos.

2.3 Authorization

Authorization to perform this survey was given by Ms. Lisa Corcoran, Project Manager, SIA Planning and Engineering Department.

2.4 Warranty

The field and laboratory results reported herein are considered sufficient in detail and scope to determine the presence of exposed and/or accessible suspect asbestos containing building materials in the building at the time of the inspection. Environmental Risk Management warrants that the findings contained herein have been prepared in the general accordance with accepted professional practices at the time of its preparation as applied by similar professionals in the industry. Changes in the state of the art or in applicable regulations cannot be anticipated and have not been addressed in this report.

The survey and analytical methods have been used to provide the client with information regarding the presence of accessible and/or exposed suspect asbestos containing building materials existing in the buildings at the time of the inspection. There is a distinct possibility that conditions may exist which were not apparent during the site visit. This inspection covered only those areas that were exposed and/or accessible to the inspector. The investigation is also limited to the information available from the client at the time of the investigation. Should the scope of the demolition project change, Environmental Risk Management recommends that an additional investigation, including but not limited to, a review of the revised scope of work, be performed to determine if asbestos-containing materials or suspect asbestos-containing materials will be impacted. No other warranties are implied or expressed.

3.0 Methodology

3.1 Inspection Procedures

Kevin McCrink, AHERA accredited inspector # 146779 conducted the asbestos survey. The initial inspection consisted of the inspector walking through the project area of the building in order to determine the general building lay out, draw a site sketch and to determine the presence of exposed and/or reasonably accessible suspect asbestos containing materials. The suspect materials were then grouped into homogenous material groups that were collected during the sampling phase.

3.2 Sampling Procedures

Following the inspection phase, the materials that were identified and grouped into homogenous suspect asbestos materials were then sampled. The sampling was limited to those materials which were exposed and/or accessible and which did not require extensive destructive access in order to sample.

The sampling protocol followed was consistent with the guidelines set forth in OSHA 29 CFR 1926.1101 and NESHAPS 40 part 61. Efforts were made to select random sampling locations, but preference was given to damaged or disturbed areas in order to minimize the damage to the building's finished surfaces. The sampling and inspection was conducted in the least disruptive manor as possible to the suspect building materials.

A copy of the Inspector's accreditation can be found in Appendix B.

4.0 Methodology

4.1 Method of Analysis

The analysis of the bulk samples for asbestos was performed by EPA method 600/M4-82-020. The bulk samples were prepared for visual examination and identification by polarizing light microscopy. Following the preparation of the material on a glass slide the samples were analyzed for asbestos forms of chrysotile, crocidolite, anthophyllite, actinolite/tremolite, amosite and non-asbestos components that totaled 100% of the sample volume. Asbestos and non-asbestos elements of each sample were identified utilizing, the unique optical properties associated with them. The identification consisted of identifying specific optical and physical characteristics that included refractive indices, color, pleochroism, birefringence, extinction angles, and sign of elongation and morphology. The volume percentage of each component in the sample was determined by visually estimating the percentage.

4.2 Laboratory Quality Assurance

The asbestos bulk samples collected from the building in this project were sent to EMC Labs, Inc. located in Phoenix, Arizona for analysis. EMC Labs, Inc. is an accredited analytical laboratory.

5.0 Findings

5.1 Asbestos Containing Materials

OSHA/EPA defines a material to be an asbestos containing material (ACM) in the material contains greater than one percent (>1%) asbestos. Multiple samples are collected and if one sample out of the homogenous sampling group is found to contain asbestos then the material is determined to be an asbestos containing material.

Asbestos Containing Materials

The materials that were sampled and analyzed from the **SIA Multiple Building Demolition Project** and found to contain asbestos consist of the following.

Building 7, Class I Materials: Interior Vermiculite

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
CMU	Vermiculite	Assumed	Yes	Yes	Miscellaneous	Good

walls block cavities	insulation in CMU block chamber cavity Estimated quantity: 1,060 square feet of CMU wall	asbestos		Assumed asbestos		
----------------------------	--	----------	--	---------------------	--	--

Building 7, Class II Materials: Exterior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Exterior metal roof exposed surface, roof panel undersides and roof panel seams	All roof sealers Estimated quantity: 9,000 s.f. of roof	7-58, 7-59, 7-60, 7-61, 7-62, 7-63, 7-64, 7-65, 7-66, 7-67, 7-68, 7-69, 7-70, 7-71, 7-72	No	Yes Roof sealer: 0%-10% Chrysotile	Miscellaneous	Good

Building 85, Class II Materials: Exterior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Main building roofs, roof mastics	All roofs, roof mastics, and sealers Estimated quantity: 1,370 s.f. of roof	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good

Building 360, Class II Materials: Exterior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Main building roofs	All roofs, roof mastics, and sealers Estimated	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good

	quantity: 5,180 s.f. of roof					
Building soffits, fascia, and siding	Transite panels and shingles Estimated quantity: 1,700 s.f.	360-1	No	Yes Transite: 15% Chrysotile	Miscellaneous	Good
All window frames, door frames, and building seams	All caulking and sealers Estimated quantity: 100 s.f.	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good
Three dock bollards on west side of building	Gray cloth/black tar Estimated quantity: 24 s.f.	360-65, 360-66	No	Yes Gray cloth: 70% Chrysotile Black sealer: 2%-4% Chrysotile	Miscellaneous	Fair

Building 360, Class II Materials: Interior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Main building east warehouse floor	Black residual floor mastic Estimated quantity: 50 s.f.	360-11, 360-12	No	Yes Black mastic: 5%-8% Chrysotile		
Main building ceiling south and east walls of office area	Transite panels and joint compound on edges and corners. (office area will need to be demoed)	360-15, 360-16, 360-26, 360-27	No	Yes Joint compound: 3% Chrysotile Transite: 15% Chrysotile	Miscellaneous	Good

	to access transite walls) Estimated quantity: 3,100 s.f.					
Main building east office area warehouse office, north entrance floor	Green 9x9 floor tile Estimated quantity: 25 s.f.	360-35. 360-36	No	Yes Floor tile: 3% Chrysotile Mastic: Assumed asbestos	Miscellaneous	Good
Main building east office area warehouse office walls	Green wall paneling mastic Estimated quantity: 300 s.f.	360-39. 360-40	No	Yes Wall paneling mastic: 15% Chrysotile	Miscellaneous	Good
Main building east office area warehouse office, southwest entrance floor and potentially under partition walls	White 12x12 floor tile Estimated quantity: 30 s.f.	360-35. 360-36	No	Yes Floor tile: 3% Chrysotile Mastic: N.D.	Miscellaneous	Good
Main building center office area break room and restroom floors and potentially under partition walls	Gray 12x12 floor tile/ black mastic Estimated quantity: 200 s.f.	360-43. 360-44	No	Yes Floor tile: N.D. Mastic: 5% Chrysotile	Miscellaneous	Good
Main	Black	360-48.	No	Yes	Miscellaneous	Good

building center office area restroom floor and potentially under partition walls	mastic under sheet vinyl flooring Estimated quantity: 200 s.f.	360-49		Sheet vinyl: N.D. Mastic: N.D. Sheet vinyl: N.D. Black mastic: 3% Chrysotile		
Main building west office area floor and potentially under partition walls	Black carpet mastic Estimated quantity: 205 s.f.	360-56. 360-57	No	Yes Carpet: N.D. Black mastic: 5% Chrysotile	Miscellaneous	Good

Building 365, Class II Materials: Main Building Exterior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Main building roofs and HVAC units	All roofs, roof mastics, and sealers Estimated quantity: 5,495 s.f. of roof	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good
Building exterior siding	Transite shingles Estimated quantity: 5,684 s.f.	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good
Exterior windows	Window glazing Estimated quantity: 70 s.f.	365-1, 365-2, 365-3, 365-4, 365-5, 365-6, 365-7, 365-8, 365-9, 365-10	No	Yes Window glazing: 0%-3% Chrysotile	Miscellaneous	Fair

All window frames, door frames, and building seams	All caulking and sealers Estimated quantity: 210 s.f.	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good
--	--	------------------	----	-------------------------	---------------	------

Building 365, Class II Materials: North Outbuilding Exterior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Building roof	All roofs, roof mastics, and sealers Estimated quantity: 595 s.f. of roof	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good
Building soffit and interior ceiling	Transite panels Estimated quantity: 590 s.f.	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good
Exterior windows	Window glazing Estimated quantity: 8 s.f.	365-1-1, 365-1-2, 365-1-3, 365-1-4	No	Yes Window glazing 0%-3% Chrysotile	Miscellaneous	Fair
All window frames, door frames, and building seams	All caulking and sealers Estimated quantity: 30 s.f.	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good

Building 365, Class II Materials: West Outbuilding Exterior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Main building roofs	All roofs, roof mastics,	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good

	and sealers Estimated quantity: 310 s.f. of roof					
Exterior windows	Window glazing Estimated quantity: 2 s.f.	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Fair
All window frames, door frames, and building seams	All caulking and sealers Estimated quantity: 10 s.f.	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Fair
Building Interior floor	Brown sheet vinyl/ black mastic Estimated quantity: 134 s.f.	365-2-1, 365-2-1	No	Yes Sheet vinyl: N.D. Mastic: 4%-5% Chrysotile	Miscellaneous	Good

Building 1378, Class II Materials: Exterior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
East roof under rubber membrane roof with roof top HVAC units	All roofs, roof mastics, and sealers Estimated quantity: 4,278 s.f. of roof	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good
East cooler, east fascia	Transite panel Estimated quantity: 6 s.f.	1378-87	No	Yes 15% Chrysotile	Miscellaneous	Good

Building 1378, Class II Materials: Interior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Main building floors throughout and potentially under partition walls	All floor coverings and mastics. Bottom layer is 9x9 asbestos floor tile and asbestos black mastic on wood. Estimated quantity: 9,800 s.f.	1378-14, 1378-15, 1378-20, 1378-21, 1378-24, 1378-30, 1378-34, 1378-42, 1378-52, 1378-53, 1378-54, 1378-58, 1378-59	No	Yes Floor tile: 15%-8% Chrysotile Black mastic: 3%-4% Chrysotile		

Building 1424, Class I Materials: Interior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Building interior	Pipe insulation and mudded fittings Estimated quantity: 720 l.f.	Assumed asbestos	Yes	Yes Assumed asbestos	Thermal System Insulation	Good

Building 1425

No asbestos materials were identified.

Building 2501, Class II Materials: Exterior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Building roofs	All roofs, roof mastics, and sealers Estimated quantity: 9,316 s.f.	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good
Building siding.	Transite shingles	Assumed asbestos	No	Yes Assumed	Miscellaneous	Fair

	Estimated quantity: 6,970 s.f.			asbestos		
Exterior windows	Window glazing Estimated quantity: 50 s.f.	2501-58, 2501-59	No	Yes Window glazing: 5% Chrysotile	Miscellaneous	Fair
All window frames, door frames, and building seams	All caulking and sealers Estimated quantity: 100 s.f.	Assumed asbestos	No	Yes Assumed asbestos	Miscellaneous	Good

Building 2501, Class II Materials: Interior

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Main building floors and potentially under partition walls	All floor coverings and mastics. Bottom layer is 9x9 asbestos floor tile and asbestos black mastic on concrete. Estimated quantity: 8,510 s.f.	2501-1, 2501-2	No	Yes Floor tile:10% Chrysotile Black mastic: 5% Chrysotile	Miscellaneous	Good
Office area ceilings	White 2x4 floral pattern, pin hole ceiling tile. Estimated quantity: 4,800 s.f.	2501-1, 2501-2	Yes	Yes Ceiling tile:4%-5% Amosite 1% Chrysotile	Miscellaneous	Good
Vault	White 2x4	2501-1,	Yes	Yes	Miscellaneous	Good

area ceiling	worm hole pattern ceiling tile. Estimated quantity:48 s.f.	2501-2		Ceiling tile:4%-5% Amosite 1% Chrysotile		
--------------	---	--------	--	---	--	--

5.2 Non-Asbestos Containing Materials

OSHA/EPA defines a material to be an asbestos containing material (ACM) in the material contains greater than one percent (>1%) asbestos. Multiple samples are collected and if one sample out of the homogenous sampling group is found to contain asbestos then the material is determined to be an asbestos containing material.

Specific materials sampled for **SIA Multiple Building Demolition Project** that were found **not to contain asbestos** and can be found in the following tables.

SIA Building 7- Non-Asbestos Containing Materials

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Interior walls	Sheetrock/ joint compound	7-1	No	No Sheetrock: N.D. Joint compound: N.D.	Miscellaneous	Good
Interior walls	Sheetrock/ joint compound	7-2	No	No Sheetrock: N.D. Joint compound: N.D.	Miscellaneous	Good
Water tank	White lagging	7-3	No	No Lagging: N.D.	Thermal System Insulation	Good
Water tank	White wrap/ white packing/ yellow foam	7-4	No	No Tank wrap: N.D. White packing: N.D. Yellow foam insulation: N.D.	Thermal System Insulation	Good
Water tank	White wrap/ white packing/ yellow foam	7-5	No	No Tank wrap: N.D. White packing: N.D. Yellow	Thermal System Insulation	Good

				foam insulation: N.D.		
Water tank	White packing/ yellow foam	7-6	No	No White packing: N.D. Yellow foam insulation: N.D.	Thermal System Insulation	Good
Water piping	White-silver wrap/ yellow fiberglass pipe insulation	7-7	No	No Pipe wrap: N.D. Pipe insulation: N.D.	Thermal System Insulation	Good
Water piping	White-silver wrap/ yellow fiberglass pipe insulation	7-8	No	No Pipe wrap: N.D. Pipe insulation: N.D.	Thermal System Insulation	Good
Water piping	White-silver wrap/ yellow fiberglass pipe insulation	7-9	No	No Pipe wrap: N.D. Pipe insulation: N.D.	Thermal System Insulation	Good
Office area ceilings	White 2x4 ceiling tile	7-10	No	No Ceiling tile: N.D.	Miscellaneous	Good
Office area ceilings	White 2x4 ceiling tile	7-11	No	No Ceiling tile: N.D.	Miscellaneous	Good
Office area walls	Medium brown 5" cove base/ mastic	7-12	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Office area walls	Medium brown 5" cove base/ mastic	7-13	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Office area walls	Sheetrock/ joint compound	7-14	No	No Sheetrock: N.D. Joint compound: N.D.	Miscellaneous	Good
Office area walls	Tan cove base/ mastic	7-15	No	No Cove base: N.D. Mastic:	Miscellaneous	Good

				N.D.		
Office area walls	Tan cove base/ mastic	7-16	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Kitchen area floors	Dark tan floor mastic	7-17	No	No Floor mastic: N.D.	Miscellaneous	Good
Kitchen area floors	Dark tan floor mastic	7-18	No	No Floor mastic: N.D.	Miscellaneous	Good
Bathroom area floors	Blue 2x2 ceramic tile/ dark gray cement	7-19	No	No Ceramic tile: N.D. Cement: N.D.	Miscellaneous	Good
Bathroom area floors	Blue 2x2 ceramic tile/ dark gray cement	7-20	No	No Ceramic tile: N.D. Cement: N.D.	Miscellaneous	Good
Bathroom area floors	Dark gray grout	7-21	No	No Grout: N.D.	Miscellaneous	Good
Bathroom area floors	Dark gray grout	7-22	No	No Grout: N.D.	Miscellaneous	Good
Bathroom area floors	Gray framing caulk	7-23	No	No Framing caulk: N.D.	Miscellaneous	Good
Bathroom area floors	Gray framing caulk	7-24	No	No Framing caulk: N.D.	Miscellaneous	Good
HVAC ducts	Beige HVAC duct tape	7-25	No	No HVAC duct tape: N.D.	Miscellaneous	Good
HVAC ducts	Beige HVAC duct tape	7-26	No	No HVAC duct tape: N.D.	Miscellaneous	Good
Kitchen area floors	Brown epoxy flooring	7-27	No	No Epoxy flooring: N.D.	Miscellaneous	Good
Kitchen area floors	Brown epoxy flooring	7-28	No	No Epoxy flooring: N.D.	Miscellaneous	Good
HVAC ducts	White HVAC duct caulk	7-29	No	No HVAC duct caulk: N.D.	Miscellaneous	Good
HVAC ducts	White HVAC duct caulk	7-30	No	No HVAC duct caulk: N.D.	Miscellaneous	Good

Kitchen area walls	Tan wall mastic/ sheetrock	7-31	No	No Wall mastic: N.D. Sheetrock: N.D.	Miscellaneous	Good
Kitchen area walls	Tan wall mastic	7-32	No	No Wall mastic: N.D.	Miscellaneous	Good
Kitchen area walls	Tan wall mastic	7-33	No	No Wall mastic: N.D.	Miscellaneous	Good
Kitchen area walls	Tan wall glue	7-34	No	No Wall glue: N.D.	Miscellaneous	Good
Kitchen area walls	Tan wall glue	7-35	No	No Wall glue: N.D.	Miscellaneous	Good
Kitchen area cooler	Yellow cooler foam insulation	7-36	No	No Cooler foam insulation: N.D.	Miscellaneous	Good
Kitchen	Yellow cooler foam insulation	7-37	No	No Cooler foam insulation: N.D.	Miscellaneous	Good
Kitchen area walls	Gray CMU block	7-38	No	No CMU block: N.D.	Miscellaneous	Good
Kitchen area walls	Gray CMU block	7-39	No	No CMU block: N.D.	Miscellaneous	Good
Kitchen area walls	White mortar	7-40	No	No Mortar: N.D.	Miscellaneous	Good
Kitchen area walls	White mortar	7-41	No	No Mortar: N.D.	Miscellaneous	Good
Exterior walls	Lt. brown exterior wall panel	7-42	No	No Exterior wall panel: N.D.	Miscellaneous	Good
Exterior walls	Lt. brown exterior wall panel	7-43	No	No Exterior wall panel: N.D.	Miscellaneous	Good
Exterior walls	Lt. brown exterior wall panel	7-44	No	No Exterior wall panel: N.D.	Miscellaneous	Good

Exterior walls	Lt. brown exterior wall panel	7-45	No	No Exterior wall panel: N.D.	Miscellaneous	Good
Exterior walls	White styrofoam insulation	7-46	No	No Styro foam insulation: N.D.	Miscellaneous	Good
Exterior walls	White styrofoam insulation	7-47	No	No Styro foam insulation: N.D.	Miscellaneous	Good
Exterior walls	Lt. brown-gray cement stucco	7-48	No	No Cement stucco: N.D.	Miscellaneous	Good
Exterior walls	Lt. brown-gray cement stucco	7-49	No	No Cement stucco: N.D.	Miscellaneous	Good
Exterior walls	Lt. brown-gray cement stucco	7-50	No	No Cement stucco: N.D.	Miscellaneous	Good
Exterior walls	Lt. brown-gray cement stucco	7-51	No	No Cement stucco: N.D.	Miscellaneous	Good
Exterior wall cavities	Exterior sheetrock/ paper	7-52	No	No Sheetrock/ paper: N.D.	Miscellaneous	Good
Exterior wall cavities	Exterior sheetrock/ paper	7-53	No	No Sheetrock/ paper: N.D.	Miscellaneous	Good
Exterior wall cavities	Yellow fiberglass insulation/ tan-black backing paper	7-54	No	No Fiberglass insulation: N.D. Backing paper: N.D.	Miscellaneous	Good
Exterior wall cavities	Yellow fiberglass insulation/ tan-black backing paper	7-55	No	No Fiberglass insulation: N.D. Backing paper: N.D.	Miscellaneous	Good
Wall penetrations	Red fire stop	7-56	No	No Fire stop: N.D.	Miscellaneous	Good
Wall penetrations	Red fire stop	7-57	No	No Fire stop: N.D.	Miscellaneous	Good
Roof insulation	White-silver backing/ yellow fiberglass	7-74	No	No Fiberglass insulation:	Miscellaneous	Good

	insulation			N.D. Backing paper: N.D.		
Roof insulation	White-silver backing/ yellow fiberglass insulation	7-75	No	No Fiberglass insulation: N.D. Backing paper: N.D.	Miscellaneous	Good
Roof insulation	Green insulation	7-76	No	No Insulation: N.D.	Miscellaneous	Good
Roof insulation	Green insulation	7-77	No	No Insulation: N.D.	Miscellaneous	Good
Roof insulation	Lt. blue foam insulation	7-78	No	No Insulation: N.D.	Miscellaneous	Good
Roof insulation	Lt. blue foam insulation	7-79	No	No Insulation: N.D.	Miscellaneous	Good

SIA Building 85- Non-Asbestos Containing Materials

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Interior walls	Knock-down texture/ sheetrock	85-1	Yes	No Texture- paint: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Interior walls	Knock-down texture/ sheetrock	85-2	Yes	No Texture- paint: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Interior walls	Knock-down texture/ sheetrock	85-3	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Interior walls	Knock-down texture/ sheetrock	85-4	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Interior walls	Knock-down texture/ sheetrock	85-5	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Bathroom floors	White sheet vinyl white mastic	85-6	No	No Sheet vinyl: N.D. Mastic:	Miscellaneous	Good

				N.D.		
Bathroom floors	White sheet vinyl white mastic	85-7	No	No Sheet vinyl: N.D. Mastic: N.D.	Miscellaneous	Good
Office floor	Black floor mat	85-8	No	No Floor mat: N.D.	Miscellaneous	Good
Office floor	Black floor mat	85-9	No	No Floor mat: N.D.	Miscellaneous	Good
HVAC duct interior	Black HVAC duct lining	85-10	No	No HVAC duct lining: N.D.	Miscellaneous	Good
HVAC duct interior	Black HVAC duct lining	85-11	No	No HVAC duct lining: N.D.	Miscellaneous	Good
Wall and ceiling cavities	Yellow fiberglass insulation	85-12	No	No Insulation: N.D.	Miscellaneous	Good
Wall and ceiling cavities	Yellow fiberglass insulation	85-13	No	No Insulation: N.D.	Miscellaneous	Good
Exterior walls	Orange brick/ white mortar	85-14	No	No Brick: N.D. Mortar: N.D.	Miscellaneous	Good
Exterior walls	Orange brick/ white mortar	85-15	No	No Brick: N.D. Mortar: N.D.	Miscellaneous	Good
Exterior walls	Orange brick/ white mortar	85-16	No	No Brick: N.D. Mortar: N.D.	Miscellaneous	Good
Exterior walls	Orange brick/ white mortar	85-17	No	No Brick: N.D. Mortar: N.D.	Miscellaneous	Good
Exterior walls	White mortar	85-18	No	No Mortar: N.D.	Miscellaneous	Good
Exterior walls	White mortar	85-19	No	No Mortar: N.D.	Miscellaneous	Good
Exterior wall seams	White caulk	85-20	No	No Caulk: N.D.	Miscellaneous	Good
Exterior wall seams	White caulk	85-21	No	No Caulk: N.D.	Miscellaneous	Good
Pump house interior	Sheetrock	85-1-1	No	No Sheetrock: N.D.	Miscellaneous	Good
Pump	Sheetrock	85-1-2	No	No	Miscellaneous	Good

house interior				Sheetrock: N.D.		
Pump house roof	White asphalt roofing shingle/tar	85-1-3	No	No Asphalt roof shingle: N.D. Tar: N.D.	Miscellaneous	Good
Pump house roof	White asphalt roofing shingle	85-1-4	No	No Asphalt roof shingle: N.D. Tar: N.D.	Miscellaneous	Good

SIA Building 360- Non-Asbestos Containing Materials

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Roof and wall cavities	Black fiberglass insulation/ black backing paper	360-2	No	No Fiberglass insulation: N.D. Backing paper: N.D.	Miscellaneous	Good
Roof and wall cavities	Black fiberglass insulation/ black backing paper	360-3	No	No Fiberglass insulation: N.D. Backing paper: N.D.	Miscellaneous	Good
HVAC ducts	Yellow fiberglass duct insulation/ black glue	360-4	No	No Fiberglass duct insulation: N.D. Glue: N.D.	Miscellaneous	Good
HVAC ducts	Yellow fiberglass duct insulation/ black glue	360-5	No	No Fiberglass duct insulation: N.D. Glue: N.D.	Miscellaneous	Good
Exterior walls under transite siding	Black tar paper strip	360-6	No	No Tar paper: N.D.	Miscellaneous	Good
Exterior walls under transite siding	Black tar paper strip	360-7	No	No Tar paper: N.D.	Miscellaneous	Good
Main building warehouse walls	Sheetrock	360-8	No	No Sheetrock: N.D.	Miscellaneous	Good
Main	Sheetrock	360-9	No	No	Miscellaneous	Good

building warehouse walls				Sheetrock: N.D.		
Main building warehouse walls	Sheetrock	360-10	No	No Sheetrock: N.D.	Miscellaneous	Good
Main building warehouse walls	Black framing base paper	360-13	No	No Framing base paper: N.D.	Miscellaneous	Good
Main building warehouse walls	Black framing base paper	360-14	No	No Framing base paper: N.D.	Miscellaneous	Good
Main building warehouse floor to wall seams	Black tar seam sealer	360-17	No	No Tar seam sealer: N.D.	Miscellaneous	Good
Main building warehouse floor to wall seams	Black tar seam sealer	360-18	No	No Tar seam sealer: N.D.	Miscellaneous	Good
Main building east office area floor	Yellow carpet mastic	360-19	No	No Carpet mastic: N.D.	Miscellaneous	Good
Main building east office area floor	Yellow carpet mastic	360-20	No	No Carpet mastic: N.D.	Miscellaneous	Good
Main building east office area	Gray cove base/ mastic	360-21	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Main building east office area	Gray cove base/ mastic	360-22	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Main building east office area ceilings	Sponge pattern texture/ sheetrock	360-23	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Main building east office area ceilings	Sponge pattern texture/ sheetrock	360-24	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Main building	Sponge pattern texture/	360-25	Yes	No Texture:	Surfacing/ Miscellaneous	Good

east office area ceilings	sheetrock			N.D. Sheetrock: N.D.		
Main building east office area walls	Knock-down pattern texture/ sheetrock	360-26	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Main building east office area walls	Knock-down pattern texture/ sheetrock	360-27	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Main building east office area walls	Knock-down pattern texture/ sheetrock	360-28	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Main building east office area floor	White leveling compound	360-29	No	No White leveling compound: N.D.	Miscellaneous	Good
Main building east office area floor	White leveling compound	360-30	No	No White leveling compound: N.D.	Miscellaneous	Good
Main building east warehouse supervisor's office walls	Sheetrock/ joint compound	360-31	No	No Sheetrock: N.D. Joint compound: N.D.	Miscellaneous	Good
Main building east warehouse supervisor's office walls	Sheetrock/ joint compound	360-32	No	No Sheetrock: N.D. Joint compound: N.D.	Miscellaneous	Good
Main building east warehouse supervisor's office floor	Tan carpet mastic/ carpet	360-33	No	No Carpet mastic: N.D. Carpet: N.D.	Miscellaneous	Good
Main building east warehouse supervisor's office floor	Tan carpet mastic	360-34	No	No Carpet mastic: N.D. Carpet: N.D.	Miscellaneous	Good
Main building east	Black flooring paper	360-37	No	No Black flooring	Miscellaneous	Good

warehouse supervisor's office floor				paper: N.D.		
Main building east warehouse supervisor's office floor	Black flooring paper	360-38	No	No Black flooring paper: N.D.	Miscellaneous	Good
Main building break room and restroom walls	Sheetrock/ joint compound	360-45	No	No Sheetrock: N.D. Joint compound: N.D.	Miscellaneous	Good
Main building break room and restroom walls	Brown cove base/ mastic	360-46	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Main building break room and restroom walls	Brown cove base/ mastic	360-47	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Main building restroom walls	White cove base/ mastic	360-50	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Main building restroom walls	White cove base/ mastic	360-51	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
West office area ceilings	White 2x4 ceiling tile	360-52	No	No Ceiling tile: N.D.	Miscellaneous	Good
West office area ceilings	White 2x4 ceiling tile	360-53	No	No Ceiling tile: N.D.	Miscellaneous	Good
West office area walls	Sheetrock/ joint compound	360-54	No	No Sheetrock: N.D. Joint compound: N.D.	Miscellaneous	Good
West office area walls	Sheetrock/ joint compound	360-55	No	No Sheetrock: N.D. Joint compound: N.D.	Miscellaneous	Good

West office area walls	Black cove base/ mastic	360-58	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
West office area walls	Black cove base/ mastic	360-59	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
West warehouse area walls	Sheetrock/ joint compound	360-60	No	No Sheetrock: N.D. Joint compound: N.D.	Miscellaneous	Good
West warehouse area ceiling	White-tan 12x12 ceiling tile	360-61	No	No Ceiling tile: N.D.	Miscellaneous	Good
West warehouse area ceiling	White-tan 12x12 ceiling tile	360-62	No	No Ceiling tile: N.D.	Miscellaneous	Good
West Warehouse area wall and roof cavities	Black insulation/ tan-black backing paper	360-63	No	No Fiberglass insulation: N.D. Backing paper: N.D.	Miscellaneous	Good
Warehouse area wall and roof cavities	Black insulation/ tan-black backing paper	360-64	No	No Fiberglass insulation: N.D. Backing paper: N.D.	Miscellaneous	Good
Boiler room chimney	Chimney block/ mortar	360-67	No	No Chimney CMU block: N.D. Mortar: N.D.	Miscellaneous	Good
Boiler room chimney	Chimney block/ mortar	360-68	No	No CMU block: N.D. Mortar: N.D.	Miscellaneous	Good
Exterior walls	CMU block/ mortar	360-69	No	No CMU block: N.D. Mortar: N.D.	Miscellaneous	Good
Exterior walls	CMU block/ mortar	360-70	No	No CMU block: N.D. Mortar: N.D.	Miscellaneous	Good

Exterior walls	CMU block/mortar	360-71	No	No CMU block: N.D. Mortar: N.D.	Miscellaneous	Good
Exterior walls	CMU block/mortar	360-72	No	No CMU block: N.D. Mortar: N.D.	Miscellaneous	Good

SIA Building 365- Non-Asbestos Containing Materials

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Exterior walls under transite siding	Black tar paper	365-11	No	No Black tar paper: N.D.	Miscellaneous	Good
Exterior walls under transite siding	Black tar paper	365-12	No	No Black tar paper: N.D.	Miscellaneous	Good
Exterior walls under transite siding	Black tar paper	365-13	No	No Black tar paper: N.D.	Miscellaneous	Good
Exterior walls under transite siding	Black tar paper	365-14	No	No Black tar paper: N.D.	Miscellaneous	Good
Exterior walls under transite siding	Black tar paper strip	365-15	No	No Black tar paper: N.D.	Miscellaneous	Good

SIA Building 1378- Non-Asbestos Containing Materials

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Interior walls	Sheetrock/joint compound	1378-1	No	No Sheetrock: N.D. Joint compound:2% Chrysotile Composite is <1% asbestos	Miscellaneous	Good
Interior top layer flooring of Room 109	Carpet/ tan mastic/ medium brown sheet vinyl/ mastic	1378-2	No	No Carpet: N.D. Carpet mastic: N.D. Sheet vinyl: N.D.	Miscellaneous	Good

				Mastic: N.D.		
Under all original wood flooring	Black flooring paper	1378-4	No	No Black flooring paper: N.D.	Miscellaneous	Good
Interior walls of building	Black cove base/ white mastic	1378-6	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Interior top layer flooring of Room 109	Brown-gray-black mosaic pattern sheet vinyl/ beige mastic	1378-7	No	No Sheet vinyl: N.D. Mastic: N.D.	Miscellaneous	Good
Interior top layer flooring of Room 109	Brown-gray-black mosaic pattern sheet vinyl/ beige mastic	1378-8	No	No Sheet vinyl: N.D. Mastic: N.D.	Miscellaneous	Good
Original wood sub-flooring	Gray paint on wood	1378-9	No	No Gray paint: N.D.	Miscellaneous	Good
Original wood sub-flooring	Gray paint on wood	1378-10	No	No Gray paint: N.D.	Miscellaneous	Good
Interior ceilings	White 2x4 ceiling tile (worm hole pattern)	1378-11	Yes	No Ceiling tile: N.D.	Miscellaneous	Good
Interior original ceilings	Sheetrock	1378-12	No	No Sheetrock: N.D.	Miscellaneous	Good
Attic area	Gray blown-in insulation	1378-13	Yes	No Gray blown-in insulation: N.D.	Miscellaneous	Good
Interior walls of Room 106	Splatter texture/ sheetrock	1378-17	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Interior walls of Room 106	Splatter texture/ sheetrock	1378-18	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Interior walls of Room 106	Splatter texture/ sheetrock	1378-19	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Interior walls of Room 106	Splatter texture/ sheetrock	1378-22	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Interior walls of	Sheetrock/ joint	1378-23	No	No Sheetrock:	Miscellaneous	Good

building	compound			N.D. Joint compound:3% Chrysotile Composite is <1% asbestos		
Interior original ceilings	White 2x4 ceiling tile (worm hole pattern)	1378-25	Yes	No Ceiling tile: N.D.	Miscellaneous	Good
Attic area	Gray blown-in insulation	1378-26	Yes	No Gray blown-in insulation: N.D.	Miscellaneous	Good
Interior walls of building	Sheetrock/ joint compound	1378-27	No	No Sheetrock: N.D. Joint compound:2% Chrysotile Composite is <1% asbestos	Miscellaneous	Good
Interior ceilings	White 2x4 ceiling tile (worm hole pattern)	1378-28	Yes	No Ceiling tile: N.D.	Miscellaneous	Good
Interior top layer flooring	Carpet/ tan mastic	1378-29	No	No Carpet: N.D. Carpet mastic: N.D.	Miscellaneous	Good
Interior walls of building	Gray cove base/ white mastic	1378-31	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Interior walls of building	Gray cove base/ white mastic	1378-32	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Interior original ceilings	Sheetrock/ joint compound	1378-33	No	No Sheetrock: N.D. Joint compound: 2% Chrysotile Composite is <1% asbestos	Miscellaneous	Good
Interior walls of building	Medium green cove base/ mastic	1378-35	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Interior walls of building	Medium green cove base/ mastic	1378-36	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Interior	White 2x4	1378-37	No	No	Miscellaneous	Good

ceilings	ceiling tile (worm hole pattern)			Ceiling tile: N.D.		
Interior original ceilings	Sheetrock	1378-38	No	No Sheetrock: N.D.	Miscellaneous	Good
Attic area	Gray blown-in insulation	1378-39	Yes	No Gray blown-in insulation: N.D.	Miscellaneous	Good
Interior original ceilings	Tan fiberboard	1378-40	No	No Tan fiberboard: N.D.	Miscellaneous	Good
Interior walls of building	Sheetrock/ joint compound	1378-41	No	No Sheetrock: N.D. Joint compound: N.D.	Miscellaneous	Good
Interior ceilings	White 2x4 ceiling tile (worm hole pattern)	1378-43	Yes	No Ceiling tile: N.D.	Miscellaneous	Good
Interior ceilings	White 12x12 ceiling tile (pencil hole pattern)	1378-44	Yes	No Ceiling tile: N.D.	Miscellaneous	Good
Interior ceilings	White 12x12 ceiling tile (pencil hole pattern)	1378-45	Yes	No Ceiling tile: N.D.	Miscellaneous	Good
Interior ceilings	Brown ceiling tile mastic	1378-46	No	No Brown ceiling tile mastic: N.D. Ceiling tile: N.D.	Miscellaneous	Good
Interior ceilings	Brown ceiling tile mastic	1378-47	No	No Brown ceiling tile mastic: N.D. Ceiling tile: N.D.	Miscellaneous	Good
Interior original ceilings	Sheetrock	1378-48	No	No Sheetrock: N.D.	Miscellaneous	Good
Interior walls of building	Gray cove base/ white mastic	1378-49	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Interior walls of building	Sheetrock/ joint compound	1378-50	No	No Sheetrock: N.D.	Miscellaneous	Good

				Joint compound: N.D.		
Interior walls of building	Sheetrock/joint compound	1378-51	No	No Sheetrock: N.D. Joint compound: N.D.	Miscellaneous	Good
Kitchen area floor	Yellow epoxy flooring	1378-56	No	No Yellow epoxy flooring: N.D.	Miscellaneous	Good
	Yellow epoxy flooring	1378-57	No	No Yellow epoxy flooring: N.D.	Miscellaneous	Good
Kitchen area floor	Gray HVAC duct tape	1378-60	No	No Gray HVAC duct tape: N.D.	Miscellaneous	Good
HVAC duct seams	Gray HVAC duct tape	1378-61	No	No Gray HVAC duct tape: N.D.	Miscellaneous	Good
Kitchen area walls	Light yellow FRP panel	1378-62	No	No FRP panel: N.D.	Miscellaneous	Good
Kitchen area walls	Light yellow FRP panel	1378-63	No	No FRP panel: N.D.	Miscellaneous	Good
Cooler door interior	Yellow foam insulation	1378-64	No	No Yellow foam insulation: N.D.	Miscellaneous	Good
Cooler door interior	Yellow foam insulation	1378-65	No	No Yellow foam insulation: N.D.	Miscellaneous	Good
Cooler door frame	Gray door seam sealer	1378-66	No	No Gray door seam sealer: N.D.	Miscellaneous	Good
Cooler door frame	Gray door seam sealer	1378-67	No	No Gray door seam sealer: N.D.	Miscellaneous	Good
Break room walls	White-yellow fiberglass ceiling tile/ brown mastic	1378-68	No	No Ceiling tile: N.D. Brown ceiling tile mastic: N.D.	Miscellaneous	Good
Break room walls	White-yellow fiberglass ceiling tile/ brown mastic	1378-69	No	No Ceiling tile: N.D. Brown ceiling	Miscellaneous	Good

				tile mastic: N.D.		
Exterior office area roofs	Brown roof shingle/black roof shingle/ green roof shingle/ built-up roofing	1378-70	No	No Brown roof shingle: N.D. Black roof shingle: N.D. Green roof shingle: N.D. Built-up roofing: N.D.	Miscellaneous	Good
Exterior office area roofs	Brown roof shingle/black roof shingle/ green roof shingle/ built-up roofing	1378-71	No	No Brown roof shingle: N.D. Black roof shingle: N.D. Green roof shingle: N.D. Built-up roofing: N.D.	Miscellaneous	Good
Exterior office area roofs	Tar on wood	1378-72	No	No Tar on wood: N.D.	Miscellaneous	Good
Exterior kitchen area roofs	Black rubber roof membrane	1378-74	No	No Black rubber roof membrane: N.D.	Miscellaneous	Good
Exterior siding	Gray skirting panel	1378-75	No	No Gray skirting panel: N.D.	Miscellaneous	Good
Exterior siding	Gray skirting panel	1378-76	No	No Gray skirting panel: N.D.	Miscellaneous	Good
Under wood siding	Black tar paper	1378-77	No	No Black tar paper: N.D.	Miscellaneous	Good
Under wood siding	Black tar paper	1378-78	No	No Black tar paper: N.D.	Miscellaneous	Good
Under wood siding	Gray siding paper	1378-79	No	No Gray siding paper: N.D.	Miscellaneous	Good
Under wood siding	Gray siding paper	1378-80	No	No Gray siding paper: N.D.	Miscellaneous	Good
Under wood siding	Sheetrock	1378-81	No	No Sheetrock: N.D.	Miscellaneous	Good
Under wood siding	Sheetrock	1378-82	No	No Sheetrock: N.D.	Miscellaneous	Good
Exterior wall cavities	Black insulation	1378-83	No	No Black insulation:	Miscellaneous	Good

				N.D.		
Exterior wall cavities	Black insulation	1378-84	No	No Black insulation: N.D.	Miscellaneous	Good
Exterior building seams	White caulk	1378-85	No	No White caulk: N.D.	Miscellaneous	Good
Exterior building seams	White caulk	1378-86	No	No White caulk: N.D.	Miscellaneous	Good
Walk-in cooler exterior foundation	Cement skin coat	1378-88	No	No Cement skim coat: N.D.	Miscellaneous	Good
Walk-in cooler exterior foundation	Cement skin coat	1378-89	No	No Cement skim coat: N.D.	Miscellaneous	Good
Walk-in cooler exterior foundation	Cement skin coat	1378-90	No	No Cement skim coat: N.D.	Miscellaneous	Good

SIA Building 1424- Non-Asbestos Containing Materials

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Exterior roof	Brown asphalt roofing shingle/tar	1424-1	No	No Brown roof shingle: N.D. Tar: N.D.	Miscellaneous	Good
Exterior roof	Brown asphalt roofing shingle/tar	1424-2	No	No Brown roof shingle: N.D. Tar: N.D.	Miscellaneous	Good
Exterior roof	Black asphalt roofing shingle/tar	1424-3	No	No Black roof shingle: N.D. Tar: N.D.	Miscellaneous	Good
Exterior roof	Black asphalt roofing shingle/tar	1424-4	No	No Black roof shingle: N.D. Tar: N.D.	Miscellaneous	Good
Exterior roof	Black tar paper	1424-5	No	No Black tar paper: N.D.	Miscellaneous	Good
Exterior roof	Black tar paper	1424-6	No	No Black tar	Miscellaneous	Good

				paper: N.D.		
Exterior roof	Black tar paper	1424-7	No	No Black tar paper: N.D.	Miscellaneous	Good
Exterior roof	Black tar paper	1424-8	No	No Black tar paper: N.D.	Miscellaneous	Good
Exterior siding	Tan/ black siding paper	1424-9	No	No Tan/ black siding paper: N.D.	Miscellaneous	Good
Exterior siding	Tan/ black siding paper	1424-10	No	No Tan/ black siding paper: N.D.	Miscellaneous	Good
Exterior siding	Tan/ black siding paper	1424-11	No	No Tan/ black siding paper: N.D.	Miscellaneous	Good
Exterior building seams	White seam sealer	1424-12	No	No White seam sealer: N.D.	Miscellaneous	Good
Exterior building seams	White seam sealer	1424-13	No	No White seam sealer: N.D.	Miscellaneous	Good
Exterior loading dock seams	White dock seam sealer	1424-14	No	No White dock seam sealer: N.D.	Miscellaneous	Good
Exterior loading dock seams	White dock seam sealer	1424-15	No	No White dock seam sealer: N.D.	Miscellaneous	Good
Interior ceilings	Green/tan particle paper ceiling panel	7306-1	No	No Green/tan particle paper ceiling panel: N.D.	Miscellaneous	Good
Interior ceilings	Green/tan particle paper ceiling panel	7306-2	No	No Green/tan particle paper ceiling panel: N.D.	Miscellaneous	Good
Interior ceilings	Green/tan particle paper ceiling panel	7306-3	No	No Green/tan particle paper ceiling panel: N.D.	Miscellaneous	Good
Interior walls of building	Sheetrock	7306-4	No	No Sheetrock: N.D.	Miscellaneous	Good

Interior walls of building	Sheetrock	7306-5	No	No Sheetrock: N.D.	Miscellaneous	Good
Interior walls of building	Sheetrock	7306-6	No	No Sheetrock: N.D.	Miscellaneous	Good

SIA Building 1425- Non-Asbestos Containing Materials

Material Location	Material Description	Sample Number	Friable Yes/No	Asbestos	Type	Condition
Office area walls	Splatter texture/ sheetrock	1425-1	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Office area walls	Splatter texture/ sheetrock	1425-2	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Office area walls	Splatter texture/ sheetrock	1425-3	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Office area walls	Splatter texture/ sheetrock	1425-4	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Office area walls	Splatter texture/ sheetrock	1425-5	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Office area floors	Blue carpet/ tan mastic	1425-6	No	No Carpet: N.D. Carpet mastic: N.D.	Miscellaneous	Good
Office area floors	Blue carpet/ tan mastic	1425-7	No	No Carpet: N.D. Carpet mastic: N.D.	Miscellaneous	Good
Office area floors	Blue carpet/ tan mastic	1425-8	No	No Carpet: N.D. Carpet mastic: N.D.	Miscellaneous	Good

Restrooms and hallway floors	Gray sheet vinyl/ mastic	1425-9	No	No Sheet vinyl: N.D. Carpet mastic: N.D.	Miscellaneous	Good
Restrooms and hallway floors	Gray sheet vinyl/ mastic	1425-10	No	No Sheet vinyl: N.D. Carpet mastic: N.D.	Miscellaneous	Good
Restrooms and hallway floors	Gray sheet vinyl/ mastic	1425-11	No	No Sheet vinyl: N.D. Carpet mastic: N.D.	Miscellaneous	Good
Office area walls	Gray cove base/ mastic	1425-12	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Office area walls Interior ceilings	Gray cove base/ mastic	1425-13	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Interior ceilings	White 2x4 ceiling tile	1425-14	Yes	No Ceiling tile: N.D.	Miscellaneous	Good
Interior ceilings	White 2x4 ceiling tile	1425-15	Yes	No Ceiling tile: N.D.	Miscellaneous	Good
Office area walls	Dark gray cove base/ mastic	1425-16	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Office area walls	Dark gray cove base/ mastic	1425-17	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Restroom walls	Tan wall panel mastic	1425-18	No	No Tan wall panel mastic: N.D.	Miscellaneous	Good
Restroom walls	Tan wall panel mastic	1425-19	No	No Tan wall panel mastic: N.D.	Miscellaneous	Good
Restrooms	Gray formica/	1425-20	No	No	Miscellaneous	Good

and hallway counter tops	glue			Formica N.D. Glue: N.D.		
Restrooms and hallway counter tops	Gray formica/ glue	1425-21	No	No Formica N.D. Glue: N.D.	Miscellaneous	Good
Office area walls	Sheetrock/ joint compound	1425-22	No	No Sheetrock: N.D. Joint compound: N.D.	Miscellaneous	Good
Office area walls	Sheetrock/ joint compound	1425-23	No	No Sheetrock: N.D. Joint compound: N.D.	Miscellaneous	Good
Exterior wall cavities	Tan-black backing paper/ yellow insulation	1425-24	No	No Tan-black backing paper: N.D. Yellow insulation: N.D.	Miscellaneous	Good
Exterior wall cavities	Tan-black backing paper/ yellow insulation	1425-25	No	No Tan-black backing paper: N.D. Yellow insulation: N.D.	Miscellaneous	Good
Roof insulation	Silver-tan backing paper/ yellow insulation	1425-26	No	No Silver-tan backing paper: N.D. Yellow insulation: N.D.	Miscellaneous	Good
Roof insulation	Silver-tan backing paper/ yellow insulation	1425-27	No	No Silver-tan backing paper: N.D. Yellow insulation: N.D.	Miscellaneous	Good
Exterior wall cavities	Gray blown-in insulation	1425-28	Yes	No Gray blown-in insulation: N.D.	Miscellaneous	Good
Exterior wall cavities	Gray blown-in insulation	1425-29	Yes	No Gray blown-in	Miscellaneous	Good

				insulation: N.D.		
Exterior roof	Brown asphalt roofing shingle/ tar	1425-30	No	No Brown roof shingle: N.D. Tar: N.D.	Miscellaneous	Good
Exterior roof	Brown asphalt roofing shingle/ tar	1425-32	No	No Brown roof shingle: N.D. Tar: N.D.	Miscellaneous	Good
Exterior roof	Black tar paper	1425-32	No	No Black tar paper: N.D.	Miscellaneous	Good
Exterior roof	Black tar paper	1425-33	No	No Black tar paper: N.D.	Miscellaneous	Good
Under wood siding	Tan/ black siding paper	1425-34	No	No Tan/ black siding paper: N.D.	Miscellaneous	Good
Under wood siding	Tan/ black siding paper	1425-35	No	No Tan/ black siding paper: N.D.	Miscellaneous	Good
Under wood siding	Tan/ black siding paper	1425-36	No	No Tan/ black siding paper: N.D.	Miscellaneous	Good
Exterior building seams	White seam sealer	1425-37	No	No White seam sealer: N.D.	Miscellaneous	Good
Exterior building seams	White seam sealer	1425-38	No	No White seam sealer: N.D.	Miscellaneous	Good
Exterior loading dock seams	White dock seam sealer	1425-39	No	No White seam sealer: N.D.	Miscellaneous	Good
Exterior loading dock seams	White dock seam sealer	1425-40	No	No White seam sealer: N.D.	Miscellaneous	Good
Main entrance ramp floor	Black non-skid/ glue	1425-41	No	No Black non- skid: N.D. Glue: N.D.	Miscellaneous	Good
Main entrance ramp floor	Black non-skid/ glue	1425-42	No	No Black non- skid: N.D. Glue: N.D.	Miscellaneous	Good

SIA Building 2501- Non-Asbestos Containing Materials

Material	Material	Sample	Friable	Asbestos	Type	Condition
----------	----------	--------	---------	----------	------	-----------

Location	Description	Number	Yes/No			
Interior walls	Brown cove base/ brown – black mastic	2501-3	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Interior walls	Brown cove base/ brown – black mastic	2501-4	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Interior walls	Brown cove base/ brown mastic	2501-5	No	No Cove base: N.D. Mastic: <1% Tremolite	Miscellaneous	Good
Interior walls	Brown cove base/ black mastic	2501-6	No	No Cove base: N.D. Mastic: <1% Tremolite	Miscellaneous	Good
Interior walls	Sheetrock/ joint compound	2501-11	No	No Sheetrock: N.D. Joint compound: 3% Chrysotile Composite is <1% asbestos	Miscellaneous	Good
Interior walls	Sheetrock/ joint compound	2501-12	No	No Sheetrock: N.D. Joint compound: 3% Chrysotile Composite is <1% asbestos	Miscellaneous	Good
Interior walls	Sheetrock/ joint compound	2501-13	No	No Sheetrock: N.D. Joint compound: 3% Chrysotile Composite is <1% asbestos	Miscellaneous	Good
Interior walls	Sheetrock/ joint compound	2501-14	No	No Sheetrock: N.D. Joint compound: 3% Chrysotile Composite is <1% asbestos	Miscellaneous	Good
Interior walls	Sheetrock/ joint compound	2501-15	No	No Sheetrock: N.D. Joint	Miscellaneous	Good

				compound: 3% Chrysotile Composite is <1% asbestos		
Room 112 walls	Tan wall mastic/ sheetrock	2501-16	No	No Tan wall mastic: N.D. Sheetrock: N.D.	Miscellaneous	Good
Interior walls	Tan wall mastic/ sheetrock	2501-17	No	No Tan wall mastic: N.D. Sheetrock: N.D.	Miscellaneous	Good
Interior walls	Black cove base/ mastic	2501-18	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Interior walls	Black cove base/ mastic	2501-19	No	No Cove base: N.D. Mastic: N.D.	Miscellaneous	Good
Room 112 demising wall	Texture/ sheetrock	2501-20	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Room 112 demising wall	Texture/ sheetrock	2501-21	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Room 112 demising wall	Texture/ sheetrock	2501-22	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
Southwest training area walls and ceiling	White-tan 12x12 ceiling tile	2501-23	No	No Ceiling tile: N.D.	Miscellaneous	Good
Southwest training area walls and ceiling	White-tan 12x12 ceiling tile	2501-24	No	No Ceiling tile: N.D.	Miscellaneous	Good
Southwest training area walls and ceiling	White-tan 12x12 ceiling tile	2501-25	No	No Ceiling tile: N.D.	Miscellaneous	Good
Southwest training area walls and ceiling	Dark brown wall tile mastic/ sheetrock	2501-26	No	No Dark brown wall tile mastic: N.D. Sheetrock: N.D.	Miscellaneous	Good
Southwest training area walls	Dark brown wall tile mastic/	2501-27	No	No Dark brown wall tile	Miscellaneous	Good


and ceiling	sheetrock			mastic: N.D. Sheetrock: N.D.		
Southwest training area walls and ceiling	Dark brown wall tile mastic/ sheetrock	2501-28	No	No Dark brown wall tile mastic: N.D. Sheetrock: N.D.	Miscellaneous	Good
Under wall panels	Tan wall mastic	2501-29	No	No Tan wall mastic: N.D.	Miscellaneous	Good
Under wall panels	Tan wall mastic	2501-30	No	No Tan wall mastic: N.D.	Miscellaneous	Good
Vault room walls	White 12x12 ceiling tile / dark brown mastic	2501-33	No	No Ceiling tile: N.D. Brown ceiling tile mastic: N.D.	Miscellaneous	Good
Vault room walls	White 12x12 ceiling tile / dark brown mastic	2501-34	No	No Ceiling tile: N.D. Brown ceiling tile mastic: N.D.	Miscellaneous	Good
Vault room walls	White 12x12 ceiling tile / dark brown mastic	2501-35	No	No Ceiling tile: N.D. Brown ceiling tile mastic: N.D.	Miscellaneous	Good
Boiler room walls	Sheetrock	2501-36	No	No Sheetrock: N.D.	Miscellaneous	Good
Boiler room walls	Sheetrock	2501-37	No	No Sheetrock: N.D.	Miscellaneous	Good
Boiler room walls	Sheetrock	2501-38	No	No Sheetrock: N.D.	Miscellaneous	Good
Boiler room walls	Brick	2501-39	No	No Sheetrock: N.D.	Miscellaneous	Good
Boiler room walls	Brick	2501-40	No	No Brick: N.D.	Miscellaneous	Good
Boiler room walls	Mortar	2501-41	No	No Mortar: N.D.	Miscellaneous	Good
Boiler room walls	Mortar	2501-42	No	No Mortar: N.D.	Miscellaneous	Good
HVAC ducts	Black HVAC duct tar	2501-43	No	No Black HVAC duct tar: N.D.	Miscellaneous	Good

HVAC ducts	Black HVAC duct tar	2501-44	No	No Black HVAC duct tar: N.D.	Miscellaneous	Good
HVAC ducts	Black HVAC duct tar	2501-45	No	No Black HVAC duct tar: N.D.	Miscellaneous	Good
Original HVAC ducts	Brown cork/ black HVAC duct tar	2501-46	No	No Brown cork: N.D. Black HVAC duct tar: N.D.	Miscellaneous	Good
Original HVAC ducts	Brown cork/ black HVAC duct tar	2501-47	No	No Brown cork: N.D. Black HVAC duct tar: N.D.	Miscellaneous	Good
Domestic water piping	White wrap/ yellow fiberglass pipe insulation	2501-48	No	No Pipe wrap: N.D. Pipe insulation: N.D.	Thermal System Insulation	Good
Domestic water piping	White wrap/ yellow fiberglass pipe insulation	2501-49	No	No Pipe wrap: N.D. Pipe insulation: N.D.	Thermal System Insulation	Good
Domestic water piping	White wrap/ yellow fiberglass pipe insulation	2501-50	No	No Pipe wrap: N.D. Pipe insulation: N.D.	Thermal System Insulation	Good
HVAC ducts	Gray HVAC duct seam caulk	2501-55	No	No Gray HVAC duct seam caulk: N.D.	Miscellaneous	Good
HVAC ducts	Gray HVAC duct seam caulk	2501-56	No	No Gray HVAC duct seam caulk: N.D.	Miscellaneous	Good
East entrance hallway walls	Texture/ sheetrock	2501-57	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
East entrance hallway walls	Texture/ sheetrock	2501-58	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good
East entrance hallway walls	Texture/ sheetrock	2501-59	Yes	No Texture: N.D. Sheetrock: N.D.	Surfacing/ Miscellaneous	Good

Exterior	Concrete	2501-60	No	No Concrete: N.D.	Miscellaneous	Good
Exterior	Concrete	2501-61	No	No Concrete: N.D.	Miscellaneous	Good
Exterior walls under transite siding	Black tar paper	2501-67	No	No Tar paper: N.D.	Miscellaneous	Good
Exterior walls under transite siding	Black tar paper	2501-68	No	No Tar paper: N.D.	Miscellaneous	Good
Exterior walls under transite siding	Black tar paper	2501-69	No	No Tar paper: N.D.	Miscellaneous	Good
Exterior walls under transite siding	Black tar paper	2501-70	No	No Tar paper: N.D.	Miscellaneous	Good
South entrance stoop roof	Maroon asphalt roof shingle	2501-71	No	No Maroon asphalt roof shingle: N.D.	Miscellaneous	Good
South entrance stoop roof	Maroon asphalt roof shingle	2501-72	No	No Maroon asphalt roof shingle: N.D.	Miscellaneous	Good

End of section.

**Appendix A
Inspector's Certification**





Appendix B
Asbestos Analytical Results

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158047

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/17/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/22/2015
Collected: 07/10/2015 Date Reported: 07/22/2015
Project Name: SIA BLDG #7, 2945 S. FLINT RD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158047-001 7-1		LAYER 1 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber Fibrous Glass Gypsum Carbonates Mica Quartz	10% 2% 88%
		LAYER 2 Joint Compound, Off White	No	None Detected	Cellulose Fiber Carbonates Mica Quartz Binder/Filler	2% 98%
0158047-002 7-2		LAYER 1 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber Fibrous Glass Gypsum Carbonates Mica Quartz	10% 2% 88%
		LAYER 2 Joint Compound, Off White	No	None Detected	Cellulose Fiber Carbonates Mica Quartz Binder/Filler	1% 99%
0158047-003 7-3		Lagging, White Note: No Wrap & Foam Present	No	None Detected	Mineral Wool Cellulose Fiber Gypsum Diatoms Mica Quartz Binder/Filler	25% 5% 70%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158047

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/17/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/22/2015
Collected: 07/10/2015 Date Reported: 07/22/2015
Project Name: SIA BLDG #7, 2945 S. FLINT RD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158047-004 7-4		LAYER 1 Wrap, White	No	None Detected	Fibrous Glass Carbonates Binder/Filler	98% 2%
		LAYER 2 Packing, White	No	None Detected	Carbonates Quartz Binder/Filler	100%
		LAYER 3 Foam, Yellow	No	None Detected	Foam Gypsum	100%
0158047-005 7-5		LAYER 1 Wrap, White	No	None Detected	Fibrous Glass Cellulose Fiber Carbonates	95% 3% 2%
		LAYER 2 Packing, White	No	None Detected	Mineral Wool Cellulose Fiber Gypsum Diatoms Mica Quartz	25% 5% 70%
		LAYER 3 Foam, Yellow	No	None Detected	Foam Binder/Filler	100%
0158047-006 7-6		LAYER 1 Packing, White Note: No Wrap Present	No	None Detected	Mineral Wool Cellulose Fiber Gypsum Diatoms Mica Quartz	25% 5% 70%
		LAYER 2 Foam, White	No	None Detected	Foam Gypsum Binder/Filler	100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158047

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/17/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/22/2015
Collected: 07/10/2015 Date Reported: 07/22/2015
Project Name: SIA BLDG #7, 2945 S. FLINT RD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158047-007 7-7		LAYER 1 Wrap, White/ Silver	No	None Detected	Cellulose Fiber 50% Fibrous Glass 10% Aluminum Quartz Binder/Filler 40%
		LAYER 2 Fiberglass Pipe Insulation, Yellow	No	None Detected	Fibrous Glass 97% Cellulose Fiber 1% Gypsum Binder/Filler 2%
0158047-008 7-8		LAYER 1 Wrap, White/ Silver	No	None Detected	Cellulose Fiber 50% Fibrous Glass 10% Aluminum Quartz Binder/Filler 40%
		LAYER 2 Fiberglass Pipe Insulation, Yellow	No	None Detected	Fibrous Glass 95% Cellulose Fiber 3% Gypsum Binder/Filler 2%
0158047-009 7-9		LAYER 1 Wrap, White/ Silver	No	None Detected	Cellulose Fiber 50% Fibrous Glass 10% Aluminum Quartz Binder/Filler 40%
		LAYER 2 Fiberglass Pipe Insulation, Yellow	No	None Detected	Fibrous Glass 97% Cellulose Fiber 1% Gypsum Binder/Filler 2%
0158047-010 7-10		2x4 Ceiling Tile, White/ Gray	No	None Detected	Cellulose Fiber 40% Mineral Wool 40% Carbonates Perlite Binder/Filler 20%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158047

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/17/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/22/2015
Collected: 07/10/2015 Date Reported: 07/22/2015
Project Name: SIA BLDG #7, 2945 S. FLINT RD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158047-011 7-11		2x4 Ceiling Tile, White/ Gray	No	None Detected	Cellulose Fiber Mineral Wool Carbonates Perlite Binder/Filler	40% 40% 20%
0158047-012 7-12		LAYER 1 5" Covebase, Medium Brown	No	None Detected	Carbonates Quartz Binder/Filler	100%
		LAYER 2 Mastic, Off White	No	None Detected	Cellulose Fiber Quartz Carbonates Binder/Filler	<1% 99%
0158047-013 7-13		LAYER 1 5" Covebase, Medium Brown	No	None Detected	Carbonates Quartz Binder/Filler	100%
		LAYER 2 Mastic, Off White	No	None Detected	Cellulose Fiber Carbonates Quartz Binder/Filler	3% 97%
0158047-014 7-14		LAYER 1 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber Fibrous Glass Gypsum Carbonates Mica Quartz	10% 2% 88%
		LAYER 2 Joint Compound, Off White	No	None Detected	Cellulose Fiber Carbonates Mica Quartz Binder/Filler	2% 98%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158047

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/17/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/22/2015
Collected: 07/10/2015 Date Reported: 07/22/2015
Project Name: SIA BLDG #7, 2945 S. FLINT RD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158047-015 7-15		LAYER 1 Covebase, Tan	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Off White	No	None Detected	Cellulose Fiber 3% Quartz Carbonates Binder/Filler 97%
0158047-016 7-16		LAYER 1 Covebase, Tan	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Off White	No	None Detected	Cellulose Fiber 1% Quartz Gypsum Binder/Filler 99%
0158047-017 7-17		Floor Mastic, Dk Tan	No	None Detected	Cellulose Fiber 5% Carbonates Binder/Filler 95%
0158047-018 7-18		Floor Mastic, Dk Tan	No	None Detected	Cellulose Fiber 3% Carbonates Binder/Filler 97%
0158047-019 7-19		LAYER 1 2x2 Ceramic Tile, Blue	No	None Detected	Quartz Gypsum Carbonates Binder/Filler 100%
		LAYER 2 Cement, Dk. Gray	No	None Detected	Cellulose Fiber <1% Quartz Gypsum Carbonates Binder/Filler 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158047

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/17/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/22/2015
Collected: 07/10/2015 Date Reported: 07/22/2015
Project Name: SIA BLDG #7, 2945 S. FLINT RD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158047-020 7-20		LAYER 1 2x2 Ceramic Tile, Blue	No	None Detected	Quartz Gypsum Carbonates Binder/Filler 100%
		LAYER 2 Cement, Dk. Gray	No	None Detected	Cellulose Fiber <1% Quartz Gypsum Carbonates Binder/Filler 99%
0158047-021 7-21		Grout, Dk. Gray	No	None Detected	Quartz Gypsum Carbonates Binder/Filler 100%
0158047-022 7-22		Grout, Dk. Gray	No	None Detected	Quartz Gypsum Carbonates Binder/Filler 100%
0158047-023 7-23		Framing Caulk, Gray	No	None Detected	Talc 2% Cellulose Fiber 1% Carbonates Gypsum Quartz Binder/Filler 97%
0158047-024 7-24		Framing Caulk, Gray	No	None Detected	Talc 3% Carbonates Gypsum Quartz Binder/Filler 97%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158047

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/17/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/22/2015
Collected: 07/10/2015 Date Reported: 07/22/2015
Project Name: SIA BLDG #7, 2945 S. FLINT RD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158047-025 7-25		HVAC Duct Tape, Beige	No	None Detected	Cellulose Fiber Gypsum Carbonates Binder/Filler	60% 40%
0158047-026 7-26		HVAC Duct Tape, Beige	No	None Detected	Cellulose Fiber Gypsum Carbonates Binder/Filler	60% 40%
0158047-027 7-27		Epoxy Flooring, Brown	No	None Detected	Quartz Binder/Filler	100%
0158047-028 7-28		Epoxy Flooring, Brown	No	None Detected	Cellulose Fiber Gypsum Binder/Filler	2% 98%
0158047-029 7-29		HVAC Duct Caulk, White	No	None Detected	Cellulose Fiber Gypsum Quartz Binder/Filler	1% 99%
0158047-030 7-30		HVAC Duct Caulk, White	No	None Detected	Silicone Binder/Filler	100%
0158047-031 7-31		LAYER 1 Wall Mastic, Tan	No	None Detected	Cellulose Fiber Carbonates Binder/Filler	<1% 99%
		LAYER 2 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber Fibrous Glass Gypsum Carbonates Mica Quartz	10% 2% 88%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158047

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/17/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/22/2015
Collected: 07/10/2015 Date Reported: 07/22/2015
Project Name: SIA BLDG #7, 2945 S. FLINT RD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158047-032 7-32		Wall Mastic, Tan	No	None Detected	Cellulose Fiber Carbonates Binder/Filler	<1% 99%
0158047-033 7-33		Wall Mastic, Tan	No	None Detected	Cellulose Fiber Carbonates Binder/Filler	1% 99%
0158047-034 7-34		Wall Glue, Tan	No	None Detected	Cellulose Fiber Quartz Binder/Filler	1% 99%
0158047-035 7-35		Wall Glue, Tan	No	None Detected	Cellulose Fiber Quartz Binder/Filler	2% 98%
0158047-036 7-36		Cooler Foam Insulation, Yellow	No	None Detected	Foam Gypsum Binder/Filler	100%
0158047-037 7-37		Cooler Foam Insulation, Yellow	No	None Detected	Cellulose Fiber Foam Gypsum Binder/Filler	1% 99%
0158047-038 7-38		CMU Block, Gray	No	None Detected	Cellulose Fiber Quartz Gypsum Carbonates Perlite Binder/Filler	<1% 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158047

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/17/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/22/2015
Collected: 07/10/2015 Date Reported: 07/22/2015
Project Name: SIA BLDG #7, 2945 S. FLINT RD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158047-039 7-39		CMU Block, Gray	No	None Detected	Cellulose Fiber Quartz Gypsum Carbonates Perlite Binder/Filler	<1% 99%
0158047-040 7-40		Mortar, White	No	None Detected	Carbonates Gypsum Quartz Mica Binder/Filler	 100%
0158047-041 7-41		Mortar, White	No	None Detected	Carbonates Gypsum Quartz Mica Binder/Filler	 100%
0158047-042 7-42		Exterior Wall Panel, Lt. Brown	No	None Detected	Quartz Mica Gypsum Binder/Filler	 100%
0158047-043 7-43		Exterior Wall Panel, Lt. Brown	No	None Detected	Quartz Mica Gypsum Binder/Filler	 100%
0158047-044 7-44		Exterior Wall Panel, Lt. Brown	No	None Detected	Quartz Mica Gypsum Binder/Filler	 100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158047

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/17/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/22/2015
Collected: 07/10/2015 Date Reported: 07/22/2015
Project Name: SIA BLDG #7, 2945 S. FLINT RD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158047-045 7-45		Exterior Wall Panel, Lt. Brown	No	None Detected	Quartz Mica Gypsum Binder/Filler	100%
0158047-046 7-46		Styrofoam Insulation, White	No	None Detected	Foam Binder/Filler	100%
0158047-047 7-47		Styrofoam Insulation, White	No	None Detected	Foam Binder/Filler	100%
0158047-048 7-48		Cement Stucco, Lt. Brown/ Gray	No	None Detected	Synthetic Fiber Carbonates Quartz Gypsum Mica Binder/Filler	<1% 99%
0158047-049 7-49		Cement Stucco, Lt. Brown/ Gray	No	None Detected	Synthetic Fiber Carbonates Quartz Gypsum Mica Binder/Filler	<1% 99%
0158047-050 7-50		Cement Stucco, Lt. Brown/ Gray	No	None Detected	Synthetic Fiber Carbonates Quartz Gypsum Mica Binder/Filler	<1% 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158047

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/17/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/22/2015
Collected: 07/10/2015 Date Reported: 07/22/2015
Project Name: SIA BLDG #7, 2945 S. FLINT RD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158047-051 7-51		Cement Stucco, Lt. Brown/ Gray	No	None Detected	Synthetic Fiber Carbonates Quartz Gypsum Mica Binder/Filler	<1% 99%
0158047-052 7-52		LAYER 1 Exterior Sheetrock, White	No	None Detected	Cellulose Fiber Gypsum Carbonates Mica	3% 97%
		LAYER 2 Paper, Brown	No	None Detected	Cellulose Fiber Carbonates Binder/Filler	95% 5%
0158047-053 7-53		LAYER 1 Exterior Sheetrock, White	No	None Detected	Cellulose Fiber Gypsum Carbonates Mica	3% 97%
		LAYER 2 Paper, Brown	No	None Detected	Cellulose Fiber Carbonates Binder/Filler	95% 5%
0158047-054 7-54		LAYER 1 Fiberglass Insulation, Yellow	No	None Detected	Fibrous Glass Carbonates	97% 3%
		LAYER 2 Backing Paper, Tan/ Black	No	None Detected	Cellulose Fiber Gypsum Carbonates Binder/Filler	60% 40%
0158047-055 7-55		LAYER 1 Fiberglass Insulation, Yellow	No	None Detected	Fibrous Glass Carbonates	98% 2%
		LAYER 2 Backing Paper, Tan/ Black	No	None Detected	Cellulose Fiber Gypsum Carbonates Binder/Filler	60% 40%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158047

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/17/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/22/2015
Collected: 07/10/2015 Date Reported: 07/22/2015
Project Name: SIA BLDG #7, 2945 S. FLINT RD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158047-056 7-56		Fire Stop, Red	No	None Detected	Carbonates Quartz Binder/Filler	100%
0158047-057 7-57		Fire Stop, Red	No	None Detected	Carbonates Binder/Filler	100%
0158047-058 7-58		Roof Seam Sealer, Lt. Gray	No	None Detected	Cellulose Fiber Wollastonite Carbonates Quartz Binder/Filler	2% 1% 97%
0158047-059 7-59		Roof Seam Sealer, Lt. Gray	No	None Detected	Cellulose Fiber Wollastonite Carbonates Quartz Binder/Filler	2% 1% 97%
0158047-060 7-60		Roof Seam Sealer, Lt. Gray	No	None Detected	Cellulose Fiber Wollastonite Carbonates Quartz Binder/Filler	2% 1% 97%
0158047-061 7-61		Roof Seam Sealer, Lt. Gray	No	None Detected	Cellulose Fiber Wollastonite Carbonates Quartz Binder/Filler	2% 1% 97%
0158047-062 7-62		Roof Seam Sealer, Medium Gray	Yes	Chrysotile 2%	Gypsum Binder/Filler	98%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158047

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/17/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/22/2015
Collected: 07/10/2015 Date Reported: 07/22/2015
Project Name: SIA BLDG #7, 2945 S. FLINT RD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158047-063 7-63		Roof Seam Sealer, Medium Gray	Yes	Chrysotile 3%	Gypsum Binder/Filler	97%
0158047-064 7-64		Roof Seam Sealer, Lt. Gray	No	None Detected	Carbonates Quartz Binder/Filler	100%
0158047-065 7-65		LAYER 1 Roof Seam Sealer, Black	Yes	Chrysotile 8%	Carbonates Binder/Filler	92%
		LAYER 2 Roof Seam Sealer, White/ Off White	Yes	Chrysotile 2%	Carbonates Binder/Filler	98%
0158047-066 7-66		LAYER 1 Roof Seam Sealer, Black	Yes	Chrysotile 8%	Carbonates Binder/Filler	92%
		LAYER 2 Roof Seam Sealer, White/ Off White	Yes	Chrysotile 2%	Carbonates Binder/Filler	98%
0158047-067 7-67		LAYER 1 HVAC Sealer, Silver	Yes	Chrysotile 3%	Synthetic Fiber 3% Wollastonite 2% Gypsum Quartz Binder/Filler	92%
		LAYER 2 HVAC Sealer, White/ Silver	No	None Detected	Silicone Carbonates Binder/Filler	100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158047

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/17/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/22/2015
Collected: 07/10/2015 Date Reported: 07/22/2015
Project Name: SIA BLDG #7, 2945 S. FLINT RD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158047-068 7-68		LAYER 1 HVAC Sealer, Silver	Yes	Chrysotile 4%	Synthetic Fiber	1%
		LAYER 2 HVAC Sealer, White/ Silver	No	None Detected	Gypsum Quartz Binder/Filler	95%
		LAYER 3 HVAC Sealer, Gray	Yes	Chrysotile 2%	Gypsum Carbonates Binder/Filler	100%
0158047-069 7-69		LAYER 1 HVAC Sealer, Silver	Yes	Chrysotile 2%	Carbonates Quartz Binder/Filler	98%
		LAYER 2 HVAC Sealer, White/ Silver	No	None Detected	Wollastonite	3%
0158047-070 7-70		Roof Seam Sealer, Black	Yes	Chrysotile 8%	Carbonates Binder/Filler	95%
					Carbonates Quartz Binder/Filler	92%
0158047-071 7-71		Roof Seam Sealer, Black	Yes	Chrysotile 10%	Carbonates Quartz Binder/Filler	90%
					Carbonates Quartz Binder/Filler	90%
0158047-072 7-72		Sealer, Green	No	None Detected	Carbonates Quartz Binder/Filler	100%
					Carbonates Quartz Binder/Filler	100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158047

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/17/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/22/2015
Collected: 07/10/2015 Date Reported: 07/22/2015
Project Name: SIA BLDG #7, 2945 S. FLINT RD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158047-073 7-73		Sealer, Green	No	None Detected	Carbonates Quartz Binder/Filler	100%
0158047-074 7-74		LAYER 1 Fiberglass Insulation, Yellow	No	None Detected	Fibrous Glass Carbonates	97% 3%
		LAYER 2 Backing, White/ Silver	No	None Detected	Fibrous Glass Aluminum Carbonates Binder/Filler	20% 80%
0158047-075 7-75		LAYER 1 Fiberglass Insulation, Yellow	No	None Detected	Fibrous Glass Carbonates	97% 3%
		LAYER 2 Backing, White/ Silver	No	None Detected	Fibrous Glass Aluminum Carbonates Binder/Filler	20% 80%
0158047-076 7-76		Insulation, Green	No	None Detected	Mineral Wool Carbonates	99% 1%
0158047-077 7-77		Insulation, Green	No	None Detected	Mineral Wool Carbonates	99% 1%
0158047-078 7-78		Foam Insulation, Lt. Blue	No	None Detected	Foam Carbonates Binder/Filler	100%
0158047-079 7-79		Foam Insulation, Lt. Blue	No	None Detected	Foam Carbonates Binder/Filler	100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158047

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/17/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/22/2015
Collected: 07/10/2015 Date Reported: 07/22/2015
Project Name: SIA BLDG #7, 2945 S. FLINT RD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID	Sample	Layer Name /	Asbestos	Asbestos Type	Non-Asbestos
Client ID	Location	Sample Description	Detected	(%)	Constituents



Analyst - Johann Hofer



Signatory - Lab Director - Kurt Kettler

Distinctly stratified, easily separable layers of samples are analyzed as subsamples of the whole and are reported separately for each discernible layer. All analyses are derived from calibrated visual estimate and measured in area percent unless otherwise noted. The report applies to the standards or procedures identified and to the sample(s) tested. The test results are not necessarily indicative or representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products, nor do they represent an ongoing quality assurance program unless so noted. These reports are for the exclusive use of the addressed client and that they will not be reproduced wholly or in part for advertising or other purposes over our signature or in connection with our name without special written permission. The report shall not be reproduced except in full, without written approval by our laboratory. The samples not destroyed in testing are retained a maximum of thirty days. The laboratory measurement of uncertainty for the test method is approximately less than 1 by area percent. Accredited by the National Institute of Standards and Technology, Voluntary Laboratory Accreditation Program for selected test method for asbestos. The accreditation or any reports generated by this laboratory in no way constitutes or implies product certification, approval, or endorsement by the National Institute of Standards and Technology. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. Polarized Light Microscopy may not be consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#: 158047
 TAT: 3 day
 Rec'd JUL 17 PM

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019
 CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

BILL TO: _____

(If Different Location)

Now Accepting: **VISA – MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]
 ****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met
2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]
3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #7, 2945 S. Flint Road, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>1</u>	7-1	7/10/15	Sheetrock/ joint compound	<u>0</u> N
<u>2</u>	7-2	7/10/15	Sheetrock/ joint compound	Y N
<u>3</u>	7-3	7/10/15	White wrap/ white lagging/ yellow foam	Y N
<u>4</u>	7-4	7/10/15	White wrap/ white packing/ yellow foam	Y N
<u>5</u>	7-5	7/10/15	White wrap/ white packing/ yellow foam	Y N
<u>6</u>	7-6	7/10/15	White wrap/ white packing/ yellow foam	Y N
<u>7</u>	7-7	7/10/15	White-silver wrap/ yellow fiberglass pipe insulation	Y N
<u>8</u>	7-8	7/10/15	White-silver wrap/ yellow fiberglass pipe insulation	Y N
<u>9</u>	7-9	7/10/15	White-silver wrap/ yellow fiberglass pipe insulation	Y N
<u>10</u>	7-10	7/10/15	White 2x4 ceiling tile	Y N
<u>11</u>	7-11	7/10/15	White 2x4 ceiling tile	Y N
<u>12</u>	7-12	7/10/15	Medium brown 5" cove base/ mastic	Y N
<u>13</u>	7-13	7/10/15	Medium brown 5" cove base/ mastic	Y N
<u>14</u>	7-14	7/10/15	Sheetrock/ joint compound	Y N
<u>15</u>	7-15	7/10/15	Tan cove base/ mastic	<u>0</u> N

SPECIAL INSTRUCTIONS: _____

Sample Collector: (Print) Kevin McCrink (Signature) [Signature]

Relinquished by: [Signature] Date/Time: 7-15-15 Received by: Diana Federica Date/Time: 7/17/15

Relinquished by: Diana Federica Date/Time: 7/17/15 Received by: [Signature] Date/Time: 7-17-15

Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#:	
TAT:	15 8047
Rec'd:	

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019

CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

BILL TO: _____ (If Different Location)

Now Accepting: **VISA – MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #7, 2945 S. Flint Road, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>16</u>	7-16	7/10/15	Tan cove base/ mastic	<u>Y</u> N
<u>17</u>	7-17	7/10/15	Dark tan floor mastic	Y <u>N</u>
<u>18</u>	7-18	7/10/15	Dark tan floor mastic	Y N
<u>19</u>	7-19	7/10/15	Blue 2x2 ceramic tile/ dark gray cement	Y N
<u>20</u>	7-20	7/10/15	Blue 2x2 ceramic tile/ dark gray cement	Y N
<u>21</u>	7-21	7/10/15	Dark gray grout	Y N
<u>22</u>	7-22	7/10/15	Dark gray grout	Y N
<u>23</u>	7-23	7/10/15	Gray framing caulk	Y N
<u>24</u>	7-24	7/10/15	Gray framing caulk	Y N
<u>25</u>	7-25	7/10/15	Beige HVAC duct tape	Y N
<u>26</u>	7-26	7/10/15	Beige HVAC duct tape	Y N
<u>27</u>	7-27	7/10/15	Brown epoxy flooring	Y N
<u>28</u>	7-28	7/10/15	Brown epoxy flooring	Y N
<u>29</u>	7-29	7/10/15	White HVAC duct caulk	Y N
<u>30</u>	7-30	7/10/15	White HVAC duct caulk	Y N

SPECIAL INSTRUCTIONS: _____

Sample Collector: (Print) Kevin McCrink (Signature) [Signature]

Relinquished by: [Signature] Date/Time: 7-15-15 Received by: Diana Federico Date/Time: 7/17/15

Relinquished by: Diana Federico Date/Time: 7/17/15 Received by: [Signature] Date/Time: 7-17-15

Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#:	158047
TAT:	
Rec'd:	

COMPANY NAME: Environmental Risk Mgmt BILL TO: _____ (If Different Location)

1324 Liberty Lake Rd, 231

Liberty Lake, WA 99019

CONTACT: Kevin McCrink

Phone/Fax: (509) 226-2523 /

Email: envriskmgm@aol.com

Now Accepting: **VISA - MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required

****Additional charges for rush analysis (please call marketing department for pricing details)

****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #7, 2945 S. Flint Road, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>31</u>	7-31	7/10/15	Tan wall mastic/ sheetrock	<u>Y</u> N
<u>32</u>	7-32	7/10/15	Tan wall mastic	Y <u>N</u>
<u>33</u>	7-33	7/10/15	Tan wall mastic	Y N
<u>34</u>	7-34	7/10/15	Tan wall glue	Y N
<u>35</u>	7-35	7/10/15	Tan wall glue	Y N
<u>36</u>	7-36	7/10/15	Yellow cooler foam insulation	Y N
<u>37</u>	7-37	7/10/15	Yellow cooler foam insulation	Y N
<u>38</u>	7-38	7/10/15	Gray CMU block	Y N
<u>39</u>	7-39	7/10/15	Gray CMU block	Y N
<u>40</u>	7-40	7/10/15	White mortar	Y N
<u>41</u>	7-41	7/10/15	White mortar	Y N
<u>42</u>	7-42	7/10/15	Lt. brown exterior wall panel	Y N
<u>43</u>	7-43	7/10/15	Lt. brown exterior wall panel	Y N
<u>44</u>	7-44	7/10/15	Lt. brown exterior wall panel	Y N
<u>45</u>	7-45	7/10/15	Lt. brown exterior wall panel	<u>Y</u> N

SPECIAL INSTRUCTIONS:

Sample Collector: (Print) Kevin McCrink (Signature) [Signature]

Relinquished by: [Signature] Date/Time: 7-15-15 Received by: Diana Federica Date/Time: 7/17/15

Relinquished by: Diana Federica Date/Time: 7/17/15 Received by: [Signature] Date/Time: 7-17-15

Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#:	158047
TAT:	
Rec'd:	

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019

CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: enriskmgt@aol.com

BILL TO: _____ (If Different Location)

Now Accepting: **VISA - MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required

****Additional charges for rush analysis (please call marketing department for pricing details)

****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #7, 2945 S. Flint Road, Spokane, WA

P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>46</u>	7-46	7/10/15	White styro foam insulation	<u>N</u>
<u>47</u>	7-47	7/10/15	White styro foam insulation	<u>Y N</u>
<u>48</u>	7-48	7/10/15	Lt. brown-gray cement stucco	<u>Y N</u>
<u>49</u>	7-49	7/10/15	Lt. brown-gray cement stucco	<u>Y N</u>
<u>50</u>	7-50	7/10/15	Lt. brown-gray cement stucco	<u>Y N</u>
<u>51</u>	7-51	7/10/15	Lt. brown-gray cement stucco	<u>Y N</u>
<u>52</u>	7-52	7/10/15	Exterior sheetrock/ paper	<u>Y N</u>
<u>53</u>	7-53	7/10/15	Exterior sheetrock/ paper	<u>Y N</u>
<u>54</u>	7-54	7/10/15	Yellow fiberglass insulation/ tan-black backing paper	<u>Y N</u>
<u>55</u>	7-55	7/10/15	Yellow fiberglass insulation/ tan-black backing paper	<u>Y N</u>
<u>56</u>	7-56	7/10/15	Red fire stop	<u>Y N</u>
<u>57</u>	7-57	7/10/15	Red fire stop	<u>Y N</u>
<u>58</u>	7-58	7/10/15	Lt. gray roof seam sealer	<u>Y N</u>
<u>59</u>	7-59	7/10/15	Lt. gray roof seam sealer	<u>Y N</u>
<u>60</u>	7-60	7/10/15	Lt. gray roof seam sealer	<u>N</u>

SPECIAL INSTRUCTIONS:

Sample Collector: (Print) Kevin McCrink (Signature) [Signature]

Relinquished by: [Signature] Date/Time: 7-15-15 Received by: Diana Federico Date/Time: 7/17/15

Relinquished by: Diana Federico Date/Time: 7/17/15 Received by: [Signature] Date/Time: 7-17-15

Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#:	158017
TAT:	
Rec'd:	

COMPANY NAME: Environmental Risk Mgmt BILL TO: _____ (If Different Location)

1324 Liberty Lake Rd, 231

Liberty Lake, WA 99019

CONTACT: Kevin McCrink

Phone/Fax: (509) 226-2523 /

Email: envriskmgm@aol.com

Now Accepting: **VISA - MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] (3-Day) [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** (Bulk-PLM) [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #7, 2945 S. Flint Road, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>61</u>	7-61	7/10/15	Lt. gray roof seam sealer	<u>(Y)</u> N
<u>62</u>	7-62	7/10/15	Medium gray roof seam sealer	Y N
<u>63</u>	7-63	7/10/15	Medium gray roof seam sealer	Y N
<u>64</u>	7-64	7/10/15	Lt. gray roof seam sealer	Y N
<u>65</u>	7-65	7/10/15	White-black roof seam sealer	Y N
<u>66</u>	7-66	7/10/15	White-black roof seam sealer	Y N
<u>67</u>	7-67	7/10/15	White-silver HVAC sealer	Y N
<u>68</u>	7-68	7/10/15	White-silver HVAC sealer	Y N
<u>69</u>	7-69	7/10/15	White-silver HVAC sealer	Y N
<u>70</u>	7-70	7/10/15	Black roof seam sealer	Y N
<u>71</u>	7-71	7/10/15	Black roof seam sealer	Y N
<u>72</u>	7-72	7/10/15	Green sealer	Y N
<u>73</u>	7-73	7/10/15	Green sealer	Y N
<u>74</u>	7-74	7/10/15	White-silver backing/ yellow fiberglass insulation	Y N
<u>75</u>	7-75	7/10/15	White-silver backing/ yellow fiberglass insulation	<u>(Y)</u> N

SPECIAL INSTRUCTIONS: _____

Sample Collector: (Print) Kevin McCrink (Signature) Kevin

Relinquished by: Kevin Date/Time: 7-15-15 Received by: Diana Federico Date/Time: 7/17/15

Relinquished by: Diana Federico Date/Time: 7/17/15 Received by: Jim - J. Deffen Date/Time: 7-17-15

Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#:	
TAT:	158047
Rec'd:	

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019
 CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

BILL TO: _____ (If Different Location)

Now Accepting: **VISA – MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]
 ****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met
2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]
3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #7, 2945 S. Flint Road, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>76</u>	7-76	7/10/15	Green insulation	<u>Y</u> N
<u>77</u>	7-77	7/10/15	Green insulation	Y <u>N</u>
<u>78</u>	7-78	7/10/15	Lt. blue foam insulation	Y N
<u>79</u>	7-79	7/10/15	Lt. blue foam insulation	<u>Y</u> N
				Y N
				Y N
				Y N
				Y N
				Y N
				Y N
				Y N
				Y N
				Y N
				Y N
				Y N
				Y N

SPECIAL INSTRUCTIONS: _____
 Sample Collector: (Print) Kevin McCrink (Signature) [Signature]
 Relinquished by: [Signature] Date/Time: 7-15-15 Received by: Diana Federico Date/Time: 7/17/15
 Relinquished by: Diana Federico Date/Time: 7/17/15 Received by: [Signature] Date/Time: 7-17-15
 Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158405

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/27/2015
Collected:	07/24/2015	Date Analyzed:	07/27/2015
Project Name:	SIA BLDG #85, 8924 W. ELECTRIC AVE	Date Reported:	07/28/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158405-001 85-1		LAYER 1 Knock-down Texture, White	No	None Detected	Cellulose Fiber Carbonates Mica Quartz Binder/Filler	1% 99%
		LAYER 2 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber Gypsum Quartz Carbonates	10% 90%
0158405-002 85-2		LAYER 1 Knock-down Texture, White	No	None Detected	Cellulose Fiber Carbonates Mica Quartz Perlite Binder/Filler	<1% 99%
		LAYER 2 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber Fibrous Glass Gypsum Quartz Carbonates	10% 1% 89%
0158405-003 85-3		LAYER 1 Knock-down Texture, White	No	None Detected	Cellulose Fiber Carbonates Mica Quartz Perlite Binder/Filler	<1% 99%
		LAYER 2 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber Gypsum Quartz Carbonates	10% 90%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158405

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/27/2015
Collected:	07/24/2015	Date Analyzed:	07/27/2015
Project Name:	SIA BLDG #85, 8924 W. ELECTRIC AVE	Date Reported:	07/28/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158405-004 85-4		LAYER 1 Knock-down Texture, White	No	None Detected	Cellulose Fiber Carbonates Mica Quartz Perlite Binder/Filler	<1% 99%
		LAYER 2 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber Gypsum Quartz Carbonates	10% 90%
0158405-005 85-5		LAYER 1 Knock-down Texture, White	No	None Detected	Cellulose Fiber Carbonates Mica Quartz Perlite Binder/Filler	<1% 99%
		LAYER 2 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber Gypsum Quartz Carbonates	10% 90%
0158405-006 85-6		LAYER 1 Sheet Vinyl, White	No	None Detected	Cellulose Fiber Synthetic Fiber Fibrous Glass Carbonates Gypsum Quartz Binder/Filler	15% 3% 2% 80%
		LAYER 2 Mastic, White	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	1% 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158405

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/27/2015
Collected:	07/24/2015	Date Analyzed:	07/27/2015
Project Name:	SIA BLDG #85, 8924 W. ELECTRIC AVE	Date Reported:	07/28/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158405-007 85-7		LAYER 1 Sheet Vinyl, White	No	None Detected	Cellulose Fiber 15% Synthetic Fiber 3% Fibrous Glass 2% Carbonates Gypsum Quartz Binder/Filler 80%
		LAYER 2 Mastic, White	No	None Detected	Cellulose Fiber 1% Carbonates Gypsum Quartz Binder/Filler 99%
0158405-008 85-8		Floor Mat, Black	No	None Detected	Synthetic Fiber 5% Carbonates Quartz Binder/Filler 95%
0158405-009 85-9		Floor Mat, Black	No	None Detected	Fibrous Glass 1% Cellulose Fiber <1% Carbonates Quartz Binder/Filler 98%
0158405-010 85-10		HVAC Duct Lining, Black	No	None Detected	Fibrous Glass 50% Synthetic Fiber 35% Carbonates Binder/Filler 15%
0158405-011 85-11		HVAC Duct Lining, Black	No	None Detected	Fibrous Glass 50% Synthetic Fiber 35% Carbonates Binder/Filler 15%
0158405-012 85-12		Fiberglass Insulation, Yellow	No	None Detected	Fibrous Glass 95% Carbonates Binder/Filler 5%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158405

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/27/2015
Collected:	07/24/2015	Date Analyzed:	07/27/2015
Project Name:	SIA BLDG #85, 8924 W. ELECTRIC AVE	Date Reported:	07/28/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158405-013 85-13		Fiberglass Insulation, Yellow	No	None Detected	Fibrous Glass Carbonates Gypsum Binder/Filler	95% 5%
0158405-014 85-14		LAYER 1 Brick, Orange	No	None Detected	Quartz Gypsum Mica Carbonates Binder/Filler	 100%
		LAYER 2 Mortar, White	No	None Detected	Cellulose Fiber Quartz Gypsum Mica Carbonates Binder/Filler	<1% 99%
0158405-015 85-15		LAYER 1 Brick, Orange	No	None Detected	Quartz Gypsum Mica Carbonates Binder/Filler	 100%
		LAYER 2 Mortar, White	No	None Detected	Cellulose Fiber Quartz Gypsum Mica Carbonates Binder/Filler	<1% 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158405

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/27/2015
Collected:	07/24/2015	Date Analyzed:	07/27/2015
Project Name:	SIA BLDG #85, 8924 W. ELECTRIC AVE	Date Reported:	07/28/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158405-016 85-16		LAYER 1 Brick, Orange	No	None Detected	Quartz Gypsum Mica Carbonates Binder/Filler 100%
		LAYER 2 Mortar, White	No	None Detected	Cellulose Fiber <1% Quartz Gypsum Mica Carbonates Binder/Filler 99%
0158405-017 85-17		LAYER 1 Brick, Orange	No	None Detected	Quartz Gypsum Mica Carbonates Binder/Filler 100%
		LAYER 2 Mortar, White	No	None Detected	Cellulose Fiber <1% Quartz Gypsum Mica Carbonates Binder/Filler 99%
0158405-018 85-18		Mortar, Gray	No	None Detected	Cellulose Fiber <1% Carbonates Gypsum Mica Quartz Binder/Filler 99%
0158405-019 85-19		Mortar, Gray	No	None Detected	Cellulose Fiber <1% Carbonates Gypsum Mica Quartz Binder/Filler 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158405

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/27/2015
Collected:	07/24/2015	Date Analyzed:	07/27/2015
Project Name:	SIA BLDG #85, 8924 W. ELECTRIC AVE	Date Reported:	07/28/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158405-020 85-20		Caulk, White	No	None Detected	Cellulose Fiber Carbonates Quartz Binder/Filler	<1% 99%
0158405-021 85-21		Caulk, White	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	<1% 99%
0158405-022 85-1-1		Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber Fibrous Glass Gypsum Quartz Carbonates	10% 2% 88%
0158405-023 85-1-2		Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber Fibrous Glass Gypsum Quartz Carbonates	10% 2% 88%
0158405-024 85-1-3		LAYER 1 Asphalt Roofing Shingle, White/ Black	No	None Detected	Fibrous Glass Carbonates Gypsum Quartz Binder/Filler	20% 80%
		LAYER 2 Tar, Black	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	<1% 99%
0158405-025 85-1-4		Asphalt Roofing Shingle, White/ Black	No	None Detected	Fibrous Glass Carbonates Gypsum Quartz Binder/Filler	20% 80%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726


Laboratory Report
0158405

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231	Date Received:	07/27/2015
	LIBERTY LAKE, WA 99019	Date Analyzed:	07/27/2015
Collected:	07/24/2015	Date Reported:	07/28/2015
Project Name:	SIA BLDG #85, 8924 W. ELECTRIC AVE	EPA Method:	EPA 600/R-93/116
Address:	SPOKANE, WA	Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID	Sample	Layer Name /	Asbestos	Asbestos Type	Non-Asbestos
Client ID	Location	Sample Description	Detected	(%)	Constituents



Analyst - Kenneth Scheske



Signatory - Lab Director - Kurt Kettler

Distinctly stratified, easily separable layers of samples are analyzed as subsamples of the whole and are reported separately for each discernible layer. All analyses are derived from calibrated visual estimate and measured in area percent unless otherwise noted. The report applies to the standards or procedures identified and to the sample(s) tested. The test results are not necessarily indicated or representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products, nor do they represent an ongoing quality assurance program unless so noted. These reports are for the exclusive use of the addressed client and that they will not be reproduced wholly or in part for advertising or other purposes over our signature or in connection with our name without special written permission. The report shall not be reproduced except in full, without written approval by our laboratory. The samples not destroyed in testing are retained a maximum of thirty days. The laboratory measurement of uncertainty for the test method is approximately less than 1 by area percent. Accredited by the National Institute of Standards and Technology, Voluntary Laboratory Accreditation Program for selected test method for asbestos. The accreditation or any reports generated by this laboratory in no way constitutes or implies product certification, approval, or endorsement by the National Institute of Standards and Technology. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. Polarized Light Microscopy may not be consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#: 158405
 TAT: 1 day
 Rec'd: JUL 27 PM.

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019
 CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

BILL TO: _____ (If Different Location)

Now Accepting: **VISA - MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required

****Additional charges for rush analysis (please call marketing department for pricing details)

****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #85, 8924 W. Electric Avenue, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>1</u>	85-1	7/24/15	Knock-down texture/ sheetrock	<u>Y</u> N
<u>2</u>	85-2	7/24/15	Knock-down texture/ sheetrock	Y <u>N</u>
<u>3</u>	85-3	7/24/15	Knock-down texture/ sheetrock	Y N
<u>4</u>	85-4	7/24/15	Knock-down texture/ sheetrock	Y N
<u>5</u>	85-5	7/24/15	Knock-down texture/ sheetrock	Y N
<u>6</u>	85-6	7/24/15	White sheet vinyl white mastic	Y N
<u>7</u>	85-7	7/24/15	White sheet vinyl white mastic	Y N
<u>8</u>	85-8	7/24/15	Black floor mat	Y N
<u>9</u>	85-9	7/24/15	Black floor mat	Y N
<u>10</u>	85-10	7/24/15	Black HVAC duct lining	Y N
<u>11</u>	85-11	7/24/15	Black HVAC duct lining	Y N
<u>12</u>	85-12	7/24/15	Yellow fiberglass insulation	Y N
<u>13</u>	85-13	7/24/15	Yellow fiberglass insulation	Y N
<u>14</u>	85-14	7/24/15	Orange brick/ white mortar	Y N
<u>15</u>	85-15	7/24/15	Orange brick/ white mortar	<u>Y</u> N

SPECIAL INSTRUCTIONS: _____
 Sample Collector: (Print) Kevin McCrink (Signature) [Signature]
 Relinquished by: [Signature] Date/Time: 7-25-15 Received by: Diana Federico Date/Time: 7/27/15
 Relinquished by: Diana Federico Date/Time: 7/27/15 Received by: [Signature] Date/Time: 7/27/15
 Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#:	158405
TAT:	
Rec'd:	

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019

CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: enriskmgm@aol.com

BILL TO: _____ (If Different Location)

Now Accepting: **VISA - MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

- TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]
 ****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met
- TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]
- DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #85, 8924 W. Electric Avenue, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>16</u>	85-16	7/24/15	Orange brick/ white mortar	<u>Y</u> N
<u>17</u>	85-17	7/24/15	Orange brick/ white mortar	Y N
<u>18</u>	85-18	7/24/15	White mortar	Y N
<u>19</u>	85-19	7/24/15	White mortar	Y N
<u>20</u>	85-20	7/24/15	White caulk	Y N
<u>21</u>	85-21	7/24/15	White caulk	Y N
<u>22</u>	85-1-1	7/24/15	Sheetrock	Y N
<u>23</u>	85-1-2	7/24/15	Sheetrock	Y N
<u>24</u>	85-1-3	7/24/15	White asphalt roofing shingle/ tar	Y N
<u>25</u>	85-1-4	7/24/15	White asphalt roofing shingle	<u>Y</u> N
				Y N
				Y N
				Y N
				Y N
				Y N

SPECIAL INSTRUCTIONS: _____

Sample Collector: (Print) Kevin McCrink (Signature) [Signature]

Relinquished by: [Signature] Date/Time: 7-25-15 Received by: Diana Federico Date/Time: 7/27/15

Relinquished by: Diana Federico Date/Time: 7/27/15 Received by: [Signature] Date/Time: 7/27/15

Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/21/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/13/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158191-001 360-1		Transite Panel, White/ Gray	Yes	Chrysotile 15%	Carbonates Gypsum Quartz Binder/Filler	85%
0158191-002 360-2		LAYER 1 Fiberglass Insulation, Black	No	None Detected	Fibrous Glass Carbonates Binder/Filler	98% 2%
		LAYER 2 Backing Paper, Black	No	None Detected	Cellulose Fiber Fibrous Glass Carbonates Gypsum Binder/Filler	60% 5% 35%
0158191-003 360-3		LAYER 1 Fiberglass Insulation, Black	No	None Detected	Fibrous Glass Carbonates Binder/Filler	98% 2%
		LAYER 2 Backing Paper, Black	No	None Detected	Cellulose Fiber Fibrous Glass Carbonates Gypsum Binder/Filler	60% 5% 35%
0158191-004 360-4		LAYER 1 Fiberglass Duct Insulation, Yellow	No	None Detected	Fibrous Glass Carbonates Binder/Filler	98% 2%
		LAYER 2 Glue, Black	No	None Detected	Fibrous Glass Carbonates Gypsum Quartz Binder/Filler	5% 95%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/21/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/13/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158191-005 360-5		LAYER 1 Fiberglass Duct Insulation, Yellow	No	None Detected	Fibrous Glass 98% Carbonates Binder/Filler 2%
		LAYER 2 Glue, Black	No	None Detected	Fibrous Glass 5% Carbonates Gypsum Quartz Binder/Filler 95%
0158191-006 360-6		Tar Paper Strip, Black	No	None Detected	Synthetic Fiber 85% Carbonates Gypsum Binder/Filler 15%
0158191-007 360-7		Tar Paper Strip, Black	No	None Detected	Synthetic Fiber 85% Carbonates Gypsum Binder/Filler 15%
0158191-008 360-8		Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber 10% Gypsum Quartz Carbonates 90%
0158191-009 360-9		Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber 10% Gypsum Quartz Carbonates 90%
0158191-010 360-10		Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber 10% Gypsum Quartz Carbonates 90%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/21/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/13/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158191-011 360-11		Residual Floor Mastic, Black	Yes	Chrysotile 8%	Carbonates Gypsum Quartz Binder/Filler	92%
0158191-012 360-12		Residual Floor Mastic, Black	Yes	Chrysotile 5%	Carbonates Gypsum Quartz Binder/Filler	95%
0158191-013 360-13		Framing Base Paper, Black	No	None Detected	Synthetic Fiber Carbonates Gypsum Binder/Filler	85% 15%
0158191-014 360-14		Framing Base Paper, Black	No	None Detected	Synthetic Fiber Carbonates Gypsum Binder/Filler	85% 15%
0158191-015 360-15		Joint Compound, White	Yes	Chrysotile 3%	Carbonates Mica Quartz Binder/Filler	97%
0158191-016 360-16		Joint Compound, White	Yes	Chrysotile 3%	Carbonates Mica Quartz Binder/Filler	97%
0158191-017 360-17		Tar Seam Sealer, Black	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	3% 97%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/21/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/13/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158191-018 360-18		Tar Seam Sealer, Black	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	3% 97%
0158191-019 360-19		Carpet Mastic, Yellow	No	None Detected	Synthetic Fiber Carbonates Gypsum Quartz Binder/Filler	1% 99%
0158191-020 360-20		Carpet Mastic, Yellow	No	None Detected	Synthetic Fiber Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	2% 1% 97%
0158191-021 360-21		LAYER 1 Cove Base, Gray	No	None Detected	Carbonates Quartz Binder/Filler	100%
		LAYER 2 Mastic, Off White	No	None Detected	Carbonates Gypsum Quartz Binder/Filler	100%
0158191-022 360-22		LAYER 1 Cove Base, Gray	No	None Detected	Carbonates Quartz Binder/Filler	100%
		LAYER 2 Mastic, Off White	No	None Detected	Carbonates Gypsum Quartz Binder/Filler	100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/21/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/13/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158191-023 360-23		LAYER 1 Sponge Pattern Texture, Off White	No	None Detected	Cellulose Fiber Carbonates Gypsum Mica Binder/Filler	<1% 99%
		LAYER 2 Sheetrock, Off White/ Brown	No	None Detected	Cellulose Fiber Gypsum Quartz Carbonates	12% 88%
0158191-024 360-24		LAYER 1 Sponge Pattern Texture, Off White	No	None Detected	Cellulose Fiber Carbonates Gypsum Mica Binder/Filler	<1% 99%
		LAYER 2 Sheetrock, Off White/ Brown	No	None Detected	Cellulose Fiber Gypsum Quartz Carbonates	12% 88%
0158191-025 360-25		LAYER 1 Sponge Pattern Texture, Off White	No	None Detected	Cellulose Fiber Carbonates Gypsum Mica Binder/Filler	<1% 99%
		LAYER 2 Sheetrock, Off White/ Brown	No	None Detected	Cellulose Fiber Gypsum Quartz Carbonates	12% 88%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/21/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/13/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158191-026 360-26		LAYER 1 Knock-down Pattern Texture, Off White	No	None Detected	Cellulose Fiber Carbonates Gypsum Mica Binder/Filler	<1% 99%
		LAYER 2 Sheetrock/Transite, Gray Note: Layer appears to be transite	Yes	Chrysotile 15%	Carbonates Gypsum Quartz Binder/Filler	85%
0158191-027 360-27		LAYER 1 Knock-down Pattern Texture, Off White	No	None Detected	Cellulose Fiber Carbonates Gypsum Mica Binder/Filler	<1% 99%
		LAYER 2 Sheetrock/Transite, Gray Note: Layer appears to be transite	Yes	Chrysotile 15%	Carbonates Gypsum Quartz Binder/Filler	85%
0158191-028 360-28		LAYER 1 Sponge Pattern Texture, Off White	No	None Detected	Cellulose Fiber Carbonates Mica Quartz Perlite Binder/Filler	<1% 99%
		LAYER 2 Sheetrock, Off White/ Brown	No	None Detected	Cellulose Fiber Gypsum Quartz Carbonates	12% 88%
0158191-029 360-29		Leveling Compound, White	No	None Detected	Cellulose Fiber Carbonates Gypsum Mica Binder/Filler	<1% 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/21/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/13/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158191-030 360-30		Leveling Compound, White	No	None Detected	Carbonates Gypsum Mica Quartz Binder/Filler	100%
0158191-031 360-31		LAYER 1 SHEETROCK, Off White/ Brown	No	None Detected	Cellulose Fiber Gypsum Quartz Carbonates	12% 88%
		LAYER 2 Joint Compound, Off White	Yes	Chrysotile 3%	Carbonates Mica Quartz Binder/Filler	97%
		LAYER 3 SHEETROCK, Joint Compound Composite, Off White/ Brown Note: COMPOSITE ANALYSIS REQUESTED	Yes	Chrysotile <1%	Cellulose Fiber Gypsum Carbonates Mica Quartz Binder/Filler	11% 88%
0158191-032 360-32		LAYER 1 SHEETROCK, Off White/ Brown	No	None Detected	Cellulose Fiber Gypsum Quartz Carbonates	12% 88%
		LAYER 2 Joint Compound, Off White	Yes	Chrysotile 3%	Carbonates Mica Quartz Binder/Filler	97%
		LAYER 3 SHEETROCK, Joint Compound Composite, Off White/ Brown Note: COMPOSITE ANALYSIS REQUESTED	Yes	Chrysotile <1%	Cellulose Fiber Gypsum Carbonates Mica Quartz Binder/Filler	11% 88%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/21/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/13/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158191-033 360-33		LAYER 1 Carpet Mastic, Tan	No	None Detected	Synthetic Fiber	2%
					Carbonates Gypsum Quartz Binder/Filler	98%
		LAYER 2 Carpet, Tan	No	None Detected	Synthetic Fiber	95%
					Carbonates Binder/Filler	5%
0158191-034 360-34		Carpet Mastic, Tan	No	None Detected	Synthetic Fiber	2%
					Carbonates Gypsum Quartz Binder/Filler	98%
0158191-035 360-35		LAYER 1 9"x9" Floor Tile, Green	Yes	Chrysotile 3%	Carbonates Quartz Binder/Filler	97%
		LAYER 2 Mastic/ Vapor Barrier, Black	No	None Detected	Cellulose Fiber	40%
					Carbonates Gypsum Quartz Binder/Filler	60%
0158191-036 360-36		LAYER 1 9"x9" Floor Tile, Green	Yes	Chrysotile 3%	Carbonates Quartz Binder/Filler	97%
		LAYER 2 Mastic/ Vapor Barrier, Black	No	None Detected	Cellulose Fiber	40%
					Carbonates Gypsum Quartz Binder/Filler	60%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/21/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/13/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158191-037 360-37		Flooring Paper, Black	No	None Detected	Cellulose Fiber Synthetic Fiber Carbonates Gypsum Quartz Binder/Filler	45% 5% 50%
0158191-038 360-38		Flooring Paper, Black	No	None Detected	Cellulose Fiber Synthetic Fiber Carbonates Gypsum Quartz Binder/Filler	45% 5% 50%
0158191-039 360-39		Panel Mastic, Green	Yes	Chrysotile 5%	Carbonates Gypsum Quartz Binder/Filler	 95%
0158191-040 360-40		Panel Mastic, Green	Yes	Chrysotile 4%	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	1% 95%
0158191-041 360-41		LAYER 1 12"x12" Floor Tile, White	Yes	Chrysotile 3%	Carbonates Quartz Binder/Filler	 97%
		LAYER 2 Mastic, Tan	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	1% 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/21/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/13/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158191-042 360-42		LAYER 1 12"x12" Floor Tile, White	Yes	Chrysotile 3%	Carbonates Quartz Binder/Filler 97%
		LAYER 2 Mastic, Tan	No	None Detected	Cellulose Fiber 1% Synthetic Fiber <1% Carbonates Gypsum Quartz Binder/Filler 98%
0158191-043 360-43		LAYER 1 12"x12" Floor Tile, Gray	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Black	Yes	Chrysotile 5%	Carbonates Gypsum Binder/Filler 95%
0158191-044 360-44		LAYER 1 12"x12" Floor Tile, Gray	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Black	Yes	Chrysotile 5%	Carbonates Gypsum Binder/Filler 95%
0158191-045 360-45		LAYER 1 Sheetrock, Off White/ Brown	No	None Detected	Cellulose Fiber 12% Gypsum Quartz Carbonates 88%
		LAYER 2 Joint Compound, Off White	No	None Detected	Cellulose Fiber <1% Carbonates Mica Quartz Binder/Filler 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/21/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/13/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158191-046 360-46		LAYER 1 Cove Base, Brown	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Beige	No	None Detected	Cellulose Fiber <1% Carbonates Gypsum Quartz Binder/Filler 99%
0158191-047 360-47		LAYER 1 Cove Base, Brown	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Beige	No	None Detected	Cellulose Fiber <1% Carbonates Gypsum Quartz Binder/Filler 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/21/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/13/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158191-048 360-48		LAYER 1 Sheet Vinyl, White	No	None Detected	Cellulose Fiber 15% Wollastonite 3% Fibrous Glass 2% Carbonates Gypsum Quartz Binder/Filler 80%
		LAYER 2 Mastic, Beige	No	None Detected	Cellulose Fiber 1% Fibrous Glass <1% Carbonates Gypsum Quartz Binder/Filler 98%
		LAYER 3 Sheet Vinyl, Off White	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 4 Mastic, Black	Yes	Chrysotile 3%	Cellulose Fiber 1% Carbonates Gypsum Quartz Binder/Filler 96%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
 Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231	Date Received:	07/21/2015
LIBERTY LAKE, WA 99019	Date Analyzed:	07/24/2015
Collected: 07/13/2015	Date Reported:	07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE,	EPA Method:	EPA 600/R-93/116
SPOKANE, WA	Submitted By:	KEVIN McCRINK
Address:	Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158191-049 360-49		LAYER 1 Sheet Vinyl, White	No	None Detected	Cellulose Fiber 15% Wollastonite 3% Fibrous Glass 2% Carbonates Gypsum Quartz Binder/Filler 80%
		LAYER 2 Mastic/ Leveling Compound, Beige/White Note: Difficult to separate adjacent layers	No	None Detected	Cellulose Fiber 2% Carbonates Gypsum Quartz Binder/Filler 98%
		LAYER 3 Sheet Vinyl, Off White	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 4 Mastic, Black	Yes	Chrysotile 3%	Cellulose Fiber <1% Carbonates Gypsum Quartz Binder/Filler 96%
0158191-050 360-50		LAYER 1 Cove Base, White	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Beige	No	None Detected	Cellulose Fiber 1% Synthetic Fiber 1% Carbonates Gypsum Quartz Binder/Filler 98%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/21/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/13/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158191-051 360-51		LAYER 1 Cove Base, White	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Beige	No	None Detected	Cellulose Fiber <1% Carbonates Gypsum Quartz Binder/Filler 99%
0158191-052 360-52		2x4 Ceiling Tile, White	No	None Detected	Mineral Wool 65% Cellulose Fiber 15% Carbonates Gypsum Perlite Binder/Filler 20%
0158191-053 360-53		2x4 Ceiling Tile, White	No	None Detected	Mineral Wool 65% Cellulose Fiber 15% Carbonates Gypsum Perlite Binder/Filler 20%
0158191-054 360-54		LAYER 1 Sheetrock, Off White/ Brown	No	None Detected	Cellulose Fiber 12% Gypsum Quartz Carbonates 88%
		LAYER 2 Joint Compound, White	No	None Detected	Cellulose Fiber <1% Carbonates Mica Quartz Perlite Binder/Filler 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/21/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/13/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158191-055 360-55		LAYER 1 Sheetrock, Off White/ Brown	No	None Detected	Cellulose Fiber	12%
					Gypsum Quartz Carbonates	88%
		LAYER 2 Joint Compound, White	No	None Detected	Cellulose Fiber	1%
					Carbonates Mica Quartz Binder/Filler	99%
0158191-056 360-56		LAYER 3 Texture, White	No	None Detected	Cellulose Fiber	1%
					Carbonates Mica Quartz Binder/Filler	99%
		LAYER 1 Carpet, Gray	No	None Detected	Synthetic Fiber	95%
					Carbonates Binder/Filler	5%
0158191-057 360-57		LAYER 2 Mastic, Tan/Black Note: Unable to separate adjacent layers	Yes	Chrysotile 5%	Synthetic Fiber	<1%
					Carbonates Gypsum Quartz Binder/Filler	94%
		LAYER 1 Carpet, Gray	No	None Detected	Synthetic Fiber	95%
					Carbonates Binder/Filler	5%
0158191-057 360-57		LAYER 2 Mastic, Tan/Black Note: Unable to separate adjacent layers	Yes	Chrysotile 5%	Cellulose Fiber	1%
					Carbonates Gypsum Quartz Binder/Filler	94%
		LAYER 1 Carpet, Gray	No	None Detected	Synthetic Fiber	95%
					Carbonates Binder/Filler	5%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/21/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/13/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158191-058 360-58		LAYER 1 Cove Base, Black	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Off White	No	None Detected	Cellulose Fiber <1% Carbonates Gypsum Quartz Binder/Filler 99%
0158191-059 360-59		LAYER 1 Cove Base, Black	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Off White	No	None Detected	Carbonates Gypsum Quartz Binder/Filler 100%
0158191-060 360-60		LAYER 1 Sheetrock, Off White/ Brown	No	None Detected	Cellulose Fiber 12% Gypsum Quartz Carbonates 88%
		LAYER 2 Joint Compound, Off White	Yes	Chrysotile 3%	Cellulose Fiber 2% Carbonates Mica Quartz Binder/Filler 95%
0158191-061 360-61		12"x12" Ceiling Tile, White / Tan	No	None Detected	Cellulose Fiber 85% Carbonates Gypsum Quartz Binder/Filler 15%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/21/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/13/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158191-062 360-62		12"x12" Ceiling Tile, White / Tan	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	85% 15%
0158191-063 360-63		LAYER 1 Insulation, Black	No	None Detected	Mineral Wool Carbonates Binder/Filler	98% 2%
		LAYER 2 Backing Paper, Tan/Black	No	None Detected	Cellulose Fiber Mineral Wool Carbonates Gypsum Binder/Filler	45% 5% 50%
0158191-064 360-64		LAYER 1 Insulation, Black	No	None Detected	Mineral Wool Carbonates Binder/Filler	98% 2%
		LAYER 2 Backing Paper, Tan/Black	No	None Detected	Cellulose Fiber Mineral Wool Carbonates Gypsum Binder/Filler	45% 5% 50%
0158191-065 360-65		LAYER 1 Cloth, Gray	Yes	Chrysotile 70%	Carbonates Gypsum Binder/Filler	30%
		LAYER 2 Tar on Bollards, Black Note: Difficult to separate adjacent layers	Yes	Chrysotile 2%	Carbonates Gypsum Quartz Binder/Filler	98%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/21/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/13/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158191-066 360-66		LAYER 1 Cloth, Gray	Yes	Chrysotile 70%	Carbonates Gypsum Binder/Filler 30%
		LAYER 2 Tar on Bollards, Black Note: Difficult to separate adjacent layers	Yes	Chrysotile 4%	Cellulose Fiber 2% Carbonates Gypsum Quartz Binder/Filler 94%
0158191-067 360-67		LAYER 1 Chimney Block, Gray	No	None Detected	Carbonates Gypsum Quartz Perlite Binder/Filler 100%
		LAYER 2 Mortar, Gray	No	None Detected	Cellulose Fiber <1% Quartz Gypsum Mica Carbonates Binder/Filler 99%
0158191-068 360-68		LAYER 1 Chimney Block, Gray	No	None Detected	Synthetic Fiber <1% Carbonates Gypsum Quartz Perlite Binder/Filler 99%
		LAYER 2 Mortar, Gray	No	None Detected	Cellulose Fiber <1% Quartz Gypsum Mica Carbonates Binder/Filler 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/21/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/13/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158191-069 360-69		LAYER 1 CMU Block, Gray	No	None Detected	Cellulose Fiber Quartz Carbonates Gypsum Mica Binder/Filler	<1% 99%
		LAYER 2 Mortar, Gray	No	None Detected	Quartz Carbonates Gypsum Mica Binder/Filler	 100%
0158191-070 360-70		LAYER 1 CMU Block, Gray	No	None Detected	Cellulose Fiber Quartz Gypsum Mica Carbonates Binder/Filler	<1% 99%
		LAYER 2 Mortar, Gray	No	None Detected	Quartz Carbonates Gypsum Mica Binder/Filler	 100%
0158191-071 360-71		LAYER 1 CMU Block, Gray	No	None Detected	Cellulose Fiber Quartz Gypsum Mica Carbonates Binder/Filler	<1% 99%
		LAYER 2 Mortar, Gray	No	None Detected	Cellulose Fiber Quartz Carbonates Gypsum Mica Binder/Filler	<1% 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158191

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/21/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/13/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 360, 7810 W. LUKE AVE, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158191-072 360-72		LAYER 1 CMU Block, Gray	No	None Detected	Quartz Gypsum Carbonates Mica Binder/Filler 100%
		LAYER 2 Mortar, Gray	No	None Detected	Cellulose Fiber <1% Quartz Carbonates Gypsum Mica Binder/Filler 99%



Analyst - Octavio Gavarreteayestas



Signatory - Lab Director - Kurt Kettler

Distinctly stratified, easily separable layers of samples are analyzed as subsamples of the whole and are reported separately for each discernible layer. All analyses are derived from calibrated visual estimate and measured in area percent unless otherwise noted. The report applies to the standards or procedures identified and to the sample(s) tested. The test results are not necessarily indicative or representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products, nor do they represent an ongoing quality assurance program unless so noted. These reports are for the exclusive use of the addressed client and that they will not be reproduced wholly or in part for advertising or other purposes over our signature or in connection with our name without special written permission. The report shall not be reproduced except in full, without written approval by our laboratory. The samples not destroyed in testing are retained a maximum of thirty days. The laboratory measurement of uncertainty for the test method is approximately less than 1 by area percent. Accredited by the National Institute of Standards and Technology, Voluntary Laboratory Accreditation Program for selected test method for asbestos. The accreditation or any reports generated by this laboratory in no way constitutes or implies product certification, approval, or endorsement by the National Institute of Standards and Technology. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. Polarized Light Microscopy may not be consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#: 158191
 TAT: 3 days
 Rec'd: JUL 20 P.M.

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019
 CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

BILL TO: _____ (If Different Location)

Now Accepting: **VISA - MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #360, 7810 W. Luke Avenue, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

(12)

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>1</u>	360-1	7/13/15	Transite panel	<u>X</u> N
<u>2</u>	360-2	7/13/15	Black fiberglass insulation/ black backing paper	Y N
<u>3</u>	360-3	7/13/15	Black fiberglass insulation/ black backing paper	Y N
<u>4</u>	360-4	7/13/15	Yellow fiberglass duct insulation/ black glue	Y N
<u>5</u>	360-5	7/13/15	Yellow fiberglass duct insulation/ black glue	Y N
<u>6</u>	360-6	7/13/15	Black tar paper strip	Y N
<u>7</u>	360-7	7/13/15	Black tar paper strip	Y N
<u>8</u>	360-8	7/13/15	Sheetrock	Y N
<u>9</u>	360-9	7/13/15	Sheetrock	Y N
<u>10</u>	360-10	7/13/15	Sheetrock	Y N
<u>11</u>	360-11	7/13/15	Black residual floor mastic	Y N
<u>12</u>	360-12	7/13/15	Black residual floor mastic	Y N
<u>13</u>	360-13	7/13/15	Black framing base paper	Y N
<u>14</u>	360-14	7/13/15	Black framing base paper	Y N
<u>15</u>	360-15	7/13/15	Joint compound	Y N

SPECIAL INSTRUCTIONS: _____
 Sample Collector: (Print) Kevin McCrink (Signature) [Signature]
 Relinquished by: [Signature] Date/Time: 7-20-15 Received by: Diana Federico Date/Time: 7/21/15
 Relinquished by: Diana Federico Date/Time: 7/21/15 Received by: [Signature] Date/Time: 7/21/15
 Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#:	<u>158191</u>
TAT:	
Rec'd:	

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019

CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

BILL TO: _____

(If Different Location)

Now Accepting: **VISA - MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #360, 7810 W. Luke Avenue, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>16</u>	360-16	7/13/15	Joint compound	<u>Y</u> N
<u>17</u>	360-17	7/13/15	Black tar seam sealer	Y <u>N</u>
<u>18</u>	360-18	7/13/15	Black tar seam sealer	Y N
<u>19</u>	360-19	7/13/15	Yellow carpet mastic	Y N
<u>20</u>	360-20	7/13/15	Yellow carpet mastic	Y N
<u>21</u>	360-21	7/13/15	Gray cove base/ mastic	Y N
<u>22</u>	360-22	7/13/15	Gray cove base/ mastic	Y N
<u>23</u>	360-23	7/13/15	Sponge pattern texture/ sheetrock	Y N
<u>24</u>	360-24	7/13/15	Sponge pattern texture/ sheetrock	Y N
<u>25</u>	360-25	7/13/15	Sponge pattern texture/ sheetrock	Y N
<u>26</u>	360-26	7/13/15	Knock-down pattern texture/ sheetrock	Y N
<u>27</u>	360-27	7/13/15	Knock-down pattern texture/ sheetrock	Y N
<u>28</u>	360-28	7/13/15	Knock-down pattern texture/ sheetrock	Y N
<u>29</u>	360-29	7/13/15	White leveling compound	Y N
<u>30</u>	360-30	7/13/15	White leveling compound	<u>Y</u> N

SPECIAL INSTRUCTIONS:

Sample Collector: (Print) Kevin McCrink (Signature) [Signature]

Relinquished by: [Signature] Date/Time: 7-20-15 Received by: Diana Federico Date/Time: 7/21/15

Relinquished by: Diana Federico Date/Time: 7/21/15 Received by: [Signature] Date/Time: 7/21/15

Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#:	158191
TAT:	
Rec'd:	

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019

CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

BILL TO: _____ (If Different Location)

Now Accepting: **VISA - MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required

****Additional charges for rush analysis (please call marketing department for pricing details)

****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #360, 7810 W. Luke Avenue, Spokane, WA

P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>31</u>	360-31	7/13/15	Sheetrock/ joint compound	<u>0</u> N
<u>32</u>	360-32	7/13/15	Sheetrock/ joint compound	Y N
<u>33</u>	360-33	7/13/15	Tan carpet mastic/ carpet	Y N
<u>34</u>	360-34	7/13/15	Tan carpet mastic	Y N
<u>35</u>	360-35	7/13/15	Green 9x9 floor tile/ black mastic	Y N
<u>36</u>	360-36	7/13/15	Green 9x9 floor tile/ black mastic	Y N
<u>37</u>	360-37	7/13/15	Black flooring paper	Y N
<u>38</u>	360-38	7/13/15	Black flooring paper	Y N
<u>39</u>	360-39	7/13/15	Green panel mastic	Y N
<u>40</u>	360-40	7/13/15	Green panel mastic	Y N
<u>41</u>	360-41	7/13/15	White 12x12 floor tile/ tan mastic	Y N
<u>42</u>	360-42	7/13/15	White 12x12 floor tile/ tan mastic	Y N
<u>43</u>	360-43	7/13/15	Gray 12x12 floor tile/ black mastic	Y N
<u>44</u>	360-44	7/13/15	Gray 12x12 floor tile/ black mastic	Y N
<u>45</u>	360-45	7/13/15	Sheetrock/ joint compound	<u>0</u> N

SPECIAL INSTRUCTIONS: _____

Sample Collector: (Print) Kevin McCrink (Signature) [Signature]

Relinquished by: [Signature] Date/Time: 7-20-15 Received by: Diana Federico Date/Time: 7/24/15

Relinquished by: Diana Federico Date/Time: 7/24/15 Received by: [Signature] Date/Time: 7/24/15

Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#:	158191
TAT:	
Rec'd:	

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019

CONTACT: Kevin McCrink

Phone/Fax: (509) 226-2523 /

Email: envriskmgm@aol.com

BILL TO: _____ (If Different Location)

Now Accepting: **VISA - MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #360, 7810 W. Luke Avenue, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
46	360-46	7/13/15	Brown cove base/ mastic	Y N
47	360-47	7/13/15	Brown cove base/ mastic	Y N
48	360-48	7/13/15	White sheet vinyl/ mastic/ sheet vinyl/ mastic	Y N
49	360-49	7/13/15	White sheet vinyl/ mastic/ sheet vinyl/ mastic	Y N
50	360-50	7/13/15	White cove base/ mastic	Y N
51	360-51	7/13/15	White cove base/ mastic	Y N
52	360-52	7/13/15	White 2x4 ceiling tile	Y N
53	360-53	7/13/15	White 2x4 ceiling tile	Y N
54	360-54	7/13/15	Sheetrock/ joint compound	Y N
55	360-55	7/13/15	Sheetrock/ joint compound	Y N
56	360-56	7/13/15	Carpet/ tan-black mastic	Y N
57	360-57	7/13/15	Carpet/ tan-black mastic	Y N
58	360-58	7/13/15	Black cove base/ mastic	Y N
59	360-59	7/13/15	Black cove base/ mastic	Y N
60	360-60	7/13/15	Sheetrock/ joint compound	Y N

SPECIAL INSTRUCTIONS: _____

Sample Collector: (Print) Kevin McCrink (Signature) [Signature]

Relinquished by: [Signature] Date/Time: 7-20-15 Received by: Diana Federico Date/Time: 7/21/15

Relinquished by: Diana Federico Date/Time: 7/21/15 Received by: [Signature] Date/Time: 7/21/15

Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB# :	158191
TAT :	
Rec' d :	

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019
 CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

BILL TO: _____

(If Different Location)

Now Accepting: **VISA – MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #360, 7810 W. Luke Avenue, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>61</u>	360-61	7/13/15	White-tan 12x12 ceiling tile	<u>Y</u> N
<u>62</u>	360-62	7/13/15	White-tan 12x12 ceiling tile	Y <u>N</u>
<u>63</u>	360-63	7/13/15	Black insulation/ tan-black backing paper	Y N
<u>64</u>	360-64	7/13/15	Black insulation/ tan-black backing paper	Y N
<u>65</u>	360-65	7/13/15	Gray cloth/ black tar on bollards	Y N
<u>66</u>	360-66	7/13/15	Gray cloth/ black tar on bollards	Y N
<u>67</u>	360-67	7/13/15	Chimney block/ mortar	Y N
<u>68</u>	360-68	7/13/15	Chimney block/ mortar	Y N
<u>69</u>	360-69	7/13/15	CMU block/ mortar	Y N
<u>70</u>	360-70	7/13/15	CMU block/ mortar	Y N
<u>71</u>	360-71	7/13/15	CMU block/ mortar	Y N
<u>72</u>	360-72	7/13/15	CMU block/ mortar	<u>Y</u> N
				Y N
				Y N
				Y N

SPECIAL INSTRUCTIONS: _____

Sample Collector: (Print) Kevin McCrink (Signature) [Signature]

Relinquished by: [Signature] Date/Time: 7-20-15 Received by: Diana Federico Date/Time: 7/21/15

Relinquished by: Diana Federico Date/Time: 7/21/15 Received by: [Signature] Date/Time: 7-21-15

Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158404

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/27/2015
Collected:	07/24/2015	Date Analyzed:	07/28/2015
Project Name:	SIA BLDG #365, 8120 W. LUKE AVE	Date Reported:	07/28/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158404-001 365-1		Window Glazing, White	No	None Detected	Carbonates Quartz Binder/Filler 100%
0158404-002 365-2		Window Glazing, White	No	None Detected	Cellulose Fiber Carbonates Quartz Binder/Filler 99%
0158404-003 365-3		Window Glazing, Gray/ Off White	No	None Detected	Cellulose Fiber Carbonates Quartz Binder/Filler 99%
0158404-004 365-4		Window Glazing, Gray/ Off White	No	None Detected	Cellulose Fiber Carbonates Quartz Binder/Filler 99%
0158404-005 365-5		Window Glazing, Gray/ Off White	Yes	Chrysotile 2%	Cellulose Fiber Carbonates Quartz Binder/Filler 97%
0158404-006 365-6		Window Glazing, Gray/ Off White	Yes	Chrysotile 3%	Carbonates Quartz Binder/Filler 97%
0158404-007 365-7		Window Glazing, Gray/ Off White	Yes	Chrysotile 3%	Cellulose Fiber Carbonates Quartz Binder/Filler 96%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158404

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/27/2015
Collected:	07/24/2015	Date Analyzed:	07/28/2015
Project Name:	SIA BLDG #365, 8120 W. LUKE AVE	Date Reported:	07/28/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158404-008 365-8		Window Glazing, Gray/ Off White	Yes	Chrysotile 3%	Cellulose Fiber <1% Carbonates Quartz Binder/Filler 96%
0158404-009 365-9		Window Glazing, White	No	None Detected	Carbonates Quartz Binder/Filler 100%
0158404-010 365-10		Window Glazing, White	No	None Detected	Carbonates Quartz Binder/Filler 100%
0158404-011 365-11		Tar Paper, Black	No	None Detected	Cellulose Fiber 60% Synthetic Fiber 5% Carbonates Gypsum Binder/Filler 35%
0158404-012 365-12		Tar Paper, Black	No	None Detected	Cellulose Fiber 65% Carbonates Gypsum Binder/Filler 35%
0158404-013 365-13		Tar Paper, Black	No	None Detected	Cellulose Fiber 60% Synthetic Fiber 5% Carbonates Gypsum Binder/Filler 35%
0158404-014 365-14		Tar Paper, Black	No	None Detected	Cellulose Fiber 65% Carbonates Gypsum Binder/Filler 35%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158404

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/27/2015
Collected:	07/24/2015	Date Analyzed:	07/28/2015
Project Name:	SIA BLDG #365, 8120 W. LUKE AVE	Date Reported:	07/28/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158404-015 365-15		Tar Paper Strip, Black	No	None Detected	Cellulose Fiber 60% Synthetic Fiber 5% Carbonates Gypsum Binder/Filler 35%
0158404-016 365-16		Tar Paper Strip, Black	No	None Detected	Cellulose Fiber 60% Synthetic Fiber 5% Carbonates Gypsum Binder/Filler 35%
0158404-017 365-1-1		Window Glazing, Gray	No	None Detected	Cellulose Fiber <1% Carbonates Quartz Binder/Filler 99%
0158404-018 365-1-2		Window Glazing, Gray	No	None Detected	Cellulose Fiber <1% Carbonates Quartz Binder/Filler 99%
0158404-019 365-1-3		Window Glazing, Gray	No	None Detected	Carbonates Quartz Binder/Filler 100%
0158404-020 365-1-4		Window Glazing, Gray/ Off White	Yes	Chrysotile 3%	Carbonates Quartz Binder/Filler 97%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158404

Bulk Asbestos Analysis by Polarized Light Microscopy


NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231	Date Received:	07/27/2015
	LIBERTY LAKE, WA 99019	Date Analyzed:	07/28/2015
Collected:	07/24/2015	Date Reported:	07/28/2015
Project Name:	SIA BLDG #365, 8120 W. LUKE AVE	EPA Method:	EPA 600/R-93/116
Address:	SPOKANE, WA	Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158404-021 365-2-1		LAYER 1 Sheet Vinyl, Brown/ Black	No	None Detected	Cellulose Fiber Synthetic Fiber Carbonates Gypsum Quartz Binder/Filler	15% 5% 80%
		LAYER 2 Mastic, Black	Yes	Chrysotile 4%	Cellulose Fiber Carbonates Gypsum Binder/Filler	2% 94%
0158404-022 365-2-2		LAYER 1 Sheet Vinyl, Brown/ Black	No	None Detected	Cellulose Fiber Synthetic Fiber Carbonates Gypsum Quartz Binder/Filler	15% 5% 80%
		LAYER 2 Mastic, Black	Yes	Chrysotile 5%	Carbonates Gypsum Quartz Binder/Filler	 95%



Analyst - Kurt Kettler



Signatory - Lab Manager - Ken Scheske

Distinctly stratified, easily separable layers of samples are analyzed as subsamples of the whole and are reported separately for each discernible layer. All analyses are derived from calibrated visual estimate and measured in area percent unless otherwise noted. The report applies to the standards or procedures identified and to the sample(s) tested. The test results are not necessarily indicative or representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products, nor do they represent an ongoing quality assurance program unless so noted. These reports are for the exclusive use of the addressed client and that they will not be reproduced wholly or in part for advertising or other purposes over our signature or in connection with our name without special written permission. The report shall not be reproduced except in full, without written approval by our laboratory. The samples not destroyed in testing are retained a maximum of thirty days. The laboratory measurement of uncertainty for the test method is approximately less than 1 by area percent. Accredited by the National Institute of Standards and Technology, Voluntary Laboratory Accreditation Program for selected test method for asbestos. The accreditation or any reports generated by this laboratory in no way constitutes or implies product certification, approval, or endorsement by the National Institute of Standards and Technology. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. Polarized Light Microscopy may not be consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#: 158404
 TAT: 1 day
 Rec'd: JUL 28 PM

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019
 CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

BILL TO: _____ (If Different Location)

Now Accepting: **VISA - MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required

****Additional charges for rush analysis (please call marketing department for pricing details)

****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]

(If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #365, 8120 W. Luke Avenue, Spokane, WA

P.O. Number: _____ Project Number: ERM-15-130

22

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>1</u>	365-1	7/24/15	Window glazing	<u>Y</u> N
<u>2</u>	365-2	7/24/15	Window glazing	Y <u>N</u>
<u>3</u>	365-3	7/24/15	Window glazing	Y N
<u>4</u>	365-4	7/24/15	Window glazing	Y N
<u>5</u>	365-5	7/24/15	Window glazing	Y N
<u>6</u>	365-6	7/24/15	Window glazing	Y N
<u>7</u>	365-7	7/24/15	Window glazing	Y N
<u>8</u>	365-8	7/24/15	Window glazing	Y N
<u>9</u>	365-9	7/24/15	Window glazing	Y N
<u>10</u>	365-10	7/24/15	Window glazing	Y N
<u>11</u>	365-11	7/24/15	Black tar paper	Y N
<u>12</u>	365-12	7/24/15	Black tar paper	Y N
<u>13</u>	365-13	7/24/15	Black tar paper	Y N
<u>14</u>	365-14	7/24/15	Black tar paper	Y N
<u>15</u>	365-15	7/24/15	Black tar paper strip	<u>Y</u> N

SPECIAL INSTRUCTIONS:

Sample Collector: (Print) Kevin McCrink

(Signature) [Signature]

Relinquished by: [Signature] Date/Time: 7-25-15 Received by: Diana Federico Date/Time: 7/27/15

Relinquished by: Diana Federico Date/Time: 7/27/15 Received by: [Signature] Date/Time: 7/27/15

Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#:	
TAT:	158404
Rec'd:	

COMPANY NAME: Environmental Risk Mgmt BILL TO: _____ (If Different Location)

1324 Liberty Lake Rd, 231

Liberty Lake, WA 99019

CONTACT: Kevin McCrink

Phone/Fax: (509) 226-2523 /

Email: envriskmgm@aol.com

Now Accepting: **VISA - MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required

****Additional charges for rush analysis (please call marketing department for pricing details)

****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #365, 8120 W. Luke Avenue, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>16</u>	365-16	7/24/15	Black tar paper strip	<u>Y</u> N
<u>17</u>	365-1-1	7/24/15	Window glazing	Y <u>N</u>
<u>18</u>	365-1-2	7/24/15	Window glazing	Y N
<u>19</u>	365-1-3	7/24/15	Window glazing	Y N
<u>20</u>	365-1-4	7/24/15	Window glazing	Y N
<u>21</u>	365-2-1	7/24/15	Brown sheet vinyl/ black mastic	Y N
<u>22</u>	365-2-2	7/24/15	Brown sheet vinyl/ black mastic	<u>Y</u> N
				Y N
				Y N
				Y N
				Y N
				Y N
				Y N
				Y N
				Y N

SPECIAL INSTRUCTIONS: _____

Sample Collector: (Print) Kevin McCrink (Signature) [Signature]

Relinquished by: [Signature] Date/Time: 7/25/15 Received by: Diana Federico Date/Time: 7/27/15

Relinquished by: Diana Federico Date/Time: 7/27/15 Received by: [Signature] Date/Time: 7/27/15

Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

*** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158242

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/22/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/21/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158242-001 1378-1		LAYER 1 Sheetrock, Off White/ Brown	No	None Detected	Cellulose Fiber Gypsum Carbonates Mica Quartz	10% 90%
		LAYER 2 Joint Compound, White/ Off White	Yes	Chrysotile 2%	Cellulose Fiber Carbonates Mica Quartz Binder/Filler	1% 97%
		LAYER 3 Sheetrock, Joint Compound Composite, Off White/ Brown/ White Note: COMPOSITE ANALYSIS REQUESTED	Yes	Chrysotile <1%	Cellulose Fiber Gypsum Carbonates Mica Quartz Binder/Filler	9% 90%
0158242-002 1378-2		LAYER 1 Carpet, Green	No	None Detected	Synthetic Fiber Carbonates Binder/Filler	80% 20%
		LAYER 2 Mastic, Tan	No	None Detected	Synthetic Fiber Carbonates Binder/Filler	2% 98%
		LAYER 3 Sheet Vinyl, Brown	No	None Detected	Cellulose Fiber Carbonates Quartz Binder/Filler	10% 90%
		LAYER 4 Mastic, Brown Note: Difficult to separate adjacent layer	No	None Detected	Cellulose Fiber Carbonates Binder/Filler	7% 93%
0158242-003 1378-3		Mastic, Brown	No	None Detected	Cellulose Fiber Quartz Binder/Filler	5% 95%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158242

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/22/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/21/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158242-004 1378-4		Flooring Paper, Black	No	None Detected	Cellulose Fiber Quartz Binder/Filler	40% 60%
0158242-005 1378-5		Mastic, Black	No	None Detected	Cellulose Fiber Gypsum Binder/Filler	3% 97%
0158242-006 1378-6		LAYER 1 Cove Base, Black	No	None Detected	Carbonates Binder/Filler	100%
		LAYER 2 Mastic, White	No	None Detected	Cellulose Fiber Quartz Carbonates Binder/Filler	1% 99%
0158242-007 1378-7		LAYER 1 Sheet Vinyl, Brown/Gray/Black Mosaic Patter	No	None Detected	Cellulose Fiber Synthetic Fiber Fibrous Glass Wollastonite Carbonates Gypsum Binder/Filler	10% 5% 3% 2% 80%
		LAYER 2 Mastic, Beige Note: Difficult to separate adjacent layer	No	None Detected	Cellulose Fiber Synthetic Fiber Carbonates Binder/Filler	3% 1% 96%
0158242-008 1378-8		LAYER 1 Sheet Vinyl, Brown/Gray/Black Mosaic Patter	No	None Detected	Cellulose Fiber Synthetic Fiber Fibrous Glass Wollastonite Carbonates Gypsum Binder/Filler	10% 5% 3% 2% 80%
		LAYER 2 Mastic, Beige Note: Difficult to separate adjacent layer	No	None Detected	Cellulose Fiber Fibrous Glass Carbonates Binder/Filler	4% 1% 95%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158242

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/22/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/21/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158242-009 1378-9		Paint, Gray	No	None Detected	Cellulose Fiber Carbonates Quartz Binder/Filler	<1% 99%
0158242-010 1378-10		Paint, Gray	No	None Detected	Cellulose Fiber Carbonates Quartz Binder/Filler	2% 98%
0158242-011 1378-11		2x4 Ceiling Tile, White/ Beige Note: Worm Hole Pattern	No	None Detected	Cellulose Fiber Carbonates Perlite Binder/Filler	85% 15%
0158242-012 1378-12		Sheetrock, Off White/ Brown	No	None Detected	Cellulose Fiber Fibrous Glass Gypsum Carbonates Mica Quartz Binder/Filler	10% 2% 88%
0158242-013 1378-13		Blown-in Insulation, Gray	No	None Detected	Cellulose Fiber Carbonates Gypsum	97% 3%
0158242-014 1378-14		LAYER 1 Carpet Mastic, Tan	No	None Detected	Synthetic Fiber Carbonates Binder/Filler	3% 97%
		LAYER 2 Leveling Compound, White Note: Difficult to separate adjacent layer	No	None Detected	Cellulose Fiber Gypsum Carbonates Mica	<1% 99%
		LAYER 3 Mastic, Black	Yes	Chrysotile 2%	Cellulose Fiber Synthetic Fiber Carbonates Binder/Filler	2% <1% 95%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158242

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/22/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/21/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158242-015 1378-15		LAYER 1 Leveling Compound, White Note: Difficult to separate adjacent layer	No	None Detected	Synthetic Fiber	<1%
		LAYER 2 Mastic, Black	Yes	Chrysotile 3%	Gypsum Carbonates Quartz	99%
					Cellulose Fiber	2%
					Carbonates Quartz Binder/Filler	95%
0158242-016 1378-16		Mastic, Black	No	None Detected	Cellulose Fiber	10%
					Carbonates Binder/Filler	90%
0158242-017 1378-17		LAYER 1 Splatter Texture, Off White	No	None Detected	Carbonates Mica Quartz Binder/Filler	100%
		LAYER 2 Sheetrock, Off White/ Brown	No	None Detected	Cellulose Fiber	10%
					Gypsum Carbonates Mica Quartz	90%
0158242-018 1378-18		LAYER 1 Splatter Texture, Off White	No	None Detected	Carbonates Mica Quartz Binder/Filler	100%
		LAYER 2 Sheetrock, Off White/ Brown	No	None Detected	Cellulose Fiber	10%
					Gypsum Carbonates Mica Quartz	90%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158242

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/22/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/21/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158242-019 1378-19		LAYER 1 Splatter Texture, Off White	No	None Detected	Cellulose Fiber <1% Carbonates Mica Quartz Binder/Filler 99%
		LAYER 2 Sheetrock, Off White/ Brown	No	None Detected	Cellulose Fiber 10% Gypsum Carbonates Mica Quartz 90%
0158242-020 1378-20		LAYER 1 9x9 Floor Tile, Brown	Yes	Chrysotile 10%	Carbonates Quartz Binder/Filler 90%
		LAYER 2 Mastic, Black Note: Difficult to separate adjacent layer	Yes	Chrysotile 2%	Cellulose Fiber 3% Carbonates Binder/Filler 95%
0158242-021 1378-21		LAYER 1 9x9 Floor Tile, Tan	Yes	Chrysotile 10%	Carbonates Quartz Binder/Filler 90%
		LAYER 2 Mastic, Black Note: Difficult to separate adjacent layer	Yes	Chrysotile 2%	Cellulose Fiber 8% Carbonates Binder/Filler 90%
0158242-022 1378-22		LAYER 1 Splatter Texture, Off White	No	None Detected	Carbonates Mica Quartz Binder/Filler 100%
		LAYER 2 Sheetrock, Off White/ Brown	No	None Detected	Cellulose Fiber 10% Gypsum Carbonates Mica Quartz 90%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158242

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/22/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/21/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158242-023 1378-23		LAYER 1 Sheetrock, Off White/ Brown	No	None Detected	Cellulose Fiber	10%
		LAYER 2 Joint Compound, White/ Off White	Yes	Chrysotile 3%	Gypsum Carbonates Mica Quartz	90%
		LAYER 3 Sheetrock, Joint Compound Composite, Off White/ Brown/ White Note: COMPOSITE ANALYSIS REQUESTED	Yes	Chrysotile <1%	Carbonates Mica Quartz Binder/Filler	97%
0158242-024 1378-24		LAYER 1 Carpet Mastic, Tan	No	None Detected	Cellulose Fiber	9%
		LAYER 2 9x9 Floor Tile, Red	Yes	Chrysotile 10%	Gypsum Carbonates Mica Quartz Binder/Filler	90%
		LAYER 3 Mastic, Black Note: Difficult to separate adjacent layer	Yes	Chrysotile 3%	Synthetic Fiber Quartz Carbonates Binder/Filler	2%
0158242-025 1378-25		2x4 Ceiling Tile, White/ Beige Note: Worm Hole Pattern	No	None Detected	Cellulose Fiber	85%
					Carbonates Perlite Binder/Filler	15%
0158242-026 1378-26		Blown-in Insulation, Gray	No	None Detected	Cellulose Fiber	95%
					Gypsum Binder/Filler	5%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158242

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/22/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/21/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158242-027 1378-27		LAYER 1 Sheetrock, Off White/ Brown	No	None Detected	Cellulose Fiber Gypsum Carbonates Mica Quartz	10% 90%
		LAYER 2 Joint Compound, White	Yes	Chrysotile 2%	Cellulose Fiber Carbonates Mica Quartz Binder/Filler	1% 97%
		LAYER 3 Sheetrock, Joint Compound Composite, Off White/ Brown/ White Note: COMPOSITE ANALYSIS REQUESTED	Yes	Chrysotile <1%	Cellulose Fiber Gypsum Carbonates Mica Quartz Binder/Filler	9% 90%
0158242-028 1378-28		2x4 Ceiling Tile, White/ Beige Note: Worm Hole Pattern	No	None Detected	Cellulose Fiber Carbonates Perlite Binder/Filler	85% 15%
0158242-029 1378-29		LAYER 1 Carpet, Black/ Brown	No	None Detected	Synthetic Fiber Carbonates Binder/Filler	85% 15%
		LAYER 2 Mastic, Tan	No	None Detected	Cellulose Fiber Carbonates Binder/Filler	5% 95%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158242

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/22/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/21/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158242-030 1378-30		LAYER 1 Carpet Mastic, Tan	No	None Detected	Synthetic Fiber	1%
		LAYER 2 9"x9" Floor Tile, Red	Yes	Chrysotile 10%	Quartz Carbonates Binder/Filler	99%
		LAYER 3 Mastic, Black	Yes	Chrysotile 3%	Carbonates Quartz Binder/Filler	90%
					Cellulose Fiber	2%
					Carbonates Quartz Binder/Filler	95%
0158242-031 1378-31		LAYER 1 Cove Base, Gray	No	None Detected	Carbonates Quartz Binder/Filler	100%
		LAYER 2 Mastic, White/ Yellow	No	None Detected	Cellulose Fiber	2%
					Carbonates Binder/Filler	98%
0158242-032 1378-32		LAYER 1 Cove Base, Gray	No	None Detected	Carbonates Binder/Filler	100%
		LAYER 2 Mastic, White/ Yellow	No	None Detected	Cellulose Fiber	1%
					Quartz Gypsum Binder/Filler	99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158242

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/22/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/21/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158242-033 1378-33		LAYER 1 Sheetrock, Beige/ Brown	No	None Detected	Cellulose Fiber	10%
		LAYER 2 Joint Compound, White/ Off White	Yes	Chrysotile 2%	Gypsum Carbonates Mica Quartz	90%
		LAYER 3 Sheetrock, Joint Compound Composite, Beige/ Brown/ White/ Off White Note: COMPOSITE ANALYSIS REQUESTED	Yes	Chrysotile <1%	Cellulose Fiber Gypsum Carbonates Mica Quartz Binder/Filler	97%
0158242-034 1378-34		LAYER 1 Carpet Mastic, Tan	No	None Detected	Cellulose Fiber	9%
		LAYER 2 9"x9" Floor Tile, Red	Yes	Chrysotile 10%	Carbonates Quartz Binder/Filler	90%
		LAYER 3 Mastic, Black	Yes	Chrysotile 4%	Synthetic Fiber Carbonates Quartz Binder/Filler	<1%
0158242-035 1378-35		LAYER 1 Cove Base, Medium Green	No	None Detected	Cellulose Fiber	1%
		LAYER 2 Mastic, White	No	None Detected	Carbonates Quartz Binder/Filler	95%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158242

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/22/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/21/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158242-036 1378-36		LAYER 1 Cove Base, Medium Green	No	None Detected	Carbonates Binder/Filler 100%
		LAYER 2 Mastic, White/ Yellow	No	None Detected	Cellulose Fiber 1% Carbonates Perlite Binder/Filler 99%
0158242-037 1378-37		2x4 Ceiling Tile, White/ Beige Note: Worm Hole Pattern	No	None Detected	Cellulose Fiber 40% Fibrous Glass 40% Carbonates Perlite Binder/Filler 20%
0158242-038 1378-38		Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber 12% Gypsum Carbonates Mica Quartz Binder/Filler 88%
0158242-039 1378-39		Blown-in Insulation, Gray	No	None Detected	Cellulose Fiber 95% Gypsum Carbonates Binder/Filler 5%
0158242-040 1378-40		Fiber Board, Brown	No	None Detected	Cellulose Fiber 95% Gypsum Binder/Filler 5%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158242

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/22/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/21/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158242-041 1378-41		LAYER 1 Sheetrock, Beige	No	None Detected	Cellulose Fiber Fibrous Glass Gypsum Carbonates Mica	10% 2% 88%
		LAYER 2 Joint Compound, White	No	None Detected	Carbonates Mica Quartz Binder/Filler	100%
0158242-042 1378-42		LAYER 1 Carpet Mastic, Tan	No	None Detected	Cellulose Fiber Carbonates Quartz Binder/Filler	2% 98%
		LAYER 2 9"x9" Floor Tile, Red	Yes	Chrysotile 8%	Carbonates Quartz Binder/Filler	92%
		LAYER 3 Mastic, Black	Yes	Chrysotile 3%	Cellulose Fiber Carbonates Binder/Filler	1% 96%
0158242-043 1378-43		2x4 Ceiling Tile, White/ Beige Note: Worm Hole Pattern	No	None Detected	Cellulose Fiber Mineral Wool Carbonates Perlite Binder/Filler	80% 5% 15%
0158242-044 1378-44		12"x12" Ceiling Tile, White/ Beige Note: Pencil Hole Pattern	No	None Detected	Mineral Wool Cellulose Fiber Carbonates Perlite Binder/Filler	60% 20% 20%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158242

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/22/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/21/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158242-045 1378-45		12"x12" Ceiling Tile, White/ Beige Note: Pencil Hole Pattern	No	None Detected	Mineral Wool 60% Cellulose Fiber 20% Carbonates Perlite Binder/Filler 20%
0158242-046 1378-46		LAYER 1 Ceiling Tile Mastic, Brown	No	None Detected	Gypsum Quartz Binder/Filler 100%
		LAYER 2 Ceiling Tile, White/ Beige	No	None Detected	Mineral Wool 50% Cellulose Fiber 35% Carbonates Perlite Binder/Filler 15%
0158242-047 1378-47		LAYER 1 Ceiling Tile Mastic, Brown	No	None Detected	Gypsum Quartz Binder/Filler 100%
		LAYER 2 Ceiling Tile, White/ Beige	No	None Detected	Mineral Wool 50% Cellulose Fiber 35% Carbonates Perlite Binder/Filler 15%
0158242-048 1378-48		Sheetrock, White/ Lt. Brown	No	None Detected	Cellulose Fiber 12% Gypsum Carbonates Mica Quartz Binder/Filler 88%
0158242-049 1378-49		Blown-in Insulation, Gray/ Beige Note: No Cove Base Present	No	None Detected	Cellulose Fiber 95% Carbonates Binder/Filler 5%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158242

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/22/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/21/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158242-050 1378-50		LAYER 1 Sheetrock, Beige	No	None Detected	Cellulose Fiber Fibrous Glass Gypsum Carbonates Mica	10% 2% 88%
		LAYER 2 Joint Compound, White/ Off White	No	None Detected	Cellulose Fiber Carbonates Mica Quartz Binder/Filler	<1% 99%
0158242-051 1378-51		LAYER 1 Sheetrock, Beige	No	None Detected	Cellulose Fiber Fibrous Glass Gypsum Carbonates Mica	10% 2% 88%
		LAYER 2 Joint Compound, White/ Off White	No	None Detected	Carbonates Mica Quartz Binder/Filler	 100%
0158242-052 1378-52		LAYER 1 Sheet Vinyl, Tan	No	None Detected	Cellulose Fiber Carbonates Quartz Binder/Filler	5% 95%
		LAYER 2 Mastic, Gray Note: Difficult to separate adjacent layer	Yes	Chrysotile 1%	Cellulose Fiber Carbonates Quartz Binder/Filler	2% 97%
		LAYER 3 9"x9" Floor Tile, Red	Yes	Chrysotile 15%	Carbonates Quartz Binder/Filler	 85%
		LAYER 4 Mastic, Black	Yes	Chrysotile 3%	Cellulose Fiber Carbonates Binder/Filler	1% 96%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158242

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/22/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/21/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158242-053 1378-53		LAYER 1 Sheet Vinyl, Tan	No	None Detected	Carbonates Quartz Binder/Filler	100%
		LAYER 2 Mastic, Gray Note: Difficult to separate adjacent layer	Yes	Chrysotile 2%	Cellulose Fiber Carbonates Quartz Binder/Filler	<1% 97%
		LAYER 3 9"x9" Floor Tile, Red	Yes	Chrysotile 15%	Carbonates Quartz Binder/Filler	85%
		LAYER 4 Mastic, Black Note: Difficult to separate adjacent layer	Yes	Chrysotile 2%	Carbonates Binder/Filler	98%
0158242-054 1378-54		Mastic, Black	Yes	Chrysotile 3%	Cellulose Fiber Carbonates Gypsum Binder/Filler	7% 90%
0158242-055 1378-55		Mastic, Black	No	None Detected	Cellulose Fiber Carbonates Binder/Filler	3% 97%
0158242-056 1378-56		Epoxy Flooring, Yellow	No	None Detected	Gypsum Quartz Binder/Filler	100%
0158242-057 1378-57		Epoxy Flooring, Yellow	No	None Detected	Gypsum Quartz Binder/Filler	100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158242

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/22/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/21/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158242-058 1378-58		LAYER 1 12"x12" Floor Tile, Off White	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Yellow	No	None Detected	Cellulose Fiber 1% Carbonates Gypsum Quartz Binder/Filler 99%
		LAYER 3 9"x9" Floor Tile, Red	Yes	Chrysotile 8%	Carbonates Quartz Binder/Filler 92%
		LAYER 4 Mastic, Black	Yes	Chrysotile 3%	Cellulose Fiber 4% Carbonates Gypsum Quartz Binder/Filler 93%
0158242-059 1378-59		LAYER 1 12"x12" Floor Tile, Off White	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Yellow	No	None Detected	Cellulose Fiber <1% Carbonates Gypsum Quartz Binder/Filler 99%
		LAYER 3 9"x9" Floor Tile, Red	Yes	Chrysotile 8%	Carbonates Quartz Binder/Filler 92%
		LAYER 4 Mastic, Black	Yes	Chrysotile 2%	Cellulose Fiber <1% Carbonates Gypsum Quartz Binder/Filler 97%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158242

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/22/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/21/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158242-060 1378-60		HVAC Duct Tape, Gray	No	None Detected	Synthetic Fiber Carbonates Quartz Binder/Filler	70% 30%
0158242-061 1378-61		HVAC Duct Tape, Gray	No	None Detected	Synthetic Fiber Carbonates Quartz Binder/Filler	70% 30%
0158242-062 1378-62		FRP Panel, Lt. Yellow	No	None Detected	Fibrous Glass Carbonates Quartz Binder/Filler	30% 70%
0158242-063 1378-63		FRP Panel, Lt. Yellow	No	None Detected	Fibrous Glass Carbonates Quartz Binder/Filler	30% 70%
0158242-064 1378-64		Foam Insulation, Yellow	No	None Detected	Foam	100%
0158242-065 1378-65		Foam Insulation, Yellow	No	None Detected	Foam	100%
0158242-066 1378-66		Door Seam Sealer, Gray	No	None Detected	Carbonates Quartz Binder/Filler	100%
0158242-067 1378-67		Door Seam Sealer, Gray	No	None Detected	Carbonates Gypsum Quartz Binder/Filler	100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158242

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/22/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/24/2015
Collected: 07/21/2015 Date Reported: 07/24/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158242-068 1378-68		LAYER 1 Fiberglass Ceiling Tile, White/ Yellow	No	None Detected	Fibrous Glass 95% Carbonates Binder/Filler 5%
		LAYER 2 Mastic, Brown	No	None Detected	Fibrous Glass 1% Cellulose Fiber <1% Carbonates Gypsum Quartz Binder/Filler 98%
0158242-069 1378-69		LAYER 1 Fiberglass Ceiling Tile, White/ Yellow	No	None Detected	Fibrous Glass 95% Carbonates Binder/Filler 5%
		LAYER 2 Mastic, Brown	No	None Detected	Fibrous Glass 3% Carbonates Gypsum Quartz Binder/Filler 97%


Analyst - Johann Hofer


Signatory - Lab Director - Kurt Kettler

Distinctly stratified, easily separable layers of samples are analyzed as subsamples of the whole and are reported separately for each discernible layer. All analyses are derived from calibrated visual estimate and measured in area percent unless otherwise noted. The report applies to the standards or procedures identified and to the sample(s) tested. The test results are not necessarily indicative or representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products, nor do they represent an ongoing quality assurance program unless so noted. These reports are for the exclusive use of the addressed client and that they will not be reproduced wholly or in part for advertising or other purposes over our signature or in connection with our name without special written permission. The report shall not be reproduced except in full, without written approval by our laboratory. The samples not destroyed in testing are retained a maximum of thirty days. The laboratory measurement of uncertainty for the test method is approximately less than 1 by area percent. Accredited by the National Institute of Standards and Technology, Voluntary Laboratory Accreditation Program for selected test method for asbestos. The accreditation or any reports generated by this laboratory in no way constitutes or implies product certification, approval, or endorsement by the National Institute of Standards and Technology. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. Polarized Light Microscopy may not be consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#: 158242
 TAT: 2 days
 Rec'd: JUL 22 P.M.
 EMC USE ONLY

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019
 CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

BILL TO: _____ (If Different Location)

Now Accepting: **VISA - MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. 1378, 3707 Godfrey Boulevard, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>1</u>	1378-1	7/21/15	Shetrock/ joint compound	<u>Y</u> N
<u>2</u>	1378-2	7/21/15	Carpet/ tan mastic/ medium brown sheet vinyl/ mastic	Y <u>N</u>
<u>3</u>	1378-3	7/21/15	Mastic on wood	Y N
<u>4</u>	1378-4	7/21/15	Black flooring paper	Y N
<u>5</u>	1378-5	7/21/15	Black mastic on wood	Y N
<u>6</u>	1378-6	7/21/15	Black cove base/ white mastic	Y N
<u>7</u>	1378-7	7/21/15	Brown-gray-black mosaic pattern sheet vinyl/ beige mastic	Y N
<u>8</u>	1378-8	7/21/15	Brown-gray-black mosaic pattern sheet vinyl/ beige mastic	Y N
<u>9</u>	1378-9	7/21/15	Gray paint on wood	Y N
<u>10</u>	1378-10	7/21/15	Gray paint on wood	Y N
<u>11</u>	1378-11	7/21/15	White 2x4 ceiling tile (worm hole pattern)	Y N
<u>12</u>	1378-12	7/21/15	Shetrock	Y N
<u>13</u>	1378-13	7/21/15	Gray blown-in insulation	Y N
<u>14</u>	1378-14	7/21/15	Tan carpet mastic/ white leveling compound/ black mastic	Y N
<u>15</u>	1378-15	7/21/15	White leveling compound/ black mastic	Y N

SPECIAL INSTRUCTIONS:

Sample Collector: (Print) Kevin McCrink (Signature) [Signature]
 Relinquished by: [Signature] Date/Time: 7/21/15 Received by: Diana Federico Date/Time: 7/22/15
 Relinquished by: Diana Federico Date/Time: 7/22/15 Received by: [Signature] Date/Time: 8-22-15
 Relinquished by: _____ Date/Time _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#:	
TAT:	158242
Rec'd:	
EMC USE ONLY	

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019
 CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgt@aol.com

BILL TO: _____ (If Different Location)

Now Accepting: **VISA – MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required

****Additional charges for rush analysis (please call marketing department for pricing details)

****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]

(If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. 1378, 3707 Godfrey Boulevard, Spokane, WA

P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
16	1378-16	7/21/15	Black mastic on wood	Y N
17	1378-17	7/21/15	Splatter texture/ sheetrock	Y N
18	1378-18	7/21/15	Splatter texture/ sheetrock	Y N
19	1378-19	7/21/15	Splatter texture/ sheetrock	Y N
20	1378-20	7/21/15	Brown 9x9 floor tile/ black mastic	Y N
21	1378-21	7/21/15	Tan 9x9 floor tile/ black mastic	Y N
22	1378-22	7/21/15	Splatter texture/ sheetrock	Y N
23	1378-23	7/21/15	Sheetrock/ joint compound	Y N
24	1378-24	7/21/15	Tan carpet mastic/ red 9x9 floor tile/ black mastic	Y N
25	1378-25	7/21/15	White 2x4 ceiling tile (worm hole pattern)	Y N
26	1378-26	7/21/15	Gray blown-in insulation	Y N
27	1378-27	7/21/15	Sheetrock/ joint compound	Y N
28	1378-28	7/21/15	White 2x4 ceiling tile (worm hole pattern)	Y N
29	1378-29	7/21/15	Carpet/ tan mastic	Y N
30	1378-30	7/21/15	Tan carpet mastic/ red 9x9 floor tile/ black mastic	Y N

SPECIAL INSTRUCTIONS:

Sample Collector: (Print) Kevin McCrink

(Signature) [Signature]

Relinquished by: [Signature] Date/Time: 7/21/15 Received by: Diana Federica Date/Time: 7/22/15

Relinquished by: Diana Federica Date/Time: 7/22/15 Received by: [Signature] Date/Time: 7-22-15

Relinquished by: _____ Date/Time _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#:	
TAT:	158242
Rec'd:	
EMC USE ONLY	

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019
 CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

BILL TO: _____ (If Different Location)

Now Accepting: **VISA – MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. 1378, 3707 Godfrey Boulevard, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
31	1378-31	7/21/15	Gray cove base/ white mastic	N
32	1378-32	7/21/15	Gray cove base/ white mastic	Y N
33	1378-33	7/21/15	Sheetrock/ joint compound	Y N
34	1378-34	7/21/15	Tan carpet mastic/ red 9x9 floor tile/ black mastic	Y N
35	1378-35	7/21/15	Medium green cove base/ mastic	Y N
36	1378-36	7/21/15	Medium green cove base/ mastic	Y N
37	1378-37	7/21/15	White 2x4 ceiling tile (worm hole pattern)	Y N
38	1378-38	7/21/15	Sheetrock	Y N
39	1378-39	7/21/15	Gray blown-in insulation	Y N
40	1378-40	7/21/15	Tan fiberboard	Y N
41	1378-41	7/21/15	Sheetrock/ joint compound	Y N
42	1378-42	7/21/15	Tan carpet mastic/ red 9x9 floor tile/ black mastic	Y N
43	1378-43	7/21/15	White 2x4 ceiling tile (worm hole pattern)	Y N
44	1378-44	7/21/15	White 12x12 ceiling tile (pencil hole pattern)	Y N
45	1378-45	7/21/15	White 12x12 ceiling tile (pencil hole pattern)	Y N

SPECIAL INSTRUCTIONS:

Sample Collector: (Print) Kevin McCrink (Signature) [Signature]
 Relinquished by: [Signature] Date/Time: 7/21/15 Received by: Diana Federico Date/Time: 7/22/15
 Relinquished by: Diana Federico Date/Time: 7/22/15 Received by: [Signature] Date/Time: 7-22-15
 Relinquished by: _____ Date/Time _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#:	
TAT:	158242
Rec'd:	
EMC USE ONLY	

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019
 CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

BILL TO: _____ (If Different Location)

Now Accepting: **VISA – MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. 1378, 3707 Godfrey Boulevard, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
46	1378-46	7/21/15	Brown ceiling tile mastic	Y N
47	1378-47	7/21/15	Brown ceiling tile mastic	Y N
48	1378-48	7/21/15	Sheetrock	Y N
49	1378-49	7/21/15	Gray cove base/ white mastic	Y N
50	1378-50	7/21/15	Sheetrock/ joint compound	Y N
51	1378-51	7/21/15	Sheetrock/ joint compound	Y N
52	1378-52	7/21/15	Tan sheet vinyl/ mastic/ red 9x9 floor tile/ black mastic	Y N
53	1378-53	7/21/15	Tan sheet vinyl/ mastic/ red 9x9 floor tile/ black mastic	Y N
54	1378-54	7/21/15	Black mastic on wood	Y N
55	1378-55	7/21/15	Black mastic on wood	Y N
56	1378-56	7/21/15	Yellow epoxy flooring	Y N
57	1378-57	7/21/15	Yellow epoxy flooring	Y N
58	1378-58	7/21/15	Off-white 12x12 floor tile/ mastic/ red 9x9 floor tile/ black mastic	Y N
59	1378-59	7/21/15	Off-white 12x12 floor tile/ mastic/ red 9x9 floor tile/ black mastic	Y N
60	1378-60	7/21/15	Gray HVAC duct tape	Y N

SPECIAL INSTRUCTIONS: _____
 Sample Collector: (Print) Kevin McCrink (Signature) [Signature]
 Relinquished by: [Signature] Date/Time: 7/21/15 Received by: Diana Federico Date/Time: 7/22/15
 Relinquished by: Diana Federico Date/Time: 7/22/15 Received by: [Signature] Date/Time: 7-22-15
 Relinquished by: _____ Date/Time _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#:	
TAT:	158242
Rec'd:	EMC USE ONLY

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019
 CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

BILL TO: _____ (If Different Location)

Now Accepting: **VISA - MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. 1378, 3707 Godfrey Boulevard, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
61	1378-61	7/21/15	Gray HVAC duct tape	<input checked="" type="checkbox"/> N
62	1378-62	7/21/15	Light yellow FRP panel	Y N
63	1378-63	7/21/15	Light yellow FRP panel	Y N
64	1378-64	7/21/15	Yellow foam insulation	Y N
65	1378-65	7/21/15	Yellow foam insulation	Y N
66	1378-66	7/21/15	Gray door seam sealer	Y N
67	1378-67	7/21/15	Gray door seam sealer	Y N
68	1378-68	7/21/15	White-yellow fiberglass ceiling tile/ brown mastic	Y N
69	1378-69	7/21/15	White-yellow fiberglass ceiling tile/ brown mastic	<input checked="" type="checkbox"/> N
				Y N
				Y N
				Y N
				Y N
				Y N
				Y N

SPECIAL INSTRUCTIONS:

Sample Collector: (Print) Kevin McCrink (Signature) [Signature]
 Relinquished by: [Signature] Date/Time: 7/21/15 Received by: Diana Federico Date/Time: 7/22/15
 Relinquished by: Diana Federico Date/Time: 7/22/15 Received by: [Signature] Date/Time: 7-22-15
 Relinquished by: _____ Date/Time _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158403

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/27/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/28/2015
Collected: 07/22/2015 Date Reported: 07/28/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158403-001 1378-70		LAYER 1 Roof Shingle, Brown	No	None Detected	Fibrous Glass	15%
					Quartz Carbonates Binder/Filler	85%
		LAYER 2 Roof Shingle, Black	No	None Detected	Fibrous Glass	15%
					Quartz Carbonates Binder/Filler	85%
		LAYER 3 Roof Shingle, Green	No	None Detected	Cellulose Fiber	30%
					Quartz Gypsum Binder/Filler	70%
		LAYER 4 Built-up Roofing, Black	No	None Detected	Cellulose Fiber	45%
				Quartz Binder/Filler	55%	
	LAYER 5 Built-up Roofing, Black	No	None Detected	Cellulose Fiber	45%	
				Quartz Binder/Filler	55%	
	LAYER 6 Built-up Roofing, Black	No	None Detected	Cellulose Fiber	45%	
				Quartz Binder/Filler	55%	
	LAYER 7 Built-up Roofing, Black	No	None Detected	Cellulose Fiber	45%	
				Quartz Binder/Filler	55%	

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158403

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/27/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/28/2015
Collected: 07/22/2015 Date Reported: 07/28/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158403-002 1378-71		LAYER 1 Roof Shingle, Brown/ Black	No	None Detected	Fibrous Glass	15%
					Quartz Carbonates Binder/Filler	85%
		LAYER 2 Roof Shingle, Green	No	None Detected	Cellulose Fiber	30%
					Quartz Gypsum Binder/Filler	70%
		LAYER 3 Built-up Roofing, Black	No	None Detected	Cellulose Fiber	45%
					Quartz Binder/Filler	55%
	LAYER 4 Built-up Roofing, Black	No	None Detected	Cellulose Fiber	45%	
				Quartz Binder/Filler	55%	
	LAYER 5 Built-up Roofing, Black	No	None Detected	Cellulose Fiber	45%	
				Quartz Binder/Filler	55%	
	LAYER 6 Built-up Roofing, Black	No	None Detected	Cellulose Fiber	45%	
				Quartz Binder/Filler	55%	
0158403-003 1378-72		Tar on Wood, Black Note: Difficult to separate adjacent layer	No	None Detected	Cellulose Fiber	15%
					Quartz Binder/Filler	85%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158403

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/27/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/28/2015
Collected: 07/22/2015 Date Reported: 07/28/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158403-004 1378-73		LAYER 1 Rubber Roof Membrane, Black	No	None Detected	Gypsum Binder/Filler 100%
		LAYER 2 Built-up Roofing, Yellow	No	None Detected	Cellulose Fiber <1% Carbonates Binder/Filler 99%
		LAYER 3 Built-up Roofing, Silver	No	None Detected	Cellulose Fiber 1% Carbonates Quartz Binder/Filler 99%
		LAYER 4 Built-up Roofing, Black	No	None Detected	Fibrous Glass 30% Quartz Binder/Filler 70%
		LAYER 5 Built-up Roofing, Black	No	None Detected	Fibrous Glass 30% Quartz Binder/Filler 70%
		LAYER 6 Built-up Roofing, Black	No	None Detected	Cellulose Fiber 45% Carbonates Binder/Filler 55%
		LAYER 7 Built-up Roofing, Brown	No	None Detected	Cellulose Fiber 95% Gypsum Binder/Filler 5%
		LAYER 8 Built-up Roofing, Green	No	None Detected	Cellulose Fiber 30% Quartz Carbonates Binder/Filler 70%

Please see EMC Labs Sample Number 0158403-022 for Additional Layers

0158403-005 1378-74	Rubber Roof Membrane, Black	No	None Detected	Carbonates Binder/Filler 100%
------------------------	-----------------------------	----	---------------	----------------------------------

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158403

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/27/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/28/2015
Collected: 07/22/2015 Date Reported: 07/28/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158403-006 1378-75		Skirting Panel, Gray	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	15% 85%
0158403-007 1378-76		Skirting Panel, Gray	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	15% 85%
0158403-008 1378-77		Tar Paper, Black	No	None Detected	Cellulose Fiber Quartz Binder/Filler	45% 55%
0158403-009 1378-78		Tar Paper, Black	No	None Detected	Cellulose Fiber Quartz Binder/Filler	45% 55%
0158403-010 1378-79		Siding Paper, Gray	No	None Detected	Cellulose Fiber Gypsum Binder/Filler	95% 5%
0158403-011 1378-80		Siding Paper, Gray	No	None Detected	Cellulose Fiber Gypsum Binder/Filler	95% 5%
0158403-012 1378-81		Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber Fibrous Glass Gypsum Carbonates Mica Quartz	10% 3% 87%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158403

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/27/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/28/2015
Collected: 07/22/2015 Date Reported: 07/28/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158403-013 1378-82		Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber Fibrous Glass Gypsum Carbonates Mica Quartz	10% 3% 87%
0158403-014 1378-83		Insulation, Black	No	None Detected	Mineral Wool Cellulose Fiber Carbonates Binder/Filler	95% 2% 3%
0158403-015 1378-84		Insulation, Black	No	None Detected	Mineral Wool Cellulose Fiber Carbonates Binder/Filler	97% 1% 2%
0158403-016 1378-85		Caulk, White	No	None Detected	Cellulose Fiber Carbonates Quartz Binder/Filler	<1% 99%
0158403-017 1378-86		Caulk, White	No	None Detected	Carbonates Quartz Binder/Filler	 100%
0158403-018 1378-87		Transite, Gray	Yes	Chrysotile 15%	Fibrous Glass Carbonates Gypsum Quartz Binder/Filler	5% 80%
0158403-019 1378-88		Cement Skin Coat, Gray	No	None Detected	Cellulose Fiber Carbonates Quartz Gypsum Mica Binder/Filler	1% 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158403

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/27/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/28/2015
Collected: 07/22/2015 Date Reported: 07/28/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158403-020 1378-89		Cement Skin Coat, Gray	No	None Detected	Cellulose Fiber Carbonates Quartz Gypsum Mica Binder/Filler	<1% 99%
0158403-021 1378-90		Cement Skin Coat, Gray	No	None Detected	Cellulose Fiber Carbonates Quartz Gypsum Mica Binder/Filler	<1% 99%
0158403-022 1378-73	ADDITIONAL LAYERS	LAYER 1 Built-up Roofing, Black	No	None Detected	Cellulose Fiber Synthetic Fiber Quartz Binder/Filler	40% 5% 55%
		LAYER 2 Built-up Roofing, Black	No	None Detected	Cellulose Fiber Quartz Binder/Filler	45% 55%
		LAYER 3 Built-up Roofing, Black	No	None Detected	Cellulose Fiber Carbonates Binder/Filler	40% 60%
		LAYER 4 Built-up Roofing, Black	No	None Detected	Cellulose Fiber Carbonates Binder/Filler	45% 55%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158403

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/27/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/28/2015
Collected: 07/22/2015 Date Reported: 07/28/2015
Project Name: SIA BLDG 1378, 3707 GODREY BLVD, EPA Method: EPA 600/R-93/116
SPOKANE, WA Submitted By: KEVIN McCRINK
Address: Collected By:

Lab ID	Sample	Layer Name /	Asbestos	Asbestos Type	Non-Asbestos
Client ID	Location	Sample Description	Detected	(%)	Constituents


Analyst - Johann Hofer
Signatory - Lab Director - Kurt Kettler

Distinctly stratified, easily separable layers of samples are analyzed as subsamples of the whole and are reported separately for each discernible layer. All analyses are derived from calibrated visual estimate and measured in area percent unless otherwise noted. The report applies to the standards or procedures identified and to the sample(s) tested. The test results are not necessarily indicative or representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products, nor do they represent an ongoing quality assurance program unless so noted. These reports are for the exclusive use of the addressed client and that they will not be reproduced wholly or in part for advertising or other purposes over our signature or in connection with our name without special written permission. The report shall not be reproduced except in full, without written approval by our laboratory. The samples not destroyed in testing are retained a maximum of thirty days. The laboratory measurement of uncertainty for the test method is approximately less than 1 by area percent. Accredited by the National Institute of Standards and Technology, Voluntary Laboratory Accreditation Program for selected test method for asbestos. The accreditation or any reports generated by this laboratory in no way constitutes or implies product certification, approval, or endorsement by the National Institute of Standards and Technology. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. Polarized Light Microscopy may not be consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#: 158403
 TAT: 1 day
 Rec' d JUL 27 PM

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019
 CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

BILL TO: _____ (If Different Location)

Now Accepting: **VISA - MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] ~~[2-Day]~~ [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required

****Additional charges for rush analysis (please call marketing department for pricing details)

****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. 1378, 3707 Godfrey Boulevard, Spokane, WA

P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
1	1378-70	7/22/15	Brown roof shingle/black roof shingle/ green roof shingle/ built-up roofing	Y N
2	1378-71	7/22/15	Brown roof shingle/black roof shingle/ green roof shingle/ built-up roofing	Y N
3	1378-72	7/22/15	Tar on wood	Y N
4	1378-73	7/22/15	Black rubber roof membrane/ built-up roofing	Y N
5	1378-74	7/22/15	Black rubber roof membrane	Y N
6	1378-75	7/22/15	Gray skirting panel	Y N
7	1378-76	7/22/15	Gray skirting panel	Y N
8	1378-77	7/22/15	Black tar paper	Y N
9	1378-78	7/22/15	Black tar paper	Y N
10	1378-79	7/22/15	Gray siding paper	Y N
11	1378-80	7/22/15	Gray siding paper	Y N
12	1378-81	7/22/15	Sheetrock	Y N
13	1378-82	7/22/15	Sheetrock	Y N
14	1378-83	7/22/15	Black insulation	Y N
15	1378-84	7/22/15	Black insulation	Y N

SPECIAL INSTRUCTIONS:

Sample Collector: (Print) Kevin McCrink (Signature) [Signature]

Relinquished by: [Signature] Date/Time: 7/25/15 Received by: Diana Federico Date/Time: 7/27/15

Relinquished by: Diana Federico Date/Time: 7/27/15 Received by: [Signature] Date/Time: 7-27-15

Relinquished by: _____ Date/Time _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY

EMC Laboratories
9830 S. 51ST St., Ste B-109
Phoenix, AZ 85044
(800) 362-3373 Fax (480) 893-1726

LAB#:	158403
TAT:	
Rec'd:	

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019

CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

BILL TO: _____

(If Different Location)

Now Accepting: **VISA – MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] (1-Day) ~~(2-Day)~~ [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. 1378, 3707 Godfrey Boulevard, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
16	1378-85	7/22/15	White caulk	N
17	1378-86	7/22/15	White caulk	Y N
18	1378-87	7/22/15	Transite	Y N
19	1378-88	7/22/15	Cement skin coat	Y N
20	1378-89	7/22/15	Cement skin coat	Y N
21	1378-90	7/22/15	Cement skin coat	N
22	1378-73	7-22-15	ADDITIONAL CHARGES	N
22	1378-73	7-22-15	ADDITIONAL LAYERS	N
				Y N
				Y N
				Y N
				Y N
				Y N
				Y N
				Y N

SPECIAL INSTRUCTIONS: _____

Sample Collector: (Print) Kevin McCrink (Signature) Kevin McCrink

Relinquished by: Kevin McCrink Date/Time: 7/27/15 Received by: Diana Federico Date/Time: 7/27/15

Relinquished by: Diana Federico Date/Time: 7/27/15 Received by: John D. Hoken Date/Time: 7-27-15

Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158406

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/27/2015
Collected:	07/23/2015	Date Analyzed:	07/28/2015
Project Name:	SIA BLDG #1424, 7306 W. PILOT DR.	Date Reported:	07/28/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158406-001 1424-1		LAYER 1 Asphalt Roofing Shingle, Brown/ Black	No	None Detected	Fibrous Glass Carbonates Quartz Gypsum Binder/Filler	15% 85%
		LAYER 2 Tar, Black	No	None Detected	Cellulose Fiber Gypsum Carbonates Binder/Filler	<1% 99%
0158406-002 1424-2		LAYER 1 Asphalt Roofing Shingle, Brown/ Black	No	None Detected	Fibrous Glass Carbonates Quartz Gypsum Binder/Filler	15% 85%
		LAYER 2 Tar, Black	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	<1% 99%
0158406-003 1424-3		LAYER 1 Asphalt Roofing Shingle, Brown/ Black	No	None Detected	Fibrous Glass Carbonates Quartz Gypsum Binder/Filler	15% 85%
		LAYER 2 Tar, Black	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	<1% 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158406

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/27/2015
Collected:	07/23/2015	Date Analyzed:	07/28/2015
Project Name:	SIA BLDG #1424, 7306 W. PILOT DR.	Date Reported:	07/28/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158406-004 1424-4		LAYER 1 Asphalt Roofing Shingle, Brown/ Black	No	None Detected	Fibrous Glass 15% Carbonates Quartz Gypsum Binder/Filler 85%
		LAYER 2 Tar, Black	No	None Detected	Fibrous Glass 1% Carbonates Gypsum Quartz Binder/Filler 99%
0158406-005 1424-5		Tar Paper, Black	No	None Detected	Cellulose Fiber 40% Carbonates Gypsum Binder/Filler 60%
0158406-006 1424-6		Tar Paper, Black	No	None Detected	Cellulose Fiber 40% Fibrous Glass <1% Carbonates Gypsum Binder/Filler 59%
0158406-007 1424-7		Tar Paper, Black	No	None Detected	Cellulose Fiber 40% Carbonates Gypsum Binder/Filler 60%
0158406-008 1424-8		Tar Paper, Black	No	None Detected	Cellulose Fiber 40% Carbonates Gypsum Binder/Filler 60%
0158406-009 1424-9		Siding Paper, Tan/ Black	No	None Detected	Cellulose Fiber 60% Carbonates Gypsum Binder/Filler 40%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158406

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/27/2015
Collected:	07/23/2015	Date Analyzed:	07/28/2015
Project Name:	SIA BLDG #1424, 7306 W. PILOT DR.	Date Reported:	07/28/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158406-010 1424-10		Siding Paper, Tan/ Black	No	None Detected	Cellulose Fiber Carbonates Gypsum Binder/Filler	60% 40%
0158406-011 1424-11		Siding Paper, Tan/ Black	No	None Detected	Cellulose Fiber Gypsum Carbonates Quartz Binder/Filler	60% 40%
0158406-012 1424-12		Seam Sealer, White	No	None Detected	Carbonates Quartz Binder/Filler	100%
0158406-013 1424-13		Seam Sealer, White	No	None Detected	Carbonates Quartz Gypsum Binder/Filler	100%
0158406-014 1424-14		Dock Seam Sealer, White	No	None Detected	Carbonates Gypsum Binder/Filler	100%
0158406-015 1424-15		Dock Seam Sealer, White	No	None Detected	Carbonates Gypsum Binder/Filler	100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158406

Bulk Asbestos Analysis by Polarized Light Microscopy


NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231	Date Received:	07/27/2015
	LIBERTY LAKE, WA 99019	Date Analyzed:	07/28/2015
Collected:	07/23/2015	Date Reported:	07/28/2015
Project Name:	SIA BLDG #1424, 7306 W. PILOT DR.	EPA Method:	EPA 600/R-93/116
Address:	SPOKANE, WA	Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID	Sample	Layer Name /	Asbestos	Asbestos Type	Non-Asbestos
Client ID	Location	Sample Description	Detected	(%)	Constituents



Analyst - Kurt Kettler



Signatory - Lab Manager - Ken Scheske

Distinctly stratified, easily separable layers of samples are analyzed as subsamples of the whole and are reported separately for each discernible layer. All analyses are derived from calibrated visual estimate and measured in area percent unless otherwise noted. The report applies to the standards or procedures identified and to the sample(s) tested. The test results are not necessarily indicated or representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products, nor do they represent an ongoing quality assurance program unless so noted. These reports are for the exclusive use of the addressed client and that they will not be reproduced wholly or in part for advertising or other purposes over our signature or in connection with our name without special written permission. The report shall not be reproduced except in full, without written approval by our laboratory. The samples not destroyed in testing are retained a maximum of thirty days. The laboratory measurement of uncertainty for the test method is approximately less than 1 by area percent. Accredited by the National Institute of Standards and Technology, Voluntary Laboratory Accreditation Program for selected test method for asbestos. The accreditation or any reports generated by this laboratory in no way constitutes or implies product certification, approval, or endorsement by the National Institute of Standards and Technology. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. Polarized Light Microscopy may not be consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#: 158406
 TAT: 1 day
 Rec'd: JUL 27 P.M.

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019
 CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgn@aol.com

BILL TO: _____
 (If Different Location)

Now Accepting: **VISA - MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #1424,7306 W. Pilot Drive, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>1</u>	1424-1	7/23/15	Brown asphalt roofing shingle/ tar	<u>Y</u> N
<u>2</u>	1424-2	7/23/15	Brown asphalt roofing shingle/ tar	Y <u>N</u>
<u>3</u>	1424-3	7/23/15	Black asphalt roofing shingle/ tar	Y N
<u>4</u>	1424-4	7/23/15	Black asphalt roofing shingle/ tar	Y N
<u>5</u>	1424-5	7/23/15	Black tar paper	Y N
<u>6</u>	1424-6	7/23/15	Black tar paper	Y N
<u>7</u>	1424-7	7/23/15	Black tar paper	Y N
<u>8</u>	1424-8	7/23/15	Black tar paper	Y N
<u>9</u>	1424-9	7/23/15	Tan/ black siding paper	Y N
<u>10</u>	1424-10	7/23/15	Tan/ black siding paper	Y N
<u>11</u>	1424-11	7/23/15	Tan/ black siding paper	Y N
<u>12</u>	1424-12	7/23/15	White seam sealer	Y N
<u>13</u>	1424-13	7/23/15	White seam sealer	Y N
<u>14</u>	1424-14	7/23/15	White dock seam sealer	Y N
<u>15</u>	1424-15	7/23/15	White dock seam sealer	<u>Y</u> N

SPECIAL INSTRUCTIONS: _____
 Sample Collector: (Print) Kevin McCrink (Signature) [Signature]
 Relinquished by: [Signature] Date/Time: 7-25-15 Received by: Diana Federico Date/Time: 7/27/15
 Relinquished by: Diana Federico Date/Time: 7/27/15 Received by: [Signature] Date/Time: 7/27/15
 Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726


Laboratory Report
0154985

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-14-056
Address:	1324 LIBERTY LAKE RD, 231	Date Received:	05/08/2015
	LIBERTY LAKE, WA 99019	Date Analyzed:	05/12/2015
Collected:	05/07/2015	Date Reported:	05/12/2015
Project Name:	7306 W. WAREHOUSE AVENUE	EPA Method:	EPA 600/R-93/116
Address:		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0154985-001 7306-1		Ceiling Panel, Green/ Tan	No	None Detected	Cellulose Fiber 90% Carbonates Binder/Filler 10%
0154985-002 7306-2		Ceiling Panel, Green/ Tan	No	None Detected	Cellulose Fiber 90% Carbonates Binder/Filler 10%
0154985-003 7306-3		Ceiling Panel, Green/ Tan	No	None Detected	Cellulose Fiber 90% Carbonates Binder/Filler 10%
0154985-004 7306-4		Sheetrock Panel, White/ Brown	No	None Detected	Cellulose Fiber 12% Gypsum Carbonates Mica 88%
0154985-005 7306-5		Sheetrock Panel, White/ Brown	No	None Detected	Cellulose Fiber 12% Gypsum Carbonates Mica 88%
0154985-006 7306-6		Sheetrock Panel, White/ Brown	No	None Detected	Cellulose Fiber 12% Gypsum Carbonates Mica 88%



Analyst - Kenneth Scheske



Signatory - Lab Director - Kurt Kettler

Distinctly stratified, easily separable layers of samples are analyzed as subsamples of the whole and are reported separately for each discernible layer. All analyses are derived from calibrated visual estimate and measured in area percent unless otherwise noted. The report applies to the standards or procedures identified and to the sample(s) tested. The test results are not necessarily indicative or representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products, nor do they represent an ongoing quality assurance program unless so noted. These reports are for the exclusive use of the addressed client and that they will not be reproduced wholly or in part for advertising or other purposes over our signature or in connection with our name without special written permission. The report shall not be reproduced except in full, without written approval by our laboratory. The samples not destroyed in testing are retained a maximum of thirty days. The laboratory measurement of uncertainty for the test method is approximately less than 1 by area percent. Accredited by the National Institute of Standards and Technology, Voluntary Laboratory Accreditation Program for selected test method for asbestos. The accreditation or any reports generated by this laboratory in no way constitutes or implies product certification, approval, or endorsement by the National Institute of Standards and Technology. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. Polarized Light Microscopy may not be consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#: 154985
 TAT: 2 days
 Rec'd: MAY 08 AM.

COMPANY NAME: Environmental Risk Mgmt
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019
 CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

BILL TO: _____ (If Different Location)

Now Accepting: **VISA - MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] ~~[1-Day]~~ [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: 7306 W. WAREHOUSE AVENUE
 P.O. Number: _____ Project Number: ERM-14-056

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>1</u>	<u>7306-1</u>	<u>5-7-15</u>	<u>GREEN/TAN CEILING PANEL</u>	<u>Y</u> N
<u>2</u>	<u>7306-2</u>			Y N
<u>3</u>	<u>7306-3</u>			Y N
<u>4</u>	<u>7306-4</u>		<u>SHEETROCK PANEL</u>	Y N
<u>5</u>	<u>7306-5</u>			Y N
<u>6</u>	<u>7306-6</u>			<u>Y</u> N
				Y N
				Y N
				Y N
				Y N
				Y N
				Y N
				Y N
				Y N

SPECIAL INSTRUCTIONS: _____
 Sample Collector: (Print) Kevin McCrink (Signature) Kevin
 Relinquished by: [Signature] Date/Time: 5-7-15 Received by: Diana Federico Date/Time: 5/8/15
 Relinquished by: Diana Federico Date/Time: 5/8/15 Received by: [Signature] Date/Time: 5/8/15
 Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158433

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/28/2015
Collected:	07/27/2015	Date Analyzed:	07/29/2015
Project Name:	SIA BLDG #1425-7210 W. PILOT DR.	Date Reported:	07/29/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158433-001 1425-1		LAYER 1 Splatter Texture, White/ Off White	No	None Detected	Synthetic Fiber <1% Carbonates Mica Quartz Binder/Filler 99%
		LAYER 2 Sheetrock, Peach/ Brown	No	None Detected	Cellulose Fiber 10% Fibrous Glass 2% Gypsum Quartz Carbonates 88%
0158433-002 1425-2		LAYER 1 Splatter Texture, White/ Off White	No	None Detected	Synthetic Fiber <1% Carbonates Mica Quartz Binder/Filler 99%
		LAYER 2 Sheetrock, Peach/ Brown	No	None Detected	Cellulose Fiber 10% Fibrous Glass 2% Gypsum Quartz Carbonates 88%
0158433-003 1425-3		LAYER 1 Splatter Texture, White/ Off White	No	None Detected	Cellulose Fiber <1% Carbonates Mica Quartz Binder/Filler 99%
		LAYER 2 Sheetrock, Peach/ Brown	No	None Detected	Cellulose Fiber 10% Fibrous Glass 2% Gypsum Quartz Carbonates 88%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158433

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/28/2015
Collected:	07/27/2015	Date Analyzed:	07/29/2015
Project Name:	SIA BLDG #1425-7210 W. PILOT DR.	Date Reported:	07/29/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158433-004 1425-4		LAYER 1 Splatter Texture, White/ Off White	No	None Detected	Cellulose Fiber <1% Carbonates Mica Quartz Binder/Filler 99%
		LAYER 2 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber 10% Fibrous Glass 2% Gypsum Quartz Carbonates 88%
0158433-005 1425-5		LAYER 1 Splatter Texture, White/ Off White	No	None Detected	Cellulose Fiber 1% Carbonates Mica Quartz Binder/Filler 99%
		LAYER 2 Sheetrock, Peach/ Brown	No	None Detected	Cellulose Fiber 10% Fibrous Glass 2% Gypsum Quartz Carbonates 88%
0158433-006 1425-6		LAYER 1 Carpet, Blue	No	None Detected	Synthetic Fiber 95% Carbonates Binder/Filler 5%
		LAYER 2 Mastic, Tan	No	None Detected	Cellulose Fiber 1% Synthetic Fiber 1% Carbonates Gypsum Quartz Binder/Filler 98%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158433

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/28/2015
Collected:	07/27/2015	Date Analyzed:	07/29/2015
Project Name:	SIA BLDG #1425-7210 W. PILOT DR.	Date Reported:	07/29/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158433-007 1425-7		LAYER 1 Carpet, Blue	No	None Detected	Synthetic Fiber Carbonates Binder/Filler	95% 5%
		LAYER 2 Mastic, Tan	No	None Detected	Synthetic Fiber Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	1% <1% 98%
0158433-008 1425-8		LAYER 1 Carpet, Blue	No	None Detected	Synthetic Fiber Carbonates Binder/Filler	95% 5%
		LAYER 2 Mastic, Tan	No	None Detected	Cellulose Fiber Synthetic Fiber Carbonates Gypsum Quartz Binder/Filler	2% 1% 97%
0158433-009 1425-9		LAYER 1 Sheet Vinyl, Gray	No	None Detected	Carbonates Quartz Binder/Filler	100%
		LAYER 2 Mastic, Off White	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	1% 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158433

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231	Date Received:	07/28/2015
	LIBERTY LAKE, WA 99019	Date Analyzed:	07/29/2015
Collected:	07/27/2015	Date Reported:	07/29/2015
Project Name:	SIA BLDG #1425-7210 W. PILOT DR.	EPA Method:	EPA 600/R-93/116
Address:	SPOKANE, WA	Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158433-010 1425-10		LAYER 1 Sheet Vinyl, Gray	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Off White	No	None Detected	Cellulose Fiber 2% Carbonates Gypsum Quartz Binder/Filler 98%
0158433-011 1425-11		LAYER 1 Sheet Vinyl, Gray	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Off White	No	None Detected	Cellulose Fiber 2% Carbonates Gypsum Quartz Binder/Filler 98%
0158433-012 1425-12		LAYER 1 Cove Base, Gray	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Off White	No	None Detected	Cellulose Fiber 3% Carbonates Gypsum Quartz Binder/Filler 97%
		LAYER 3 Mastic - Top, Off White	No	None Detected	Cellulose Fiber 1% Carbonates Gypsum Quartz Binder/Filler 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158433

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/28/2015
Collected:	07/27/2015	Date Analyzed:	07/29/2015
Project Name:	SIA BLDG #1425-7210 W. PILOT DR.	Date Reported:	07/29/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158433-013 1425-13		LAYER 1 Cove Base, Gray	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Off White	No	None Detected	Cellulose Fiber 1% Carbonates Gypsum Quartz Binder/Filler 99%
		LAYER 3 Compound, White	No	None Detected	Cellulose Fiber 1% Carbonates Mica Quartz Binder/Filler 99%
0158433-014 1425-14		2x4 Ceiling Tile, White/ Beige	No	None Detected	Mineral Wool 50% Cellulose Fiber 30% Carbonates Gypsum Quartz Perlite Binder/Filler 20%
0158433-015 1425-15		2x4 Ceiling Tile, White/ Beige	No	None Detected	Mineral Wool 50% Cellulose Fiber 30% Carbonates Gypsum Quartz Perlite Binder/Filler 20%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158433

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/28/2015
Collected:	07/27/2015	Date Analyzed:	07/29/2015
Project Name:	SIA BLDG #1425-7210 W. PILOT DR.	Date Reported:	07/29/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158433-016 1425-16		LAYER 1 Cove Base, Dk. Gray	No	None Detected	Carbonates Quartz Binder/Filler	100%
		LAYER 2 Mastic, Off White	No	None Detected	Carbonates Gypsum Quartz Binder/Filler	100%
0158433-017 1425-17		LAYER 1 Cove Base, Dk. Gray	No	None Detected	Carbonates Quartz Binder/Filler	100%
		LAYER 2 Mastic, Off White	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	<1% 99%
0158433-018 1425-18		LAYER 1 Wall Panel Mastic, Tan	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	<1% 99%
		LAYER 2 Compound, White	No	None Detected	Cellulose Fiber Carbonates Mica Quartz Binder/Filler	<1% 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158433

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/28/2015
Collected:	07/27/2015	Date Analyzed:	07/29/2015
Project Name:	SIA BLDG #1425-7210 W. PILOT DR.	Date Reported:	07/29/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158433-019 1425-19		LAYER 1 Wall Panel Mastic, Tan	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	<1% 99%
		LAYER 2 Compound, White	No	None Detected	Cellulose Fiber Carbonates Mica Quartz Binder/Filler	<1% 99%
0158433-020 1425-20		LAYER 1 Formica, Gray	No	None Detected	Cellulose Fiber Gypsum Binder/Filler	70% 30%
		LAYER 2 Glue, Lt. Yellow	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	1% 99%
		LAYER 3 Compound, White	No	None Detected	Carbonates Quartz Binder/Filler	 100%
0158433-021 1425-21		LAYER 1 Formica, Gray	No	None Detected	Cellulose Fiber Gypsum Binder/Filler	70% 30%
		LAYER 2 Glue, Lt. Yellow	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	1% 99%
		LAYER 3 Compound, White	No	None Detected	Carbonates Quartz Binder/Filler	 100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158433

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/28/2015
Collected:	07/27/2015	Date Analyzed:	07/29/2015
Project Name:	SIA BLDG #1425-7210 W. PILOT DR.	Date Reported:	07/29/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158433-022 1425-22		LAYER 1 Sheetrock, Peach/ Brown	No	None Detected	Cellulose Fiber Gypsum Quartz Carbonates	12% 88%
		LAYER 2 Compound, White	No	None Detected	Cellulose Fiber Carbonates Mica Quartz Binder/Filler	<1% 99%
0158433-023 1425-23		LAYER 1 Sheetrock, Peach/ Brown	No	None Detected	Cellulose Fiber Fibrous Glass Gypsum Quartz Carbonates	10% 2% 88%
		LAYER 2 Compound, White	No	None Detected	Cellulose Fiber Carbonates Mica Quartz Binder/Filler	1% 99%
0158433-024 1425-24		LAYER 1 Backing Paper, Tan/ Black	No	None Detected	Cellulose Fiber Carbonates Gypsum Binder/Filler	70% 30%
		LAYER 2 Insulation, Yellow	No	None Detected	Fibrous Glass Carbonates Binder/Filler	95% 5%
0158433-025 1425-25		LAYER 1 Backing Paper, Tan/ Black	No	None Detected	Cellulose Fiber Carbonates Gypsum Binder/Filler	70% 30%
		LAYER 2 Insulation, Yellow	No	None Detected	Fibrous Glass Carbonates Binder/Filler	95% 5%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158433

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/28/2015
Collected:	07/27/2015	Date Analyzed:	07/29/2015
Project Name:	SIA BLDG #1425-7210 W. PILOT DR.	Date Reported:	07/29/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158433-026 1425-26		LAYER 1 Backing Paper, Silver/ Tan	No	None Detected	Cellulose Fiber Fibrous Glass Aluminum Carbonates Gypsum Binder/Filler	45% 15% 40%
		LAYER 2 Insulation, Yellow	No	None Detected	Fibrous Glass Carbonates Binder/Filler	95% 5%
0158433-027 1425-27		LAYER 1 Backing Paper, Silver/ Tan	No	None Detected	Cellulose Fiber Fibrous Glass Aluminum Carbonates Gypsum Binder/Filler	45% 15% 40%
		LAYER 2 Insulation, Yellow	No	None Detected	Fibrous Glass Carbonates Binder/Filler	95% 5%
0158433-028 1425-28		Blown-in Insulation, Gray	No	None Detected	Cellulose Fiber Carbonates Gypsum Binder/Filler	95% 5%
0158433-029 1425-29		Blown-in Insulation, Gray	No	None Detected	Cellulose Fiber Carbonates Gypsum Binder/Filler	97% 3%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158433

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/28/2015
Collected:	07/27/2015	Date Analyzed:	07/29/2015
Project Name:	SIA BLDG #1425-7210 W. PILOT DR.	Date Reported:	07/29/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158433-030 1425-30		LAYER 1 Asphalt Roofing Shingle, Brown	No	None Detected	Fibrous Glass Carbonates Gypsum Quartz Binder/Filler	20% 80%
		LAYER 2 Tar, Black	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	3% 97%
0158433-031 1425-31		LAYER 1 Asphalt Roofing Shingle, Brown	No	None Detected	Fibrous Glass Carbonates Gypsum Quartz Binder/Filler	20% 80%
		LAYER 2 Tar, Black	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	<1% 99%
0158433-032 1425-32		Tar Paper, Black	No	None Detected	Cellulose Fiber Carbonates Gypsum Binder/Filler	60% 40%
0158433-033 1425-33		Tar Paper, Black	No	None Detected	Cellulose Fiber Carbonates Gypsum Binder/Filler	60% 40%
0158433-034 1425-34		Siding Paper, Tan/ Black	No	None Detected	Cellulose Fiber Carbonates Gypsum Binder/Filler	70% 30%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158433

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/28/2015
Collected:	07/27/2015	Date Analyzed:	07/29/2015
Project Name:	SIA BLDG #1425-7210 W. PILOT DR.	Date Reported:	07/29/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158433-035 1425-35		Siding Paper, Tan/ Black	No	None Detected	Cellulose Fiber Carbonates Gypsum Binder/Filler	70% 30%
0158433-036 1425-36		Siding Paper, Tan/ Black	No	None Detected	Cellulose Fiber Carbonates Gypsum Binder/Filler	70% 30%
0158433-037 1425-37		Seam Sealer, White	No	None Detected	Cellulose Fiber Carbonates Quartz Binder/Filler	<1% 99%
0158433-038 1425-38		Seam Sealer, White	No	None Detected	Cellulose Fiber Carbonates Quartz Binder/Filler	<1% 99%
0158433-039 1425-39		Dock Seam Sealer, White	No	None Detected	Cellulose Fiber Quartz Gypsum Mica Carbonates Binder/Filler	<1% 99%
0158433-040 1425-40		Dock Seam Sealer, White	No	None Detected	Cellulose Fiber Quartz Gypsum Mica Carbonates Binder/Filler	<1% 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158433

Bulk Asbestos Analysis by Polarized Light Microscopy


NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231	Date Received:	07/28/2015
	LIBERTY LAKE, WA 99019	Date Analyzed:	07/29/2015
Collected:	07/27/2015	Date Reported:	07/29/2015
Project Name:	SIA BLDG #1425-7210 W. PILOT DR.	EPA Method:	EPA 600/R-93/116
Address:	SPOKANE, WA	Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158433-041 1425-41		LAYER 1 Non-Skid, Black	No	None Detected	Carbonates Gypsum Quartz Binder/Filler 100%
		LAYER 2 Glue, Clear	No	None Detected	Cellulose Fiber 1% Carbonates Gypsum Quartz Binder/Filler 99%
0158433-042 1425-42		LAYER 1 Non-Skid, Black	No	None Detected	Carbonates Gypsum Quartz Binder/Filler 100%
		LAYER 2 Glue, Clear	No	None Detected	Cellulose Fiber 1% Carbonates Gypsum Quartz Binder/Filler 99%



Analyst - Kurt Kettler



Signatory - Lab Manager - Ken Scheske

Distinctly stratified, easily separable layers of samples are analyzed as subsamples of the whole and are reported separately for each discernible layer. All analyses are derived from calibrated visual estimate and measured in area percent unless otherwise noted. The report applies to the standards or procedures identified and to the sample(s) tested. The test results are not necessarily indicated or representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products, nor do they represent an ongoing quality assurance program unless so noted. These reports are for the exclusive use of the addressed client and that they will not be reproduced wholly or in part for advertising or other purposes over our signature or in connection with our name without special written permission. The report shall not be reproduced except in full, without written approval by our laboratory. The samples not destroyed in testing are retained a maximum of thirty days. The laboratory measurement of uncertainty for the test method is approximately less than 1 by area percent. Accredited by the National Institute of Standards and Technology, Voluntary Laboratory Accreditation Program for selected test method for asbestos. The accreditation or any reports generated by this laboratory in no way constitutes or implies product certification, approval, or endorsement by the National Institute of Standards and Technology. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. Polarized Light Microscopy may not be consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#: 158433
 TAT: 1 day
 Rec'd: EMC USE ONLY 2 8 AM

COMPANY NAME: Environmental Risk Mgmt BILL TO: _____ (If Different Location)
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019
 CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

Now Accepting: **VISA - MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] **[1-Day]** [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** **[Bulk-PLM]** [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #1425,7210 W. Pilot Drive, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

42

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
1	1425-1	7/27/15	Splatter texture/ sheetrock	Y N
2	1425-2	7/27/15	Splatter texture/ sheetrock	Y N
3	1425-3	7/27/15	Splatter texture/ sheetrock	Y N
4	1425-4	7/27/15	Splatter texture/ sheetrock	Y N
5	1425-5	7/27/15	Splatter texture/ sheetrock	Y N
6	1425-6	7/27/15	Blue carpet/ tan mastic	Y N
7	1425-7	7/27/15	Blue carpet/ tan mastic	Y N
8	1425-8	7/27/15	Blue carpet/ tan mastic	Y N
9	1425-9	7/27/15	Gray sheet vinyl/ mastic	Y N
10	1425-10	7/27/15	Gray sheet vinyl/ mastic	Y N
11	1425-11	7/27/15	Gray sheet vinyl/ mastic	Y N
12	1425-12	7/27/15	Gray cove base/ mastic	Y N
13	1425-13	7/27/15	Gray cove base/ mastic	Y N
14	1425-14	7/27/15	White 2x4 ceiling tile	Y N
15	1425-15	7/27/15	White 2x4 ceiling tile	Y N

SPECIAL INSTRUCTIONS: _____
 Sample Collector: (Print) Kevin McCrink (Signature) [Signature]
 Relinquished by: [Signature] Date/Time: 7/27/15 Received by: Diana Federico Date/Time: 7/28/15
 Relinquished by: Diana Federico Date/Time: 7/28/15 Received by: [Signature] Date/Time: 7/28/15
 Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY

EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#:	
TAT:	158433
Rec'd:	
EMC USE ONLY	

COMPANY NAME: Environmental Risk Mgmt BILL TO: _____ (If Different Location)

1324 Liberty Lake Rd, 231

Liberty Lake, WA 99019

CONTACT: Kevin McCrink

Phone/Fax: (509) 226-2523 /

Email: envriskmgm@aol.com

Now Accepting: **VISA - MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] **[1-Day]** [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** **[Bulk-PLM]** [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 90 days from analysis.)

Project Name: SIA Bldg. #1425,7210 W. Pilot Drive, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
16	1425-16	7/27/15	Dark gray cove base/ mastic	Y N
17	1425-17	7/27/15	Dark gray cove base/ mastic	Y N
18	1425-18	7/27/15	Tan wall panel mastic	Y N
19	1425-19	7/27/15	Tan wall panel mastic	Y N
20	1425-20	7/27/15	Gray formica/ glue	Y N
21	1425-21	7/27/15	Gray formica/ glue	Y N
22	1425-22	7/27/15	Sheetrock/ joint compound	Y N
23	1425-23	7/27/15	Sheetrock/ joint compound	Y N
24	1425-24	7/27/15	Tan-black backing paper/ yellow insulation	Y N
25	1425-25	7/27/15	Tan-black backing paper/ yellow insulation	Y N
26	1425-26	7/27/15	Silver-tan backing paper/ yellow insulation	Y N
27	1425-27	7/27/15	Silver-tan backing paper/ yellow insulation	Y N
28	1425-28	7/27/15	Gray blown-in insulation	Y N
29	1425-29	7/27/15	Gray blown-in insulation	Y N
30	1425-30	7/27/15	Brown asphalt roofing shingle/ tar	Y N

SPECIAL INSTRUCTIONS: _____

Sample Collector: (Print) Kevin McCrink (Signature) [Signature]

Relinquished by: [Signature] Date/Time: 7/27/15 Received by: Diana Federico Date/Time: 7/28/15

Relinquished by: Diana Federico Date/Time: 7/28/15 Received by: [Signature] Date/Time: 7/29/15

Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#:	
TAT:	158433
Rec'd:	EMC USE ONLY

COMPANY NAME: Environmental Risk Mgmt BILL TO: _____ (If Different Location)
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019
 CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

Now Accepting: **VISA – MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] **[1-Day]** [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** **[Bulk-PLM]** [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #1425,7210 W. Pilot Drive, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
31	1425-31	7/27/15	Brown asphalt roofing shingle/ tar	Y N
32	1425-32	7/27/15	Black tar paper	Y N
33	1425-33	7/27/15	Black tar paper	Y N
34	1425-34	7/27/15	Tan/ black siding paper	Y N
35	1425-35	7/27/15	Tan/ black siding paper	Y N
36	1425-36	7/27/15	Tan/ black siding paper	Y N
37	1425-37	7/27/15	White seam sealer	Y N
38	1425-38	7/27/15	White seam sealer	Y N
39	1425-39	7/27/15	White dock seam sealer	Y N
40	1425-40	7/27/15	White dock seam sealer	Y N
41	1425-41	7/27/15	Black non-skid/ glue	Y N
42	1425-42	7/27/15	Black non-skid/ glue	Y N
				Y N
				Y N
				Y N

SPECIAL INSTRUCTIONS: _____
 Sample Collector: (Print) Kevin McCrink (Signature) [Signature]
 Relinquished by: [Signature] Date/Time: 7/27/15 Received by: Diana Federico Date/Time: 7/28/15
 Relinquished by: Diana Federico Date/Time: 7/28/15 Received by: [Signature] Date/Time: 7/28/15
 Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158123

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/20/2015
Collected:	07/15/2015	Date Analyzed:	07/23/2015
Project Name:	SIA BLDG. #2501-8600 W. ELECTRIC AVE	Date Reported:	07/23/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158123-001 2501-1		LAYER 1 9"x9" Floor Tile, Brown	Yes	Chrysotile 10%	Carbonates Quartz Binder/Filler 90%
		LAYER 2 Mastic, Black	Yes	Chrysotile 5%	Carbonates Gypsum Quartz Binder/Filler 95%
0158123-002 2501-2		LAYER 1 9"x9" Floor Tile, Brown	Yes	Chrysotile 10%	Carbonates Quartz Binder/Filler 90%
		LAYER 2 Mastic, Black	Yes	Chrysotile 5%	Carbonates Gypsum Quartz Binder/Filler 95%
0158123-003 2501-3		LAYER 1 Cove Base, Brown	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Black	No	None Detected	Wollastonite Carbonates Gypsum Quartz Binder/Filler 2% 98%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158123

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231	Date Received:	07/20/2015
	LIBERTY LAKE, WA 99019	Date Analyzed:	07/23/2015
Collected:	07/15/2015	Date Reported:	07/23/2015
Project Name:	SIA BLDG. #2501-8600 W. ELECTRIC AVE	EPA Method:	EPA 600/R-93/116
Address:	SPOKANE, WA	Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158123-004 2501-4		LAYER 1 Cove Base, Brown	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Black	No	None Detected	Carbonates Gypsum Quartz Binder/Filler 100%
0158123-005 2501-5		LAYER 1 Cove Base, Brown	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Brown	Yes	Tremolite <1%	Non-Fibrous Tremolite 3% Talc 2% Carbonates Gypsum Quartz Binder/Filler 94%
0158123-006 2501-6		LAYER 1 Cove Base, Brown	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Black/ Brown	Yes	Tremolite <1%	Non-Fibrous Tremolite 3% Talc 2% Carbonates Gypsum Quartz Binder/Filler 94%
0158123-007 2501-7		2x4 Ceiling Tile, White(Floral Pin Hole Pattern)	Yes	Amosite 4% Chrysotile 1%	Mineral Wool 85% Carbonates Gypsum Binder/Filler 10%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158123

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/20/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/23/2015
Collected: 07/15/2015 Date Reported: 07/23/2015
Project Name: SIA BLDG. #2501-8600 W. ELECTRIC AVE EPA Method: EPA 600/R-93/116
Address: SPOKANE, WA Submitted By: KEVIN McCRINK
Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158123-008 2501-8		2x4 Ceiling Tile, White/ Off White	Yes	Amosite 5%	Cellulose Fiber Mineral Wool Carbonates Gypsum Perlite Binder/Filler 20%
0158123-009 2501-9		2x4 Ceiling Tile, White/ Off White	Yes	Amosite Chrysotile 5% 1%	Mineral Wool Carbonates Gypsum Binder/Filler 9%
0158123-010 2501-10		2x4 Ceiling Tile, White/ Off White	Yes	Amosite Chrysotile 5% 1%	Mineral Wool Carbonates Gypsum Binder/Filler 9%
0158123-011 2501-11		LAYER 1 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber Fibrous Glass Gypsum Carbonates Mica Quartz 88%
		LAYER 2 Joint Compound, White/ Lt. Blue	Yes	Chrysotile 3%	Cellulose Fiber Carbonates Mica Quartz Binder/Filler 96%
		LAYER 3 Sheetrock, Joint Compound Composite, White/ Brown/ Lt. Blue Note: COMPOSITE ANALYSIS REQUESTED	Yes	Chrysotile <1%	Cellulose Fiber Fibrous Glass Gypsum Carbonates Mica Quartz Binder/Filler 9% 1% 89%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158123

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231	Date Received:	07/20/2015
	LIBERTY LAKE, WA 99019	Date Analyzed:	07/23/2015
Collected:	07/15/2015	Date Reported:	07/23/2015
Project Name:	SIA BLDG. #2501-8600 W. ELECTRIC AVE	EPA Method:	EPA 600/R-93/116
Address:	SPOKANE, WA	Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158123-012 2501-12		LAYER 1 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber 10% Fibrous Glass 2% Gypsum Carbonates Mica Quartz 88%
		LAYER 2 Joint Compound, White/ Lt. Blue	Yes	Chrysotile 3%	Cellulose Fiber <1% Carbonates Mica Quartz Binder/Filler 96%
		LAYER 3 Sheetrock, Joint Compound Composite, White/ Brown/ Lt. Blue Note: COMPOSITE ANALYSIS REQUESTED	Yes	Chrysotile <1%	Cellulose Fiber 9% Fibrous Glass 1% Gypsum Carbonates Mica Quartz Binder/Filler 89%
0158123-013 2501-13		LAYER 1 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber 10% Fibrous Glass 2% Gypsum Carbonates Mica Quartz 88%
		LAYER 2 Joint Compound, White/ Lt. Blue	Yes	Chrysotile 3%	Cellulose Fiber 1% Carbonates Mica Quartz Binder/Filler 96%
		LAYER 3 Sheetrock, Joint Compound Composite, White/ Brown/ Lt. Blue Note: COMPOSITE ANALYSIS REQUESTED	Yes	Chrysotile <1%	Cellulose Fiber 9% Fibrous Glass 1% Gypsum Carbonates Mica Quartz Binder/Filler 89%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158123

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/20/2015
Collected:	07/15/2015	Date Analyzed:	07/23/2015
Project Name:	SIA BLDG. #2501-8600 W. ELECTRIC AVE	Date Reported:	07/23/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158123-014 2501-14		LAYER 1 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber Gypsum Carbonates Mica Quartz	12% 88%
		LAYER 2 Joint Compound, White/ Lt. Blue	Yes	Chrysotile 3%	Cellulose Fiber Carbonates Mica Quartz Binder/Filler	<1% 96%
		LAYER 3 Sheetrock, Joint Compound Composite, White/ Brown/ Lt. Blue Note: COMPOSITE ANALYSIS REQUESTED	Yes	Chrysotile <1%	Cellulose Fiber Gypsum Carbonates Mica Quartz Binder/Filler	11% 88%
0158123-015 2501-15		LAYER 1 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber Gypsum Carbonates Mica Quartz	12% 88%
		LAYER 2 Joint Compound, White/ Lt. Blue	Yes	Chrysotile 3%	Cellulose Fiber Carbonates Mica Quartz Binder/Filler	1% 96%
		LAYER 3 Sheetrock, Joint Compound Composite, White/ Brown/ Lt. Blue Note: COMPOSITE ANALYSIS REQUESTED	Yes	Chrysotile <1%	Cellulose Fiber Gypsum Carbonates Mica Quartz Binder/Filler	11% 88%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158123

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/20/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/23/2015
Collected: 07/15/2015 Date Reported: 07/23/2015
Project Name: SIA BLDG. #2501-8600 W. ELECTRIC AVE EPA Method: EPA 600/R-93/116
Address: SPOKANE, WA Submitted By: KEVIN McCRINK
Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158123-016 2501-16		LAYER 1 Wall Mastic, Tan	No	None Detected	Cellulose Fiber	5%
					Carbonates Gypsum Quartz Binder/Filler	95%
		LAYER 2 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber	10%
					Gypsum Quartz Carbonates	90%
0158123-017 2501-17		LAYER 1 Wall Mastic, Tan	No	None Detected	Cellulose Fiber	1%
					Carbonates Gypsum Quartz Binder/Filler	99%
		LAYER 2 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber	10%
					Gypsum Quartz Carbonates	90%
0158123-018 2501-18		LAYER 1 Cove Base, Black	No	None Detected	Carbonates Quartz Binder/Filler	100%
		LAYER 2 Mastic, Brown/ Tan	No	None Detected	Cellulose Fiber	<1%
					Carbonates Gypsum Quartz Binder/Filler	99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158123

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/20/2015
Collected:	07/15/2015	Date Analyzed:	07/23/2015
Project Name:	SIA BLDG. #2501-8600 W. ELECTRIC AVE	Date Reported:	07/23/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158123-019 2501-19		LAYER 1 Cove Base, Black	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Mastic, Brown/ Tan	No	None Detected	Talc Carbonates Gypsum Quartz Binder/Filler 98%
0158123-020 2501-20		LAYER 1 Texture, White/ Off White Note: Difficult to separate adjacent layers	No	None Detected	Carbonates Mica Quartz Perlite Binder/Filler 100%
		LAYER 2 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber Fibrous Glass Gypsum Quartz Carbonates 10% 2% 88%
0158123-021 2501-21		LAYER 1 Texture, Off White	No	None Detected	Cellulose Fiber Carbonates Mica Quartz Perlite Binder/Filler 99% <1%
		LAYER 2 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber Fibrous Glass Gypsum Quartz Carbonates 10% 2% 88%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158123

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/20/2015
Collected:	07/15/2015	Date Analyzed:	07/23/2015
Project Name:	SIA BLDG. #2501-8600 W. ELECTRIC AVE	Date Reported:	07/23/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158123-022 2501-22		LAYER 1 Texture, Off White	No	None Detected	Carbonates Mica Quartz Perlite Binder/Filler 100%
		LAYER 2 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber 10% Fibrous Glass 2% Gypsum Quartz Carbonates 88%
0158123-023 2501-23		12"x12" Ceiling Tile, White / Tan	No	None Detected	Cellulose Fiber 85% Carbonates Gypsum Binder/Filler 15%
0158123-024 2501-24		12"x12" Ceiling Tile, White / Tan	No	None Detected	Cellulose Fiber 85% Carbonates Gypsum Binder/Filler 15%
0158123-025 2501-25		12"x12" Ceiling Tile, White / Tan	No	None Detected	Cellulose Fiber 85% Carbonates Gypsum Binder/Filler 15%
0158123-026 2501-26		LAYER 1 Wall Tile Mastic, Dk. Brown	No	None Detected	Carbonates Gypsum Quartz Binder/Filler 100%
		LAYER 2 Sheetrock, White/ Brown	No	None Detected	Cellulose Fiber 12% Gypsum Quartz Carbonates 88%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158123

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/20/2015
Collected:	07/15/2015	Date Analyzed:	07/23/2015
Project Name:	SIA BLDG. #2501-8600 W. ELECTRIC AVE	Date Reported:	07/23/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158123-027 2501-27		LAYER 1 Wall Tile Mastic, Dk. Brown	No	None Detected	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	<1% 99%
		LAYER 2 Sheetrock/ Fiber Board, White/ Brown Note: Layer appears to be Fiber Board	No	None Detected	Cellulose Fiber Carbonates Gypsum Binder/Filler	85% 15%
0158123-028 2501-28		LAYER 1 Wall Tile Mastic, Dk. Brown	No	None Detected	Talc Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	2% <1% 97%
		LAYER 2 Sheetrock/ Fiber Board, White/ Brown Note: Layer appears to be Fiber Board	No	None Detected	Cellulose Fiber Carbonates Gypsum Binder/Filler	85% 15%
0158123-029 2501-29		Wall Mastic, Tan	No	None Detected	Carbonates Gypsum Quartz Binder/Filler	 100%
0158123-030 2501-30		Wall Mastic, Tan	No	None Detected	Carbonates Gypsum Quartz Binder/Filler	 100%
0158123-031 2501-31		2x4 Ceiling Tile (Worm Hole Pattern), White	Yes	Chrysotile 3%	Mineral Wool Wollastonite Carbonates Gypsum Perlite Binder/Filler	80% 2% 15%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158123

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/20/2015
Collected:	07/15/2015	Date Analyzed:	07/23/2015
Project Name:	SIA BLDG. #2501-8600 W. ELECTRIC AVE	Date Reported:	07/23/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158123-032 2501-32		2x4 Ceiling Tile (Worm Hole Pattern), White	Yes	Chrysotile 3%	Mineral Wool Wollastonite Carbonates Gypsum Perlite Binder/Filler 15%
0158123-033 2501-33		LAYER 1 12"x12" Ceiling Tile, White	No	None Detected	Mineral Wool Carbonates Gypsum Perlite Binder/Filler 20%
		LAYER 2 Mastic, Dk. Brown	Yes	Tremolite <1%	Non-Fibrous Tremolite Talc Gypsum Carbonates Quartz Binder/Filler 2% 2% 95%
0158123-034 2501-34		LAYER 1 12"x12" Ceiling Tile, White	No	None Detected	Mineral Wool Carbonates Gypsum Perlite Binder/Filler 20%
		LAYER 2 Mastic, Dk. Brown	Yes	Tremolite <1%	Non-Fibrous Tremolite Talc Gypsum Carbonates Quartz Binder/Filler 2% 2% 95%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158123

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/20/2015
Collected:	07/15/2015	Date Analyzed:	07/23/2015
Project Name:	SIA BLDG. #2501-8600 W. ELECTRIC AVE	Date Reported:	07/23/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158123-035 2501-35		LAYER 1 12"x12" Ceiling Tile, White	No	None Detected	Mineral Wool 80% Carbonates Gypsum Perlite Binder/Filler 20%
		LAYER 2 Mastic, Dk. Brown	Yes	Tremolite <1%	Non-Fibrous Tremolite 2% Talc 2% Gypsum Carbonates Quartz Binder/Filler 95%
0158123-036 2501-36		Sheetrock, Off White/ Brown	No	None Detected	Cellulose Fiber 10% Fibrous Glass 2% Gypsum Quartz Carbonates 88%
0158123-037 2501-37		Sheetrock, Off White/ Brown	No	None Detected	Cellulose Fiber 10% Fibrous Glass 2% Gypsum Quartz Carbonates 88%
0158123-038 2501-38		Sheetrock, Off White/ Brown	No	None Detected	Cellulose Fiber 10% Fibrous Glass 2% Gypsum Quartz Carbonates 88%
0158123-039 2501-39		Brick, Orange	No	None Detected	Cellulose Fiber <1% Quartz Gypsum Mica Carbonates Binder/Filler 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158123

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/20/2015
Collected:	07/15/2015	Date Analyzed:	07/23/2015
Project Name:	SIA BLDG. #2501-8600 W. ELECTRIC AVE	Date Reported:	07/23/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158123-040 2501-40		Brick, Orange	No	None Detected	Cellulose Fiber Quartz Gypsum Mica Carbonates Binder/Filler	<1% 99%
0158123-041 2501-41		Mortar, Gray	No	None Detected	Synthetic Fiber Quartz Carbonates Gypsum Mica Binder/Filler	<1% 99%
0158123-042 2501-42		Mortar, Gray	No	None Detected	Cellulose Fiber Quartz Carbonates Gypsum Mica Binder/Filler	<1% 99%
0158123-043 2501-43		HVAC Duct Tar, Black	No	None Detected	Carbonates Gypsum Binder/Filler	 100%
0158123-044 2501-44		HVAC Duct Tar, Black	No	None Detected	Carbonates Gypsum Binder/Filler	 100%
0158123-045 2501-45		HVAC Duct Tar, Black	No	None Detected	Carbonates Gypsum Binder/Filler	 100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158123

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231	Date Received:	07/20/2015
	LIBERTY LAKE, WA 99019	Date Analyzed:	07/23/2015
Collected:	07/15/2015	Date Reported:	07/23/2015
Project Name:	SIA BLDG. #2501-8600 W. ELECTRIC AVE	EPA Method:	EPA 600/R-93/116
Address:	SPOKANE, WA	Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158123-046 2501-46		LAYER 1 Cork, Brown	No	None Detected	Cork	100%
		LAYER 2 HVAC Duct Tar, Black	No	None Detected	Carbonates Gypsum Quartz Binder/Filler	100%
0158123-047 2501-47		LAYER 1 Cork, Brown	No	None Detected	Cork	100%
		LAYER 2 HVAC Duct Tar, Black	No	None Detected	Carbonates Gypsum Quartz Binder/Filler	100%
0158123-048 2501-48		Fiberglass Pipe Insulation, Yellow Note: No White Wrap Present	No	None Detected	Fibrous Glass Carbonates Binder/Filler	98% 2%
0158123-049 2501-49		LAYER 1 Wrap, White	No	None Detected	Cellulose Fiber Carbonates Gypsum Binder/Filler	98% 2%
		LAYER 2 Fiberglass Pipe Insulation, Yellow Note: No White Wrap Present	No	None Detected	Fibrous Glass Carbonates Binder/Filler	98% 2%
0158123-050 2501-50		LAYER 1 Wrap, White	No	None Detected	Cellulose Fiber Carbonates Gypsum Binder/Filler	98% 2%
		LAYER 2 Fiberglass Pipe Insulation, Yellow Note: No White Wrap Present	No	None Detected	Fibrous Glass Carbonates Binder/Filler	98% 2%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158123

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/20/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/23/2015
Collected: 07/15/2015 Date Reported: 07/23/2015
Project Name: SIA BLDG. #2501-8600 W. ELECTRIC AVE EPA Method: EPA 600/R-93/116
Address: SPOKANE, WA Submitted By: KEVIN McCRINK
Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158123-051 2501-51		Window Glazing, Lt. Gray	No	None Detected	Carbonates Quartz Binder/Filler 100%
0158123-052 2501-52		Window Glazing, Lt. Gray	No	None Detected	Carbonates Quartz Binder/Filler 100%
0158123-053 2501-53		Window Glazing, White	Yes	Chrysotile 5%	Carbonates Gypsum Quartz Binder/Filler 95%
0158123-054 2501-54		Window Glazing, White	Yes	Chrysotile 5%	Carbonates Gypsum Quartz Binder/Filler 95%
0158123-055 2501-55		HVAC Duct Seam Caulk, Gray	No	None Detected	Carbonates Gypsum Quartz Binder/Filler 100%
0158123-056 2501-56		HVAC Duct Seam Caulk, Gray	No	None Detected	Carbonates Gypsum Quartz Binder/Filler 100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158123

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/20/2015
Collected:	07/15/2015	Date Analyzed:	07/23/2015
Project Name:	SIA BLDG. #2501-8600 W. ELECTRIC AVE	Date Reported:	07/23/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158123-057 2501-57		LAYER 1 Texture, Off White	No	None Detected	Cellulose Fiber <1% Carbonates Mica Quartz Perlite Binder/Filler 99%
		LAYER 2 Sheetrock, White/ Gray	No	None Detected	Cellulose Fiber 10% Fibrous Glass 2% Gypsum Quartz Carbonates 88%
0158123-058 2501-58		LAYER 1 Texture, Off White	No	None Detected	Cellulose Fiber <1% Carbonates Mica Quartz Perlite Binder/Filler 99%
		LAYER 2 Sheetrock, White/ Gray	No	None Detected	Cellulose Fiber 10% Fibrous Glass 2% Gypsum Quartz Carbonates 88%
0158123-059 2501-59		LAYER 1 Texture, Off White	No	None Detected	Cellulose Fiber <1% Carbonates Mica Quartz Perlite Binder/Filler 99%
		LAYER 2 Sheetrock, White/ Gray	No	None Detected	Cellulose Fiber 10% Fibrous Glass 2% Gypsum Quartz Carbonates 88%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158123

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231 LIBERTY LAKE, WA 99019	Date Received:	07/20/2015
Collected:	07/15/2015	Date Analyzed:	07/23/2015
Project Name:	SIA BLDG. #2501-8600 W. ELECTRIC AVE	Date Reported:	07/23/2015
Address:	SPOKANE, WA	EPA Method:	EPA 600/R-93/116
		Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158123-060 2501-60		Concrete, Gray	No	None Detected	Quartz Carbonates Gypsum Mica Binder/Filler	100%
0158123-061 2501-61		Concrete, Gray	No	None Detected	Cellulose Fiber Quartz Carbonates Gypsum Mica Binder/Filler	<1% 99%
0158123-062 2501-62		Transite Shingle, Gray	Yes	Chrysotile 15%	Carbonates Gypsum Quartz Binder/Filler	85%
0158123-063 2501-63		Window Glazing, White	No	None Detected	Carbonates Quartz Binder/Filler	100%
0158123-064 2501-64		Window Glazing, White	No	None Detected	Carbonates Quartz Binder/Filler	100%
0158123-065 2501-65		Caulk, White	Yes	Chrysotile 2%	Talc Carbonates Quartz Binder/Filler	3% 95%
0158123-066 2501-66		Caulk, White	No	None Detected	Carbonates Quartz Binder/Filler	100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158123

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIRONMENTAL RISK MGMT Job# / P.O. #: ERM-15-130
Address: 1324 LIBERTY LAKE RD, 231 Date Received: 07/20/2015
LIBERTY LAKE, WA 99019 Date Analyzed: 07/23/2015
Collected: 07/15/2015 Date Reported: 07/23/2015
Project Name: SIA BLDG. #2501-8600 W. ELECTRIC AVE EPA Method: EPA 600/R-93/116
Address: SPOKANE, WA Submitted By: KEVIN McCRINK
Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0158123-067 2501-67		LAYER 1 Tar Paper, Black	No	None Detected	Cellulose Fiber	65%
					Carbonates Gypsum Binder/Filler	35%
		LAYER 2 Tar Paper, Black	No	None Detected	Cellulose Fiber	40%
					Carbonates Gypsum Quartz Binder/Filler	60%
0158123-068 2501-68		LAYER 1 Tar Paper, Black	No	None Detected	Cellulose Fiber	65%
					Carbonates Gypsum Binder/Filler	35%
		LAYER 2 Tar Paper, Black	No	None Detected	Cellulose Fiber	40%
					Carbonates Gypsum Quartz Binder/Filler	60%
0158123-069 2501-69		Tar Paper, Black	No	None Detected	Cellulose Fiber	65%
					Carbonates Gypsum Binder/Filler	35%
0158123-070 2501-70		LAYER 1 Tar Paper, Black	No	None Detected	Cellulose Fiber	65%
					Carbonates Gypsum Binder/Filler	35%
		LAYER 2 Tar Paper, Black	No	None Detected	Cellulose Fiber	40%
					Carbonates Gypsum Quartz Binder/Filler	60%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0158123

Bulk Asbestos Analysis by Polarized Light Microscopy


NVLAP#101926-0

Client:	ENVIRONMENTAL RISK MGMT	Job# / P.O. #:	ERM-15-130
Address:	1324 LIBERTY LAKE RD, 231	Date Received:	07/20/2015
	LIBERTY LAKE, WA 99019	Date Analyzed:	07/23/2015
Collected:	07/15/2015	Date Reported:	07/23/2015
Project Name:	SIA BLDG. #2501-8600 W. ELECTRIC AVE	EPA Method:	EPA 600/R-93/116
Address:	SPOKANE, WA	Submitted By:	KEVIN McCRINK
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0158123-071 2501-71		Roof Shingle, Black	No	None Detected	Cellulose Fiber 15% Fibrous Glass 5% Carbonates Gypsum Quartz Binder/Filler 80%
0158123-072 2501-72		Roof Shingle, Black	No	None Detected	Cellulose Fiber 15% Fibrous Glass 5% Carbonates Gypsum Quartz Binder/Filler 80%



Analyst - Kurt Kettler



Signatory - Lab Manager - Ken Scheske

Distinctly stratified, easily separable layers of samples are analyzed as subsamples of the whole and are reported separately for each discernible layer. All analyses are derived from calibrated visual estimate and measured in area percent unless otherwise noted. The report applies to the standards or procedures identified and to the sample(s) tested. The test results are not necessarily indicated or representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products, nor do they represent an ongoing quality assurance program unless so noted. These reports are for the exclusive use of the addressed client and that they will not be reproduced wholly or in part for advertising or other purposes over our signature or in connection with our name without special written permission. The report shall not be reproduced except in full, without written approval by our laboratory. The samples not destroyed in testing are retained a maximum of thirty days. The laboratory measurement of uncertainty for the test method is approximately less than 1 by area percent. Accredited by the National Institute of Standards and Technology, Voluntary Laboratory Accreditation Program for selected test method for asbestos. The accreditation or any reports generated by this laboratory in no way constitutes or implies product certification, approval, or endorsement by the National Institute of Standards and Technology. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. Polarized Light Microscopy may not be consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#: 158123
 TAT: 3 days
 Rec'd: JUL 20 P.M.

COMPANY NAME: Environmental Risk Mgmt BILL TO: _____ (If Different Location)
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019
 CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

Now Accepting: VISA - MASTERCARD Price Quoted: \$ _____ / Sample \$ _____ / Layers _____

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

- TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]
 ****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met
- TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]
- DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #2501, 8600 W. Electric Avenue, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>1</u>	2501-1	7/15/15	Brown 9x9 floor tile/ black mastic	<u>Y</u> N
<u>2</u>	2501-2	7/15/15	Brown 9x9 floor tile/ black mastic	Y N
<u>3</u>	2501-3	7/15/15	Brown cove base/ brown - black mastic	Y N
<u>4</u>	2501-4	7/15/15	Brown cove base/ brown - black mastic	Y N
<u>5</u>	2501-5	7/15/15	Brown cove base/ brown mastic	Y N
<u>6</u>	2501-6	7/15/15	Brown cove base/ black mastic	Y N
<u>7</u>	2501-7	7/15/15	White 2x4 ceiling tile (floral pin hole pattern)	Y N
<u>8</u>	2501-8	7/15/15	White 2x4 ceiling tile (floral pin hole pattern)	Y N
<u>9</u>	2501-9	7/15/15	White 2x4 ceiling tile (floral pin hole pattern)	Y N
<u>10</u>	2501-10	7/15/15	White 2x4 ceiling tile (floral pin hole pattern)	Y N
<u>11</u>	2501-11	7/15/15	Sheetrock/ joint compound	Y N
<u>12</u>	2501-12	7/15/15	Sheetrock/ joint compound	Y N
<u>13</u>	2501-13	7/15/15	Sheetrock/ joint compound	Y N
<u>14</u>	2501-14	7/15/15	Sheetrock/ joint compound	Y N
<u>15</u>	2501-15	7/15/15	Sheetrock/ joint compound	<u>Y</u> N

SPECIAL INSTRUCTIONS: _____
 Sample Collector: (Print) Kevin McCrink (Signature) [Signature]
 Relinquished by: [Signature] Date/Time: 7-17-15 Received by: Diana Federico Date/Time: 7/20/15
 Relinquished by: Diana Federico Date/Time: 7/20/15 Received by: [Signature] Date/Time: 7/20/15
 Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#:	
TAT:	158123
Rec'd:	

COMPANY NAME: Environmental Risk Mgmt BILL TO: _____ (If Different Location)
1324 Liberty Lake Rd, 231
Liberty Lake, WA 99019
 CONTACT: Kevin McCrink
 Phone/Fax: (509) 226-2523 /
 Email: envriskmgm@aol.com

Now Accepting: VISA - MASTERCARD Price Quoted: \$ _____ / Sample \$ _____ / Layers _____

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required

****Additional charges for rush analysis (please call marketing department for pricing details)

****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]

(If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #2501, 8600 W. Electric Avenue, Spokane, WA

P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>16</u>	2501-16	7/15/15	Tan wall mastic/ sheetrock	<u>Y</u> N
<u>17</u>	2501-17	7/15/15	Tan wall mastic/ sheetrock	Y <u>N</u>
<u>18</u>	2501-18	7/15/15	Black cove base/ mastic	Y N
<u>19</u>	2501-19	7/15/15	Black cove base/ mastic	Y N
<u>20</u>	2501-20	7/15/15	Texture/ sheetrock	Y N
<u>21</u>	2501-21	7/15/15	Texture/ sheetrock	Y N
<u>22</u>	2501-22	7/15/15	Texture/ sheetrock	Y N
<u>23</u>	2501-23	7/15/15	White-tan 12x12 ceiling tile	Y N
<u>24</u>	2501-24	7/15/15	White-tan 12x12 ceiling tile	Y N
<u>25</u>	2501-25	7/15/15	White-tan 12x12 ceiling tile	Y N
<u>26</u>	2501-26	7/15/15	Dark brown wall tile mastic/ sheetrock	Y N
<u>27</u>	2501-27	7/15/15	Dark brown wall tile mastic/ sheetrock	Y N
<u>28</u>	2501-28	7/15/15	Dark brown wall tile mastic/ sheetrock	Y N
<u>29</u>	2501-29	7/15/15	Tan wall mastic	Y N
<u>30</u>	2501-30	7/15/15	Tan wall mastic	<u>Y</u> N

SPECIAL INSTRUCTIONS:

Sample Collector: (Print) Kevin McCrink

(Signature) [Signature]

Relinquished by: [Signature] Date/Time: 7-17-15

Received by: Diana Federico Date/Time: 7/20/15

Relinquished by: Diana Federico Date/Time: 7/20/15

Received by: [Signature] Date/Time: 7/20/15

Relinquished by: _____ Date/Time: _____

Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB# :	
TAT :	158123
Rec'd :	

COMPANY NAME: Environmental Risk Mgmt BILL TO: _____ (If Different Location)

1324 Liberty Lake Rd, 231

Liberty Lake, WA 99019

CONTACT: Kevin McCrink

Phone/Fax: (509) 226-2523 /

Email: envriskmgm@aol.com

Now Accepting: VISA - MASTERCARD Price Quoted: \$ _____ / Sample \$ _____ / Layers _____

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]
- ****Prior confirmation of turnaround time is required
- ****Additional charges for rush analysis (please call marketing department for pricing details)
- ****Laboratory analysis may be subject to delay if credit terms are not met
2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]
3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
- (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #2501, 8600 W. Electric Avenue, Spokane, WA

P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>31</u>	2501-31	7/15/15	White 2x4 ceiling tile (worm hole pattern)	<u>Y</u> N
<u>32</u>	2501-32	7/15/15	White 2x4 ceiling tile (worm hole pattern)	Y N
<u>33</u>	2501-33	7/15/15	White 12x12 ceiling tile / dark brown mastic	Y N
<u>34</u>	2501-34	7/15/15	White 12x12 ceiling tile / dark brown mastic	Y N
<u>35</u>	2501-35	7/15/15	White 12x12 ceiling tile / dark brown mastic	Y N
<u>36</u>	2501-36	7/15/15	Sheetrock	Y N
<u>37</u>	2501-37	7/15/15	Sheetrock	Y N
<u>38</u>	2501-38	7/15/15	Sheetrock	Y N
<u>39</u>	2501-39	7/15/15	Brick	Y N
<u>40</u>	2501-40	7/15/15	Brick	Y N
<u>41</u>	2501-41	7/15/15	Mortar	Y N
<u>42</u>	2501-42	7/15/15	Mortar	Y N
<u>43</u>	2501-43	7/15/15	Black HVAC duct tar	Y N
<u>44</u>	2501-44	7/15/15	Black HVAC duct tar	Y N
<u>45</u>	2501-45	7/15/15	Black HVAC duct tar	<u>Y</u> N

SPECIAL INSTRUCTIONS: _____

Sample Collector: (Print) Kevin McCrink (Signature) [Signature]

Relinquished by: [Signature] Date/Time: 7-18-15 Received by: Diana Fedrico Date/Time: 7/20/15

Relinquished by: Diana Fedrico Date/Time: 7/20/15 Received by: [Signature] Date/Time: 7/20/15

Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
 EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB# :	
TAT :	158123
Rec'd :	

COMPANY NAME: Environmental Risk Mgmt BILL TO: _____ (If Different Location)

1324 Liberty Lake Rd, 231

Liberty Lake, WA 99019

CONTACT: Kevin McCrink

Phone/Fax: (509) 226-2523 /

Email: envriskmgm@aol.com

Now Accepting: VISA - MASTERCARD Price Quoted: \$ _____ / Sample \$ _____ / Layers _____

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

- TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]
 ****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met
- TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]
- DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #2501, 8600 W. Electric Avenue, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>46</u>	2501-46	7/15/15	Brown cork/ black HVAC duct tar	<u>Y</u> N
<u>47</u>	2501-47	7/15/15	Brown cork/ black HVAC duct tar	Y <u>N</u>
<u>48</u>	2501-48	7/15/15	White wrap/ yellow fiberglass pipe insulation	Y N
<u>49</u>	2501-49	7/15/15	White wrap/ yellow fiberglass pipe insulation	Y N
<u>50</u>	2501-50	7/15/15	White wrap/ yellow fiberglass pipe insulation	Y N
<u>51</u>	2501-51	7/15/15	Lt. gray window glazing	Y N
<u>52</u>	2501-52	7/15/15	Lt. gray window glazing	Y N
<u>53</u>	2501-53	7/15/15	White window glazing	Y N
<u>54</u>	2501-54	7/15/15	White window glazing	Y N
<u>55</u>	2501-55	7/15/15	Gray HVAC duct seam caulk	Y N
<u>56</u>	2501-56	7/15/15	Gray HVAC duct seam caulk	Y N
<u>57</u>	2501-57	7/15/15	Texture/ sheetrock	Y N
<u>58</u>	2501-58	7/15/15	Texture/ sheetrock	Y N
<u>59</u>	2501-59	7/15/15	Texture/ sheetrock	Y N
<u>60</u>	2501-60	7/15/15	Concrete	<u>Y</u> N

SPECIAL INSTRUCTIONS: _____

Sample Collector: (Print) Kevin McCrink (Signature) [Signature]

Relinquished by: [Signature] Date/Time: 7-17-15 Received by: Diana Federico Date/Time: 7/20/15

Relinquished by: Diana Federico Date/Time: 7/20/15 Received by: [Signature] Date/Time: 7/20/15

Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

CHAIN OF CUSTODY
EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB# :	
TAT :	158123
Rec' d :	

COMPANY NAME: Environmental Risk Mgmt BILL TO: _____ (If Different Location)

1324 Liberty Lake Rd, 231

Liberty Lake, WA 99019

CONTACT: Kevin McCrink

Phone/Fax: (509) 226-2523 /

Email: envriskmgm@aol.com

Now Accepting: VISA - MASTERCARD Price Quoted: \$ _____ / Sample \$ _____ / Layers _____

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [4hr rush] [8hr rush] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]
- ****Prior confirmation of turnaround time is required
- ****Additional charges for rush analysis (please call marketing department for pricing details)
- ****Laboratory analysis may be subject to delay if credit terms are not met
2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]
3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 60 days from analysis.)

Project Name: SIA Bldg. #2501, 8600 W. Electric Avenue, Spokane, WA
 P.O. Number: _____ Project Number: ERM-15-130

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No
<u>61</u>	2501-61	7/15/15	Concrete	<u>Y</u> N
<u>62</u>	2501-62	7/15/15	Transite shingle	Y <u>N</u>
<u>63</u>	2501-63	7/15/15	White window glazing	Y N
<u>64</u>	2501-64	7/15/15	White window glazing	Y N
<u>65</u>	2501-65	7/15/15	White caulk	Y N
<u>66</u>	2501-66	7/15/15	White caulk	Y N
<u>67</u>	2501-67	7/15/15	Black tar paper	Y N
<u>68</u>	2501-68	7/15/15	Black tar paper	Y N
<u>69</u>	2501-69	7/15/15	Black tar paper	Y N
<u>70</u>	2501-70	7/15/15	Black tar paper	Y N
<u>71</u>	2501-71	7/15/15	Maroon asphalt roof shingle	Y N
<u>72</u>	2501-72	7/15/15	Maroon asphalt roof shingle	<u>Y</u> N
				Y N
				Y N
				Y N

SPECIAL INSTRUCTIONS: _____

Sample Collector: (Print) Kevin McCrink (Signature) [Signature]

Relinquished by: [Signature] Date/Time: 7-17-15 Received by: Diana Federico Date/Time: 7/20/15


Relinquished by: Diana Federico Date/Time: 7/20/15 Received by: [Signature] Date/Time: 7/20/15

Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

Appendix C
Laboratory Certification

United States Department of Commerce
National Institute of Standards and Technology



Certificate of Accreditation to ISO/IEC 17025:2005

NVLAP LAB CODE: 101926-0

EMC Labs, Inc.
Phoenix, AZ

*is accredited by the National Voluntary Laboratory Accreditation Program for specific services,
listed on the Scope of Accreditation, for:*

BULK ASBESTOS FIBER ANALYSIS

*This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2005.
This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality
management system (refer to joint ISO-ILAC-IAF Communiqué dated January 2009).*

2015-07-01 through 2016-06-30

Effective dates



W. D. Wild

For the National Institute of Standards and Technology



**National Voluntary
Laboratory Accreditation Program**



SCOPE OF ACCREDITATION TO ISO/IEC 17025:2005

EMC Labs, Inc.
 9830 S. 51st St. Suite B-109
 Phoenix, AZ 85044-5677
 Mr. Kurt A. Kettler
 Phone: 480-940-5294 Fax: 480-893-1726
 E-Mail: kkettler@earthlink.net
 URL: <http://www.emclabs.com>

BULK ASBESTOS FIBER ANALYSIS (PLM)

NVLAP LAB CODE 101926-0

<i>NVLAP Code</i>	<i>Designation / Description</i>
18/A01	EPA 600/M4-82-020: Interim Method for the Determination of Asbestos in Bulk Insulation Samples
18/A03	EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials

2015-07-01 through 2016-06-30

Effective dates

For the National Institute of Standards and Technology